ACI Motor Ltd.

WARRANTY CLAIM FORM (New Machinery)

| Name | Abdur Rehim Talukdar/ Md. Nannu |
|---------------|---------------------------------|
| Customer Code | D01682 |
| Mobile | 01716-719487 |
| Upazila | Sunamganj Sadar |
| District | Sunamgani |

Harvester Details

| Warranty Number | HAR/WRT/1490 |
|-----------------|---------------|
| Product | Harvester |
| Model | Yanmar AG600A |
| Engine No | 11465A |
| Chassis No | C60B500015 |
| Delivery Date | 07-Apr-2022 |
| Working Hour | 434.00 |

Complain Details

| Customer's | |
|------------|--|
| Complaint | |

Engine doesn't start.

Customer complain was engine doesn't start. We checked & found that there is a Internal fault on Primary ECU & error code(28 00099 9) showing on meter board. The secondary ECU also faulty because as soon as we connect the ECU reaping motor fuse 30A cut off. But no short circuit in wires. Solution: Need to Replace the Primary & Secondary ECU.

Parts Details

| SL No. | Parts Description | Parts Code | Quantity | Amount | |
|---------------------|---|---------------|------------|--------|--------|
| 1 | (Y-129967-75010) ECU | H607 | 100 | 1 | 55000 |
| 2 | (Y-1E6B92-80800) ECU, 3.5 MOTOR SERVICE | \$095 | | , | 50000 |
| Total Amount | | ••• | | • | |
| | | - · | | | 105000 |
| MQR Number | 00 | Job Card No | 00 | | |
| MQR Date | 29/10/2022 | Job Card Date | 29/10/2022 | | |

Proposed By

Checked By

Recommended By

Approved By

SE/Sr.SE/TMS

