



WARRANTY CLAIM FORM

h ()) () () () ()	Tvv '1	Daninagor	100
Md.Motaher Mondol		The second secon	11.5
01811-822121	District	Naogaon	
ATION			
Yanmar Combine Harve	ester		
AG 600A			A Company
44940A			
C60B401244	***	My Mill My many 12	
20 April 2021		and the second	
567.6		1914	
	AND THE STREET	The state of the s	
S			
When Paddy harvesting	time suddenly Stearing	ng is not moving right site.	
Solenoid is damage			176,117
	ATION Yanmar Combine Harve AG 600A 44940A C60B401244 20 April 2021 567.6 S When Paddy harvesting	O1811-822121 District ATION Yanmar Combine Harvester AG 600A 44940A C60B401244 20 April 2021 567.6 S When Paddy harvesting time suddenly Stearing	O1811-822121 District Naogaon ATION Yanmar Combine Harvester AG 600A 44940A C60B401244 20 April 2021 567.6 S When Paddy harvesting time suddenly Stearing is not moving right site.

SI	Part Name	Parts Code	Quanti	Unit Price	Total Amount
1	(1E8379-66770) SOLRNOID	J146	1	26500	26500
2					
3					
4			THU T	1	
5					
6				and the second second second second	
7			-00	No seattle research	
					26,500

HO Fill up	and the second s		
Warranty No		Job Card No	
	24/05/2022	Job Card	The state of the s
Warranty claim Date		Date	25/05/2022

Proposed By	Recommended By	Checked By	Forward By	Approved By
SE/ Sr. SE/ TMS	RSM/SM	SCE/Sr. SCE/AMS	Sr.Manager Service	Director (S&PD)

N.B: Attach job card, damage parts photo and recommendation from sales personnel.