June SONALIKA

INTERNATIONAL TRACTORS LIMITED

Vill. Chak Gujran, P.O. Piplanwala , Jalandhar Road, Hoshiarpur

Warranty Claim

						,						PRI	NT		
COUNTRY NAME	DUNTRY NAME BANGLADESH			DBR NAME			ACI LTI	ACI LTD			R CODE		270		
DEALER NAME	EALER NAME ACI DINAJPUR DINAJPUR			DEALER ADDRESS			Dinajpur			CUSTOMER NAME			-	Md Asadujjama Babu	
CUSTOMER ADDRESS															
Warranty Claim No	2700036-9	476R5-201	23_10		JobCard No		2700026 04	76DE 202	2.64	Phanaia	No		D700	140400040	
Tractor Model	2700036-9476B5-2023-10 DI 50 RX 2WD			Engine No			2700036-9476B5-2023-64 3105NH24I1213904			Chassis No Job Card Date				J12196218 5-2023	
Date	16-Feb-202	23			Last Service Da	te	010011112411	210001			Failure			0-2023	
Date of Sale	28-Dec-202	22			Hours Worked		165.00		I	nvoice	No		36028		
Last Service Hours					Customer Comp	laint	BAD NOISE FROM THE								
Invoice Date	oice Date 21-Sep-2022				HOUSING Buyer Ref No										
PDI & Service Details												***************************************	MIN MANAGEMENT AND	AT THE STATE OFFICE AS A RESIDENCE AS A SHARE ASSAULT.	
PDI	1st Service	2nd Serv	vice :	3rd S	ervice	4th Ser	vice	5th Serv	ice	6th	Service		7th Sen	vice	
12-Dec-2022															
Complaint Details															
Data not available.															
Data not available.													-		
Part Details															
Complaint Code				1 00 2 00 0 0 1 1 0 1 0 1 1					Quantity Billing T				SE	Analysis	
abour Dotail(B)	CULPRIT PART NO)	20005095AA		TAPPER ROLLE	R BEAR	ING 32309		2.00		WARRA	ANTY			
abour Detail(B)															
Complaint Code	Action Taken				Labour Code				Labour Hours				Lai	oour Charg	
Data not available.															
Consumables C															
Complaint Code	Description				Qty				Rate			Amount			
Data not available.									, 1010			Ame	Juni		
OutsideJob (D)															
Complaint Code	Details of Job				BillNo										
Data not available.							BIIINO		Date			Amo	unt		
laim Summary															
Part(A)			Labour (I	21		-					***************************************				
utaida lah (D)				•				Consumables (C)							
			Sale Tax	(=)	•	J			Total(A+B+	C+D+E	()	22850			
Culprit Part No	20005095/				Culprit Part N	lame									
Dealer Analysis	AFTER INSPECTION WE FOUND THAT TAPPER ROLLER BEARING 32309 HAS CRACKED. SCR RAISE SCR-2700036-2023-303			ED.	Dealer Action Taken				Complaint status Close				ose		
Acknowledgement					Acknowledge	ont C									
		0	Low		Acknowledgen	ient Date	•				Re	marks			