

INTERNATIONAL TRACTORS LIMITED

Vill. Chak Gujran, P.O. Piplanwala, Jalandhar Road, Hoshiarpur

Warranty Claim

PRINT DBR CODE 2700036 DBR NAME ACI LTD BANGLADESH COUNTRY NAME MD: Digharkanda, Chatrapara **CUSTOMER NAME** Mahabubur DEALER ADDRESS **ACI MYMENSINGH** Aamlitola, Mymensingh DEALER NAME Rahman CUSTOMER ADDRESS HXCDR1066032S3 2700036-2000036B11-2023-3 Chassis No JobCard No 2700036-2000036B11-2022-3 Warranty Claim No 4100FL14F1060853 13-Sep-2022 Engine No DI 55 RX 2WD Tractor Model 13-Sep-2022 Date of Failure Last Service Date 13-Sep-2022 Date Invoice No 3602801263 988.00 31-Jul-2021 Hours Worked Date of Sale BAD NOISE WAS COMING **Customer Complaint** Last Service Hours FROM THE SILENCER. Buyer Ref No 09-Jun-2021 Invoice Date PDI & Service Details 7th Service 5th Service 6th Service PDI 1st Service 2nd Service 3rd Service 4th Service 17-Jun-2021 Complaint Details Complaint Desc Sub Aggregates Complaint Code Aggregates ENGINE-SILENCER NOISY **ENGINE** EN137 art Details Complaint Code Failure Type Part No Part Description Quantity **Billing Type** SE Analysis WARRANTY CULPRIT PART NO 10071979AA EXHAUST DUCT (OVAL TYPE) 1.00 Labour Detail(B) Labour Code **Complaint Code Action Taken** Labour Hours **Labour Charge** Data not available. Consumables C Complaint Code Description Qty Rate **Amount** Data not available. OutsideJob (D) Complaint Code Details of Job BillNo Date Amount Data not available. Claim Summary Part(A) Labour (B) Consumables (C) Outside Job (D) Sale Tax (E) 0 Total(A+B+C+D+E) 22850 Culprit Part No 10071979AA Culprit Part Name AFTER INSPECTION WE FOUND Dealer Analysis THAT EXHAUST DUCT FAULTY, SCR Dealer Action Taken Complaint status Close RAISED SCR-2700036-2022-1299 PRE cknowledgement Yes Acknowledgement Date MODIFIED 19-Sep-2022 Remarks FAILURE Redower knowledge Done By DIPTENDU ROY

