

## INTERNATIONAL TRACTORS LIMITED

Vill. Chak Gujran, P.O. Piplanwala, Jalandhar Road, Hoshiarpur

## Warranty Claim

PRINT DBR CODE 2700036 ACI LTD DBR NAME BANGLADESH Md Saber COUNTRY NAME **CUSTOMER NAME** DEALER ADDRESS Sylhet **ACI SYLHET Sylhet** Chowdhury DEALER NAME CUSTOMER ADDRESS FZGDJ1173039S3 2700036-9476B8-2023-5 Chassis No JobCard No 2700036-9476B8-2022-7 Warranty Claim No 12-Oct-2022 Job Card Date 3105NH24E1168629 Engine No DI 50 RX SUPREME 2WD 12-Oct-2022 Tractor Model Date of Failure Last Service Date 12-Oct-2022 Invoice No 3602810013 Date 372.00 Hours Worked 14-Jul-2022 Date of Sale BAD NOISE WAS COMING **Customer Complaint** FROM THE FRONT AXLE. Last Service Hours 26-May-2022 Buyer Ref No Invoice Date PDI & Service Details 7th Service 6th Service 5th Service 4th Service 2nd Service 3rd Service 1st Service PDI 13-Jul-2022 Complaint Details Complaint Desc Complaint Code Sub Aggregates Aggregates FRONT AXLE- FRONT WHEEL BRG WORN FA06 FRONT AXLE Part Details SE Analysis Quantity **Billing Type** Part Description Failure Type Part No Complaint Code 1.00 WARRANTY MUD BLOCK (50X80X10.5) 20003513AB CONSEQUENTIAL PARTS WARRANTY 1.00 20003258AA BEARING 32206 **CULPRIT PART NO** Labour Detail(B) Labour Charge **Labour Hours** Labour Code **Complaint Code Action Taken** Data not available. Consumables C **Amount** Rate Qty Complaint Code Description Data not available. OutsideJob (D) BillNo **Amount** Date Details of Job Complaint Code Data not available. Claim Summary Consumables (C) Labour (B) Part(A) 0 Total(A+B+C+D+E) 22850 Sale Tax (E) Outside Job (D) 20003258AA Culprit Part Name Culprit Part No AFTER INSPECTION WE FOUND THAT FRONT AXLE BEARING 32206 Dealer Action Taken Close Complaint status Dealer Analysis HAS WORN OUT.



