ACI Motor Ltd.

WARRANTY CLAIM FORM (New Machinery)

Customer Informations

District

Customer Code Mobile Upazila

Md Billal Hossain d01722

01713292944 **Jamalgon** Sunamgonj

Harvester Details

Warranty Number Model **Engine No** Chassis No **Delivery Date** Working Hour

HAR/WRT/109 Harvester AG600A 500205 C60B500205 08-Jun-2022

194.30

Complain Details

Customer's Complaint

The reaping unit can't up in the harvesting time

SE Analysis

We have checked and found that the solenoid valve is cracked in side of solenoid. That parts need to replaced under warranty.

Parts Details

SL No.

Parts Description

26500 26500

Total Amount

SOLENOID, DG2-03-4PR-

J147

Parts Code

35551

MQR Number MQR Date

MQS-1 22/06/2022

Job Card No Job Card Date

30/05/2022

Checked By

Recommended By

- 431

SE/Sr.SE/TMS

Proposed By

Manager/Sr.Manager Service

Kirector (S & PD)