Sonalika

INTERNATIONAL TRACTORS LIMITED

Vill. Chak Gujran, P.O. Piplanwala , Jalandhar Road, Hoshiarpur

Warranty Claim

	BANGLADESH			DBR NAME			PRINT				
							ACILTD		RCODE	2700036 Md	
COUNTRY NAME	BANGEADEST					la se e re		CU	STOMER NAME	Mustakin Ali	
DEALER NAME	ACI JESSORE JESSORE			DEALER ADDRESS		Jessore				(Meherpur)	
CUSTOMER ADDRESS	S										
				JobCard No		2700036-94	176B6-2023-29	Chassis	No	JZDDH954782S3	
Warranty Claim No	2700036-947686-2022-42			Engine No		4100FL04H950301 Jo		Job Card		19-Oct-2022	
Tractor Model	60 RX SUPREME 2WD			Last Service Da	ate			Date of I		19-Oct-2022	
Date	19-Oct-2022 30-Nov-2020			Hours Worked		1577.00		Invoice I	No	3602809365	
Date of Sale	20-1404-5050			Customer Complaint			VERE NOT IN RIGHT SIDE				
Last Service Hours				Customer Com	plaint	WHILE STE	ERING.				
Invoice Date	29-Aug-20	20		Buyer Ref No							
PDI & Service Details										Tab Camina	
	1st Service	2nd Service	3rd	Service	4th Servi	ce	5th Service	6th S	ervice	7th Service	
PDI 30-Sep-2020	15t GETVICE	2.10 001 1100									
30-30p 2320											
Complaint Details											
Aggregates	regates Sub Aggregates			Complaint Code			Complaint Desc STEERING -POWER STEERING			STEERING PUMP	
STEERING SYSTEM				ST17			SEIZED				
Part Details											
		I Don	t No		Part Des	rintion		Quantity	Billing Typ	e SE Analysis	
Complaint Code	Failure Type CULPRIT PART NO		27A HY	D. PUMP ASSY.(9				1.00	WARRANTY		
Labour Detail(B)											
Complaint Code	plaint Code Action Taken			Labour Code			Labour Hours			Labour Charge	
Data not available.											
Consumables C											
	D dollar			Qty '			Rate Am			nount	
Complaint Code	Description			diy							
Data not available.											
OutsideJob (D)											
Complaint Code	Details of Job			BillNo			Date		Ar	Amount	
Data not available.											
laim Summary											
art(A)	Labou			(B)			Consumables (C)				
Outside Job (D)	Sale T						Total(A+B+C+D+E) 22850				
100											
	00240202			Culorit Part	Name						
Culprit Part No	rit Part No 803402027A AFTER INSPECTION WE FOUN!			Culprit Part Name							
lealer Analysis	THAT HY	DRAULIC PUMP STEERING HAS	OF	Dealer Action	on Taken				Complaint statu	s Close	
cknowledgement	Yes		~	Acknowledgem	ent Date	2	25-Oct-2022		Remarks	THERE NO FLO THROU PUMP.	
cknowledge Done By pproval	DIPTENDU	ROY	adul Ju	Approved Date					Remarks		
oproval Done By		,	·						0		
ayment				Payment Date					Remarks		

