## SONALIKA

## INTERNATIONAL TRACTORS LIMITED

Vill. Chak Gujran, P.O. Piplanwala , Jalandhar Road, Hoshiarpur

Warranty Claim

PRINT DBR CODE 2700036 ACILTD DBR NAME BANGLADESH Md. Azad Amchottar, Nawdapara, City CUSTOMER NAME COUNTRY NAME Ali DEALER ADDRESS Hat Road, Rajshahi, ACI MOTORS - RAJSHAHI DEALER NAME CUSTOMER ADDRESS LZGDR1134190S3 2700036-9476B3-2023-82 Chassis No JobCard No 2700036-9476B3-2022-135 Job Card Date 02-Jul-2022 Warranty Claim No 3105ELU14L1129505 Engine No DI 750 III SUPER 2WD 02-Jul-2022 Date of Failure Tractor Model Last Service Date 3602806371 02-Jul-2022 Invoice No Hours Worked 12-Apr-2022 Date of Sale **FUEL METER WAS NOT** SHOWING PROPER Customer Complaint READING. Last Service Hours Buyer Ref No 28-Dec-2021 Invoice Date 7th Service PDI & Service Details 6th Service 5th Service 4th Service 2nd Service 3rd Service 1st Service PDI 12-Jan-2022 Complaint Details Complaint Des Complaint Code Sub Aggregates INSTRUMENT-FUEL METER NOT WORKING IN06 ELECTRICALS Part Details SE Analysis Billing Type Part Description Quantity Failure Type Part No Complaint Code WARRANTY TANK UNIT CULPRIT PART NO 10022398AA Labour Detail(B) Labour Charge **Labour Hours Labour Code Action Taken** Complaint Code Data not available. Consumables C Rate Amount Qty Description Complaint Code Data not available. OutsideJob (D) Amount BillNo Date Complaint Code Details of Job Data not available. Claim Summary Consumables (C) Labour (B) Part(A) Total(A+B+C+D+E) 22850 0 Sale Tax (E) Outside Job (D) 10022398AA Culprit Part Name Culprit Part No AFTER INSPECTION WE FOUND Dealer Action Taken Complaint status Close Dealer Analysis THAT TANK UNIT HAS DAMAGED TANK UNIT SHOWS 17-Jul-2022 Acknowledgement Date Remarks Acknowledgement Yes WRONG RESISTANCE Acknowledge Done By DIPTENDU ROY 18-Jul-2022 Approval Approved Approved Date Remarks 90012123 Approval Done By SUMESH KUMAR Remarks Payment Date Payment Done By Warranty Claim Date PENDING FOR PAYMENT Date of Upload 07-Jul-2022 07-Jul-2022 Status Service Engineer remarks TANK UNIT SHOWS WRONG RESISTANCE

