ACI Motor Ltd.

WARRANTY CLAIM FORM (New Machinery)

Customer Informations

Customer Code

Mobile

Upazila

District

Md. Abdul Gafur E00260 01877324482 Dhanbari Harvester Details

Warranty Number

Product

HAR/WRT/1399

Harvester AG600 81907A C60B401678 02-Nov-2021

496.00

Complain Details

Customer's Complaint

When the Harvester's augur pipe is lifted up, it has automatically started going down

Tangail

SE Analysis

We checked that and found this problem. After checking all related things in this issue we take decision VALVE ASSY has Internally damaged. Because we check related Solenoid also and it has respond smoothly. Problem has been solved by replaced this mentioned parts.

Model

Engine No

Delivery Date

Working Hour

Parts Details

SL No.	Parts Description	Parts Code	Quantity	Amount	
1	Y-1E9064-66700-VALVE ASSY	SE96		1	160000
Total Amount					160000
MQR Number		Job Card No	40002		
man namber					

Proposed By

Checked By

Recommended By

Approved By

5

SE/Sr.SE/TMS

SCE/SI.SCE/AMS

Manager/Sr.Manager Service

Director