SONALIKA

INTERNATIONAL TRACTORS LIMITED

Vill. Chak Gujran, P.O. Piplanwala , Jalandhar Road, Hoshiarpur

Warranty Claim

											PRIN	Т	
COUNTRY NAME	COUNTRY NAME BANGLADESH			DBR NAME			ACI LTD			DBR CODE		2700036	
DEALER NAME ACI BOGRA BOGRA				DEALER ADDRESS			Bogra			CUSTOMER NAME		Md. Azizul Hoque	
CUSTOMER ADDRESS	8											Hoque	
Warranty Claim No	2700036-	9476B3-2023-14	Jo	obCard No		2700036-94	76B3-2	2023-208	Chass	is No		KXCDJ1234095S3	
Tractor Model	ALL ROUNDER 55 SUPREME			Engine No 4100FL24						ard Date		17-Jan-2023	
Date 17-Jan-2023 Date of Sale 15-Nov-2022				Last Service Date Hours Worked 20.00				Date of Failure Invoice No				17-Jan-2023	
Last Service Hours	13-1100-20	022				LEFT SIDE	HEAD	LIGHT NOT	IIIVOICI	9 140		3602813619	
				ustomer Con	iplaint	WORKING	PROP	ERLY.					
Invoice Date	16-Oct-20	022	В	uyer Ref No									
PDI & Service Details													
PDI	1st Service 2nd		3rd Sen	3rd Service		4th Service		5th Service		6th Service		7th Service	
28-Oct-2022													
Complaint Details					^								
Aggregates Sub Aggregates				Complaint Code			Cor			omplaint Desc			
ELECTRICALS				EL23			EL			ELECTRICAL-HEAD LIGHT HIGH/LOW			
									BEAM NOT WORKING				
Part Details													
Commission Cod							_		_		_		
Complaint Code	CULPRIT PAR	lure Type	Part N 10070176AA		Part De	scription	-	Quantity 1.00	WA	Billing Type RRANTY	-	SE Analysis	
Labour Detail(B)	JOEI IGI FAI	KT NO	1007017022	ITEX	D LIGHT A	331		1.00	True.	in Court			
Complaint Code Action Taken				Labour Code					Labour Hours Labour Charge				
Data not available.													
Consumables C													
Complaint Code Description				Qty			Rate			Am	Amount		
Data not available.													
OutsideJob (D)													
Complaint Code	aint Code Details of Job			BillNo			Date	Date			Amount		
Data not available.													
Claim Summary													
Part(A)		L	abour (B)					Consun	nables	(C)		Control and American Control Control and American American Control and A	
			ale Tax (E)						Total(A+B+C+D+E) 22850				
Culprit Part No	1007017	6AA		Culprit Par	t Name								
	AFTER INSPECTION WE FOUND												
Dealer Analysis	THAT LE	FT SIDE HEAD LIC	SHT	Dealer Acti	on Taken					Complaint	etatue	Close	

