

## INTERNATIONAL TRACTORS LIMITED

Vill. Chak Gujran, P.O. Piplanwala , Jalandhar Road, Hoshiarpur

## Warranty Claim

PRINT ACILTD DBR CODE 2700036 DBR NAME BANGLADESH COUNTRY NAME Sadekul CUSTOMER NAME DEALER ADDRESS Bogra **ACI BOGRA BOGRA** DEALER NAME Islam CUSTOMER ADDRESS EXCDH945613S3 2700036-9476B3-2023-85 Chassis No 2700036-9476B3-2022-138 Warranty Claim No 10-Jul-2022 4100FL04G939518 Job Card Date Engine No DI 55 RX 2WD Tractor Model Date of Failure 10-Jul-2022 Last Service Date 10-Jul-2022 Date 3602809109 Invoice No Hours Worked 1642.00 31-Jan-2021 Date of Sale ENGINE BECAME Customer Complaint Last Service Hours OVERHEATED Buyer Ref No 30-Jul-2020 Invoice Date PDI & Service Details 7th Service 5th Service 6th Service 3rd Service 4th Service 1st Service 2nd Service PDI 07-Sep-2020 Complaint Details Complaint Desc ENGINE-RADIATOR CORE TUBE BLOCKED EN121 ENGINE art Details **Billing Type** SE Analysis Quantity Complaint Code WARRANTY CONSEQUENTIAL PARTS 703405057G GASKET CYL. HEAD (NA) RADIATOR ASSY. (218 TUBE) NA-RX WARRANTY CULPRIT PART NO 803413107B THERMOSTAT ASSY.74 Deg WARRANTY CULPRIT PART NO 8034130160 Labour Detail(B) Labour Code Labour Hours Labour Charge **Complaint Code Action Taken** Data not available Consumables C Qty Rate Amount Complaint Code Description Data not available. OutsideJob (D) BillNo Date Amount Details of Job Complaint Code Data not available. Claim Summary Labour (B) Consumables (C) Part(A) Sale Tax (E) 0 Total(A+B+C+D+E) 22850 Outside Job (D) 803413016C Culprit Part No. Culprit Part Name AFTER INSPECTION WE FOUND THAT COOLANT COULD NOT CIRCULATE THROUGH RADIATOR Dealer Analysis Dealer Action Taken Complaint status Close PROPERLY, THERMOSTAT VALVE HAS DAMAGED. RADIATOR TUBE BLOCKED Acknowledgement 17-Jul-2022 AND THERMOSTAT Remarks CLOGGED Acknowledge Done By DIPTENDU ROY Approved Approval Approved Date 18-Jul-2022 90012124 Approval Done By SUMESH KUMAR

