## SONALIKA

## INTERNATIONAL TRACTORS LIMITED

Vill. Chak Gujran, P.O. Piplanwala, Jalandhar Road, Hoshiarpur

## Warranty Claim

PRINT 2700036 DBR NAME ACILTD DBR CODE BANGLADESH COUNTRY NAME Md.Alom DEALER ADDRESS CUSTOMER NAME ACI RANGPUR Rangpur Rangpur Mondol DEALER NAME CUSTOMER ADDRESS 2700036-9476B5-2023-47 Chassis No LZGDR1134037S3 JobCard No 2700036-9476B5-2022-60 Warranty Claim No 16-Dec-2022 Job Card Date Engine No 3105NH14L1129007 DI 50 RX 2WD Tractor Model Date of Failure 16-Dec-2022 Last Service Date 16-Dec-2022 Date 3602806091 Invoice No Hours Worked 21-Mar-2022 Date of Sale ENGINE STOPPED Customer Complaint SUDDENLY WITH A LOUD Last Service Hours NOISE. 16-Dec-2021 Buyer Ref No Invoice Date PDI & Service Details 7th Service 2nd Service 5th Service 6th Service 1st Service 3rd Service 4th Service PDI 06-Jan-2022 Complaint Details ENGINE-ABNORMAL NOISE FROM ENGINE ENGINE **EN01** Part Details CONSEQUENTIAL PARTS 7034010980 CYLINDER LINER (Ø105) 3.00 WARRANTY WARRANTY CONSEQUENTIAL PARTS PISTON RING SET (Ø105) FM 3.00 203403056A CONSEQUENTIAL PARTS 803403014J CONNECTING ROD ASSY. (common) 1.00 WARRANTY CONSEQUENTIAL PARTS 903003040J Crank Shaft 3cyl. INTG.-FL(common) 39Cr5 1.00 WARRANTY BIG-END LINER KIT Ø64 (6pcs) 0.30u/s-CONSEQUENTIAL PARTS 203003022A 1.00 WARRANTY Main Bearing Set Ø75\_8pcs (Std.)118s CONSEQUENTIAL PARTS 203001008B 1.00 WARRANTY GASKET CYL. HEAD (NA) CONSEQUENTIAL PARTS 703405057G 3.00 WARRANTY CONSEQUENTIAL PARTS 703405106A GASKET (VALVE COVER) FOR 'P'- TYPE 3.00 WARRANTY CONSEQUENTIAL PARTS 703401087A CYLINDER LINER SEALING (Ø105) 9.00 WARRANTY Thrust Bearing Kit (Std) Cu\_110/118st 203401042A CONSEQUENTIAL PARTS 1.00 WARRANTY CULPRIT PART NO 803007060A SUCTION STRAINER (2 & 3 CYL) 1.00 WARRANTY Labour Detail(B) Complaint Code Action Taken Labour Code **Labour Hours** Labour Charge Data not available. Consumables C Complaint Code Description Qty Rate Amount Data not available. OutsideJob (D) Complaint Code Details of Job BillNo Date Amount Data not available. Claim Summary Part(A) Labour (B) Consumables (C) Outside Job (D) Sale Tax (E) 0 Total(A+B+C+D+E) 22850 Culprit Part No 803007060A Culprit Part Name Dealer Analysis AFTER INSPECTION WE FOUND Dealer Action Taken THAT SUCTION STRAINER CRACKED AND SUCTION PIPE FOUND LOOSE, DUE TO LACK OF Complaint status

LUBRICATION CRANK SHAFT.