## LENGTO SONALIKA

## INTERNATIONAL TRACTORS LIMITED

Vill. Chak Gujran, P.O. Piplanwala , Jalandhar Road, Hoshiarpur

Warranty Claim

								PRI	NT
COUNTRY NAME	BANGL	ADESH	DB	R NAME	ACI L	TD		DBR CODE	2700036
DEALER NAME	ACI BOGRA BOGRA		DE	DEALER ADDRESS E		Bogra		CUSTOMER NAME	Md.Sharifu Islam (
CUSTOMER ADDRESS	S								Singra)
								EZ	DDH942584
Varranty Claim No		9476B3-2022-231	JobCar			176B3-2023-17		assis No	-DXCDR110461683
ractor Model	ALL ROU		Engine No 4100FL1- Last Service Date		1099762		Card Date e of Failure	12-Dec-2022 12-Dec-2022	
Date	12-Dec-20				1400.00			e of Failure pice No	12-Dec-2022 5 3602803789
ate of Sale	28-Oct-20	121	Hours V	Worked	1488.00 WHEELS W	VERE NOT	invo	oice No	3602803789
ast Service Hours			Custom	ner Complaint	MOVING LE STEERING	EFT SIDE WHIL	.E		
nvoice Date	17-Sep-2	021	Buyer F	Ref No					
DI & Service Details									
PDI	1st Service	2nd Service	3rd Service	4th Ser	vice	5th Service		6th Service	7th Service
26-Sep-2021	Tot del vice	Zila del vice	ord dervice		V100				
Complaint Details									
Aggregates		Sub Aggregates		Compla	int Code			Complaint Desc	
STEERING SYSTEM				ST21				STEERING -POWER S WORKING	TG MOTOR NOT
Part Details							-		***************************************
Complaint Code	Failure `	Type Part	No I	Part De	scription	T	Quantit	y Billing Type	SE Analysis
	CULPRIT PART			R STEERING UN			00	WARRANTY	
abour Detail(B)							-		The state of the s
Complaint Code	Action	Taken		Labour	Code		Labour I	Hours	Labour Charg
Data not available.									
onsumables C									
Complaint Code	Des		Otv Par				te Amount		
Data not available.		cription			Oty	,	Rate	Amo	ount
Jata not available.		cription			Dty		Rate	Amo	ount
Jata not available.		cription			Oty		Rate	Amo	ount
		cription			Diy		Rate	Amo	ount
utsideJob (D)	Data								
OutsideJob (D)  Complaint Code  Data not available.	Deta	alls of Job			BillNo		Rate		ount
outsideJob (D) Complaint Code Data not available.	Deta								
outsideJob (D) Complaint Code Data not available. Islam Summary	Deta		or (B)				Date	Am	
utsideJob (D)	Deta	ills of Job Labor	ır (B) Fax (E)			Con		Amo	ount
omplaint Code  Data not available.  Jaim Summary	Deta	ills of Job Labor				Con	Date Sumables	Ame	ount
complaint Code Data not available.  Italim Summary  Part(A)  Dutside Job (D)		ulls of Job Labor Sale 1	fax (E)	0		Con	Date Sumables	Ame	ount
outsideJob (D) Complaint Code Data not available. Italim Summary	1002926	ulls of Job Labor Sale 1	Culp			Con	Date Sumables	Ame	ount
outside Job (D)  complaint Code  Data not available.  laim Summary  art(A)  outside Job (D)	1002926 AFTER THAT PO	Labou Sale 1	Culp	0		Con	Date Sumables	Ame	ount
complaint Code Data not available.  Islam Summary  Part(A)  Putside Job (D)  Culprit Part No  Pealer Analysis	1002926 AFTER THAT PO	Labou Sale 1	Culp ID Dea	0 prit Part Name	BillNo	Con	Date Sumables	Amo 5 (C) +D+E) 22850	ount  Close
omplaint Code Data not available.  alim Summary  art(A)  utside Job (D)  fullprit Part No  lealer Analysis	1002926 AFTER I THAT PO COULD Yes	Labor Sale 1 19AA INSPECTION WE FOUN DWER STEERING UNIT NOT BUILD PRESSURI	Culp ID Dea	0 orit Part Name eler Action Taken	BillNo	Con	Date Sumables	Ame  s (C)  +D+E) 22850  Complaint status	ount  Close
outsideJob (D)  complaint Code  Data not available.  laim Summary  art(A)  outside Job (D)  culprit Part No  dealer Analysis  cknowledgement	1002926 AFTER I THAT PO COULD Yes	Labor Sale 1 19AA INSPECTION WE FOUN DWER STEERING UNIT NOT BUILD PRESSURI	Culp Dea  Acknow	0 orit Part Name eler Action Taken	BillNo	Con	Date Sumables	Ame  s (C)  +D+E) 22850  Complaint status  Remarks	ount  Close
complaint Code Data not available.  Idaim Summary  Part(A)  Culprit Part No  Dealer Analysis  Cicknowledgement  Cicknowledge Done By  pproval	1002926 AFTER I THAT PO COULD Yes	Labou Sale 1 Sale 1 SAA INSPECTION WE FOUN DWER STEERING UNIT NOT BUILD PRESSURI	Culp Dea  Acknow	0 prit Part Name ller Action Taken wledgement Date	BillNo	Con	Date Sumables	Ame  s (C)  +D+E) 22850  Complaint status	ount
complaint Code Data not available.  Italm Summary Part(A) Dutside Job (D)	1002926 AFTER I THAT PO COULD Yes	Labor Sale 1 19AA INSPECTION WE FOUN DWER STEERING UNIT NOT BUILD PRESSURI	Culp Dea  Acknow	0 prit Part Name ller Action Taken wledgement Date	BillNo	Con	Date Sumables	Ame  s (C)  +D+E) 22850  Complaint status  Remarks	ount  Close