PRINT

SCR-2700036-2022-1497 25-Oct-2022 2700036 BANGLADESH Distributor Code Distributor Name Country ACI LTD 04-Oct-2022 Dealer Name Scr Related PRODUCT IMPROVMENET Failure Date DISTRIBUTOR STOCK ENGINE-RADIATOR LEAKAGE Complaint Reported Complaint Job Card Date Warranty Status JobCard No. DI 50 RX SUPREME 2WD 3105NH24I1213927 ChassisNo Model DZGDJ1219656S3 Engine No. 04-Oct-2022 Date of Sale Repair Date Hours Other NO Area of Operation Other Attachment Tractor Off Road Other NO Cause of Failure Proposed Solution Repeat Name of Dealer Contact 01730787626 Contact Number Shahed Bin Jahan Reason Person

PDI	1st Service	2nd Service	3rd Service	4th Service	REPAIRIFANY	WARRANTYIFANY
ut.					_	

Distributor/Dealer findings/Observations

Action Taken by the Distributor/ Dealer:-

Coolant was coming out from the Radiator, After inspection we found that Radiator has leakage.

Replaced the failure parts under PDI.

Acknowledgement By Service Team

PDI TRACTOR.

RCA by service Team

VENDOR CODE IS S.M.

AUTO.

Complaint status at Service Team End

Ack Status

Request

YES

Corrective Action

Remarks

Taken/Suggested

Ack Date Seviority

25-Oct-2022

Very High

Details of Parts replaced

Part Number	Part Discription	Failure Part Type	Quantity
800413003A	RADIATOR ASSY. (180 TUBES) FE	CULPRIT PART NO	1

Previous Complaints

Download

No complaints

video.mp4

Vendor.jpg

Download