

## INTERNATIONAL TRACTORS LIMITED

Vill. Chak Gujran, P.O. Piplanwala , Jalandhar Road, Hoshiarpur

Warranty Claim

PRINT ACILTD DBR CODE 2700036 DBR NAME BANGLADESH COUNTRY NAME Md.Shohagh CUSTOMER NAME DEALER ADDRESS Bogra ACI BOGRA BOGRA DEALER NAME Hossen CUSTOMER ADDRESS BZDDR101635583 2700036-9476B3-2022-164 JobCard No 2700036-9476B3-2023-111 Chassis No. Warranty Claim No. 4100FL14A1011628 Job Card Date 13-Aug-2022 60 RX SUPREME 2WD Engine No. Tractor Model 13-Aug-2022 Date of Failure Last Service Date 13-Aug-2022 Date 3602811438 Invoice No Hours Worked 1220.00 30-Apr-2021 Date of Sale WHEELS WERE MOVING SLOWLY WHILE STEERING Customer Complaint Last Service Hours Buyer Ref No 29-Jan-2021 Invoice Date PDI & Service Details 6th Service 7th Service 5th Service 2nd Service 3rd Service 4th Service PDI 1st Service 9-Feb-2021 complaint Details STEERING -POWER STEERING PUMP STEERING SYSTEM ST17 SEIZED Part Details WARRANTY CULPRIT PART NO HYD PUMP ASSY (9.5cc) 2 mtg. P.Steering 803402027A Labour Detail(B) Labour Code Labour Hours Labour Charge Complaint Code **Action Taken** Data not available. Consumables C Rate Qty Amount Complaint Code Description Data not available. OutsideJob (D) BillNo Complaint Code Details of Job Date Amount Data not available. Claim Summary Part(A) Labour (B) Consumables (C) Outside Job (D) Sale Tax (E) 0 Total(A+B+C+D+E) 22850 Culprit Part No Culprit Part Name 803402027A AFTER INSPECTION WE FOUND THAT HYDRAULIC PUMP OF Dealer Action Taken Dealer Analysis Complaint status Close POWER STEERING HAS DAMAGED there is no od Acknowledgement Da Acknowledgement Yes Remarks through pump DIPTENDU ROY Uknowledge Done By

