Hollow Sonalika

INTERNATIONAL TRACTORS LIMITED

Vill. Chak Gujran, P.O. Piplanwala , Jalandhar Road, Hoshiarpur

Warranty Claim

								PRINT		
COUNTRY NAME	NAME BANGLADESH			DBR NAME ACILT				DBR CODE	2700036	
DEALER NAME	ACI MYMENSINGH			DEALER ADDRES		Digharkanda, Chatrapara Aamlitola, Mymensingh		CUSTOMER NAME	Mithun Saha	
CUSTOMER ADDRESS									Guilla	
Warranty Claim No	2700036-9476B1-2023-14			JobCard No				Chassis No	CXQDR1128776S3	
Tractor Model	DI 48 RX 2WD 09-Feb-2023			Engine No			(1123628	Job Card Date	09-Feb-2023 09-Feb-2023	
Date Date of Sale	09-Feb-2023 06-Mar-2022			Last Service Date Hours Worked		998.00		Date of Failure Invoice No	3602805607	
Last Service Hours	OUTIVIAITE VEL			Customer Complaint		TRUMPET HOUSING CRACKED.		mivoled No	3002003007	
Invoice Date	25-Nov-202		Buyer Ref No							
Invoice Bate	20 1101 201			Tyer recrito						
PDI & Service Details										
PDI	1st Service	2nd Service	3rd Ser	vice	4th Ser	vice	5th Service	6th Service	7th Service	
07-Dec-2021					_					
Complaint Details										
Data not available.										
Part Details										
Complaint Code	Complaint Code Failure Type		Part No			escription	Quantity		SE Analysis	
CULPRIT PART NO		300053761A	00053761A TRUMPET HOUSING			1.00	WARRANTY			
Labour Detail(B)										
Complaint Code	omplaint Code Action Taken			Labour			Lab	our Hours	r Hours Labour Charge	
Data not available.										
Consumables C										
Complaint Code	laint Code Description			Qty		Qty	Rate	Amount		
Data not available.										
OutsideJob (D)										
Complaint Code Details of Job				BillNo			Date	ate Amount		
Data not available.										
Claim Summary							,			
Part(A) Labour (B)			Labour (B)	Co			Consur	nsumables (C)		
Outside Job (D)	Job (D) Sale		Sale Tax (E)	0			Total(A	Total(A+B+C+D+E) 2288		
Culprit Part No	3000537	61A		Culprit Part	Name					
Dealer Analysis	AFTER INSPECTION WE FOUND CRACK MARK ON TRUMPET HOUSING.			Dealer Action	on Taken			Complaint statu	s Close	

