ACI Motor Ltd.

WARRANTY CLAIM FORM (New Machinery)

Customer Informations

Name Abdur Rouf Customer Code E00718 Mobile 01676664195 Upazila Haluaghat District Mymensingh

Harvester Details

Product	Harvester
Model	AG600A
Engine No	11828A
Chassis No	C60B500117
Delivery Date	10/04/2022
Working Hour	175.00

Complain Details

Customer's	Complaint
------------	-----------

Engine doesn't start

SE Analysis

After checking we found the ECU, 3.5 Motor Service was faully. Error code was 00 0027F 12. The parts needs to be replaced was decided after doing SA-D diagnosis.

Parts Details

SL No.	Parts Description	Parts Code	Quantity	Amoun	t
1	(Y-1E6B92-80800) ECU, 3.5 MOTOR SERVICE	\$095		1	50000
Total Amount					50000
MQR Number	00	Job Card No	00		
MQR Date	25/05/2022	Job Card Date	23/05/2022		

Proposed By

Checked By

Recommended By

Approved By

HAY MKENNY

SE/Sr.SE/TMS

SCE/Sr.SCE/AMS

Manager/Sr.Manager Service

Director (5 a PD)