2 ND LAB Program

. model small

.data

n db 5

a db 05,07,04,03,06

.code

Mov Ax, @ data

MOV DS, AX

lea si, a

Mov CL, n

dea Ct, = -

out loop; Mov ch, Cl

Mov SI, ooh

in loop: Mov AL, a[si]

inc SI

cmo al, alst

J C Hoexchange

xchq al, a[si]
Mov a[si-1], al-

noexchange: Dec CH

JHZ inloop

Dec CL

JHZ outloop

Mov ah, 4ch

int 21h

END