SHARE

nsulating ipe Lipe Lipe CT

COLD PIPE INSULATOR

• Ourable • Flexible • Water Resistant

Net Weight: 18 oz. (510 g.)

WARNING:

Flammable Aerosol. Contains gas under pressure; May explode if heated.

See Other Cautions on Back Panel.

INSULATING PIPE SPRAY is a spray-on, cold pipe insulation spray that prevents condensation from forming on the exterior of copper, PVC, cast iron, or pipes of other material. Convenient aerosol form with fan spray applicator allows user to get to those hard to reach areas and conforms to irregularly shaped surfaces.







WARNING:

Flammable Aerosol. Contains gas under pressure; May explode if heated causes eye and skin irritation. Suspected of causing cancer.

PREVENTION:

Keep away from heat, sparks open flames, and hot surfaces. No moking Do not pray on an open flame on other ignition source. Pressurized container: Do not plerce or burn, even after use Protect from sunlight. To not expose to temperatures exceeding 51°C/122°F. Store in a well-rentilated place. Wash hands the oughly after handling. Obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Wear protective gloves and eve protection.

RESPONSE

Wash with plenty of water If skin irritation occurs. Get medical attention take off contaminated clothing and wash before

TFIN BYES: Ninse cardiously with water for several wiports. Remove contact largest from the several value of the continue rinsing. If eye irritation persists: Get medical attention.

If exposed or concerned: Get medical advice or attention.

STORAGE:

Store locked up.

DISPOSAL:

Dispose of contents and container in accordance with local, state, and national regulations.

INGREDIENTS/CAS#:

Methylene Chloride (75-09-2); Propane/n-Butane (68476-86-8); Acrylic Polymer (N/A), Hexadecenoic Acid (57-10-3); Octadecanoic acid (57-11-4).

NFPA® RATINGS:

Health: 2; Flammability: 2; Reactivity: 0

DIRECTIONS:

Remove dust and loose dirt from area to be treated. Cover surfaces under area to be treated to avoid overspray. Shake vigorously before using. Continue shaking for one minute and occasionally during use. For proper coating adhesion, apply only to dry surfaces. Hold can 8 to 10 inches from surface and apply several thin coats using a sweeping motion. Allow each coat to dry thoroughly for several minutes before applying the next coat. If product appears to run, then can is too close to surface.

WARNING:

This product contains a chemical known to the State of California to cause cancer.

Sold by:

8014.030315

Share Corp. • P.O. Box 245013 • Milwaukee, WI 53224 • (800) 776-7192 • www.sharecorp.com