G21 G98
G28 U0 W0
M06 T01
M03 S1500
G00 X51 Z01
G71 U1 R1
G71 P01 Q02 U0.1 W0.1 F30
N01 G01 X20 Z0
X20 Z-20
G02 X30 Z-30 R20
G01 Z-40
N02 G03 X50 Z-55 R20
G70 P01 Q02 F25
M06 T02
M03 S300
G00 X21 Z-19
G01 X20 F20
G75 R1
G75 X15 Z-20 P100 Q1000 F20
M06 T03
M03 S300
G00 X21 Z1
G01 X20 F80
G76 P041560 Q20 R0.01
G76 X17.548 Z-17 P0613 Q150 F2
G28 U0 W0
M05
M30