N05 G21 G99 N10 G28 U0 W0 N15 M06 T01 N20 M03 S1200

N25 M08

N30 G00 X0 Z2

N35 G71 U1 R0.5 N40 G71 P45 Q90 U0.5 W0.5 F0.2

N45 G01 X0 Z0

N55 G03 X16 Z-5 R9

N60 G01 Z-10

N70 G02 X21 Z-15 R5

N75 G01 X32 Z-18

N80 G01 Z-28

N85 G02 X42 Z-33 R5

N90 G01 X50 Z-55

N128 M06 T02

N129 G70 P45 Q90 U0.5 W0.5 F0.15

N105 M06 T02

N110 M03 S600

N115 G01 X50 N137 G01 Z-66

N120 G75 R0.5

N125 G75 X44 Z-66 P2000 Q2000 F0.15

N140 G28 U0 W0

N145 M09

N150 M05

N155 M30