Wait Multiple() EXECUTE ENTER START -> SETUP OVERKIDE OVERRIDE LEGS -Mission start - not suspended - tay heard MAIN sleep for leg. READ + PARSE runtine after THREAD STATUS MSGS Issuing ammands RELEASE OVERRIDE UPDATE MEADING - I VEHICLE STATUS STATUS READER THREAD COM TAG LISTENER THREAD Port KEEP-ALIVE LISTEN FOR CHANGE MSG IN CODE FILE. SIGNAL FOR OVERFIDE CHECK FOR MSG (Set Event) CHANGE SEND KEEPALIVE MSG = MUTEX KEEPALIVE THREAD & = Skep () or on Timer Queve