Report No: TSD/11 dated Apr-06

TITLE: WELDING POSITIONS & VARIOUS TYPES OF JOINTS

CONTENTS:

- 1. Introduction
- 2. Welding joints



1.0 WELDING POSITIONS:

A procedure specification always designates the positions in which the welding shall be done. The se positions are schematically shown in figure-1 to figure-4.




Figure-1: Positions of test plates for groove welds.




Figure-2: Positions of test pipes for groove welds.

Report No: Dwekam/TSD/11 dated Apr-06




Figure-3: Positions of test plates for fillet welds.




Figure-4: Positions of test pipes for fillet welds.

2.0 WELDING JOINTS:





The loads in a welded structure are transferred from one member to another through weld placed in the joints. The type of joints used in a welded construction and the applicable welds are shown in figure-5 to figure-9.




Figure-5: Types of weld joints.






Figure-6: Single groove welds.

(G) Single-Flare-Bevel-Groove Weld

(H) Single-Flare-V-Groove Weld

Report No: Dwekam/TSD/11 dated Apr-06





Figure-7: Double groove welds.



Report No: Dwekam/TSD/11 dated Apr-06







Figure-8: Fillet welds.

Figure-9: Various corner joints

The description of various features of a fillet weld bead is shown in figure-10.






Figure-10: Fillet weld configuration – (A) convex fillet and (B) concave fillet.

