```
C:\MASM>masm binsearch;;
Microsoft (R) Macro Assembler Version 5.00
Copyright (C) Microsoft Corp 1981-1985, 1987. All rights reserved.

51458 + 465086 Bytes symbol space free

0 Warning Errors
0 Severe Errors

C:\MASM>link binsearch;;

Microsoft (R) Overlay Linker Version 3.60
Copyright (C) Microsoft Corp 1983-1987. All rights reserved.

LINK: warning L4021: no stack segment

C:\MASM>binsearch

ELEMENT FOUND IN THE LIST...
C:\MASM>
```

```
C:\MASM>masm binsearch;;
Microsoft (R) Macro Assembler Version 5.00
Copyright (C) Microsoft Corp 1981-1985, 1987. All rights reserved.

51458 + 465086 Bytes symbol space free

0 Warning Errors
0 Severe Errors

C:\MASM>link binsearch;;

Microsoft (R) Overlay Linker Version 3.60
Copyright (C) Microsoft Corp 1983-1987. All rights reserved.

LINK: warning L4021: no stack segment

C:\MASM>binsearch

SEARCH FAILED!! ELEMENT NOT FOUND IN THE LIST
C:\MASM>
```