ASSIGNMENT 5

20214263 **SHASHI RAJ CSED REQUIREMENT:** Cat5e Cable **RJ45 Connectors** Cable Stripper Scissors Crimping tool Steps followed to make wire Step 1: Stripping the cable end and we need to take care of it so that we do not cut the wire. Step 2: Since the wires are twisted we need to untwist them . Step 3: Now according to the need we need to arrange the wires. For straight through wire 1.White Orange 2.Orange 3.White Green 4.Blue 5.White Blue 6.Green

7.White Brown

8.Brown

For Crossover cable wiring	
Connector A	
1. White Orange	
2.Orange	
3. White Green	
4.Blue	
5.White Blue	
6.Green	
7.White Brown	
8.Brown	
Connector B	
1.white green	
2. Green	
3. White Orange	
4.Blue	
5.White blue	
6.Orange	
7.White brown	
8.Brown	
Step 4:	
We need to trim all wires evenly and about half inch it should be exposed	
Step 5:	
While maintaining the order attach the connector.	
Step 6.	
Now checking whether the wire has reached to the tip of the connector.	
Step 7:	

At last we have to crimp the connector onto cable end (8p) and squeeze it firmly.

Step 8:

Testing of the wire has to be done using testing equipment.