




Timing diagram for MDR, TOS = [MDR] + [H]




Control signals are set up




Drive H and B bus




ALU and shifter



ALU and shifter



Propagation from shifter to C bus



Registers loaded from C bus