Name & Signature: Name & Signature:	Requested by Check-up done by: Work accepted by:	ype is not a Dependive compressive by. 7 low fire on	Brief Description Check-up finding Job Order:	Work Requested: Parts and labor services for the repair of Split Type Air-conditioning Unit located at FASD Area	REQUEST FOR MAINTENANCE	DEPARTMENT OF SCIENCE AND TECHNOLOGY Regional Office No. X
Name & Signature Date: 76 FFB. 7070	Corrective maintenance by:	> Attached is the service	Corrective Maintenance Performed:	Received by: RAPangan	ANCE	TECHNOLOGY
Name & Signature: Date: No prob 1272	End-user Receipt	Acris jours of the operational.	Inspection & Acceptance:	Date: 18 February 2020		

VP REF'S & AIRCONS SERVICES

Carinugan, Balulang CDO Cell # 0926-255-3134

CUSTOMER:

DOST - X

ADDRESS :

CARMEN, C.D.O.C.

DATE

August 26,2020

SERVICE REPORT

SCOPE OF WORK: REPAIR

PARTICULARS

LOCATION

1 UNIT

SPLIT TYPE AIRCONDITIONING

ADMIN OFFICE

- Replacement of Brand new compressor
- Recharging of Freon 22
- The unit is in good condition and operational.

NOTE: Per P.O. # 20-03-061, Dated: March 11, 2020

PHEPARED HY:

VAN VICTOR B. PIL