# **HVAC Tutorial**

# Place Fittings



PROCESS, POWER & MARINE

Version 2014





## Copyright

© 1999-2014 Intergraph® Corporation and/or its affiliates. All Rights Reserved.

Warning: This computer program, including software, icons, graphical symbols, file formats, and audio-visual displays; may be used only as permitted under the applicable software license agreement; contains confidential and proprietary information of Intergraph and/or third parties which is protected by patent, trademark, copyright and/or trade secret law and may not be provided or otherwise made available without proper authorization.

#### **Restricted Rights Legend**

Use, duplication, or disclosure by the Government is subject to restrictions as set forth in subparagraph (c) (1) (ii) of the Rights in Technical Data and Computer Software clause at DFARS 252.227-7013 or subparagraphs (c) (1) and (2) of Commercial Computer Software -- Restricted Rights at 48 CFR 52.227-19, as applicable.

Unpublished - rights reserved under the copyright laws of the United States.

#### Terms of Use

Use of this software product is subject to the End User License Agreement ("EULA") delivered with this software product unless the licensee has a valid signed license for this software product with Intergraph Corporation. If the licensee has a valid signed license for this software product with Intergraph Corporation, the valid signed license shall take precedence and govern the use of this software product. Subject to the terms contained within the applicable license agreement, Intergraph Corporation gives licensee permission to print a reasonable number of copies of the documentation as defined in the applicable license agreement and delivered with the software product for licensee's internal, non-commercial use. The documentation may not be printed for resale or redistribution.

#### **Warranties and Disclaimers**

All warranties given by Intergraph Corporation about software are set forth in the EULA provided with the software or with the applicable license for the software product signed by Intergraph Corporation, and nothing stated in, or implied by, this document or its contents shall be considered or deemed a modification or amendment of such warranties.

Intergraph believes the information in this publication is accurate as of its publication date. Intergraph Corporation is not responsible for any error that may appear in this document. The information and the software discussed in this document are subject to change without notice.

#### **Trademarks**

Intergraph and the Intergraph logo are registered trademarks of Intergraph Corporation. Hexagon and the Hexagon logo are registered trademarks of Hexagon AB or its subsidiaries. Microsoft and Windows are registered trademarks of Microsoft Corporation. Other brands and product names are trademarks of their respective owners.

#### SESSION 4

# **Place Fittings**

## Objective

By the end of this session, you will be able to:

Place fittings such as elbows and tees in a ductwork.

## Before Starting this Procedure

- SP3D Overview
- SP3D Common Sessions
- Routing a Duct


## **Overview**

Fittings can be inserted into an existing ductwork or added to the ends of existing duct paths. A typical way to do this is to use the **Insert In-Line Component** command. Because Smart 3D by default generates part geometry (metal sheet) by taking the cross-section shape and size during modeling, you can replace these parts (metal sheet) with Catalog items. The part that results from the replace method is a Catalog item that can be purchased. These items are generally reported on a Material Take off Report for purchasing.

In this session, because a typical ductwork is already routed, you will learn the procedure to place the following fittings using the replace method.

- Tee
- HVAC elbow
- HVAC Square elbow

Miter elbow




# **Place a Fitting**

Place a **Rectangular Tee** fitting at an intersection between two duct paths.

Before placing the fitting, ensure that you define the workspace to include **Unit U06**, activate the HVAC task, and select **HVAC\_CS** as the coordinate system. Activate **PinPoint**, set the target to origin, and change **Locate Filter** to **Duct Features**.

1. Select the **Duct Along Leg Feature** located at the intersection between the two duct paths. Use **QuickPick** to help you select the **Duct Along Leg Feature**.




The **Duct Feature** ribbon displays.

2. Select More from the Part list.




The Select Part dialog box displays.

3. Expand Branches > RectTee to select RectTee1.




- 4. Click OK.
- 5. Click in the graphic view to place the tee.

6. Place an HVAC elbow fitting. Select the turn feature to be inserted by the HVAC elbow, and then select the **HVACEIbow** part under **\Turns\HVACEIbow** from the Catalog.




7. Perform the same steps that you performed for placing a rectangular tee fitting and select the **HVACsqrThroatElbow01** part to place an HVAC square-throat elbow.

TIP The HVACsqrThroatElbow01 part is located under the \Turns\HsqrThroatElbow



8. Place a miter elbow. Select **Miter** as the part type, and then specify the number of **Miters** as **1** on the **Duct Feature** ribbon.





For more information related to inserting fittings, see the HVACUsersGuide.pdf file.