Drawing Creation Tutorial

Drawings by Query



PROCESS, POWER & MARINE

Version 2014

Friday, June 13, 2014





Copyright

© 2014 Intergraph® Corporation and/or its affiliates. All Rights Reserved.

Warning: This computer program, including software, icons, graphical symbols, file formats, and audio-visual displays; may be used only as permitted under the applicable software license agreement; contains confidential and proprietary information of Intergraph and/or third parties which is protected by patent, trademark, copyright and/or trade secret law and may not be provided or otherwise made available without proper authorization.

Restricted Rights Legend

Use, duplication, or disclosure by the Government is subject to restrictions as set forth in subparagraph (c) (1) (ii) of the Rights in Technical Data and Computer Software clause at DFARS 252.227-7013 or subparagraphs (c) (1) and (2) of Commercial Computer Software -- Restricted Rights at 48 CFR 52.227-19, as applicable.

Unpublished - rights reserved under the copyright laws of the United States.

Terms of Use

Use of this software product is subject to the End User License Agreement ("EULA") delivered with this software product unless the licensee has a valid signed license for this software product with Intergraph Corporation. If the licensee has a valid signed license for this software product with Intergraph Corporation, the valid signed license shall take precedence and govern the use of this software product. Subject to the terms contained within the applicable license agreement, Intergraph Corporation gives licensee permission to print a reasonable number of copies of the documentation as defined in the applicable license agreement and delivered with the software product for licensee's internal, non-commercial use. The documentation may not be printed for resale or redistribution.

Warranties and Disclaimers

All warranties given by Intergraph Corporation about software are set forth in the EULA provided with the software or with the applicable license for the software product signed by Intergraph Corporation, and nothing stated in, or implied by, this document or its contents shall be considered or deemed a modification or amendment of such warranties.

Intergraph believes the information in this publication is accurate as of its publication date. Intergraph Corporation is not responsible for any error that may appear in this document. The information and the software discussed in this document are subject to change without notice.

Trademarks

Intergraph and the Intergraph logo are registered trademarks of Intergraph Corporation. Hexagon and the Hexagon logo are registered trademarks of Hexagon AB or its subsidiaries. Microsoft and Windows are registered trademarks of Microsoft Corporation. Other brands and product names are trademarks of their respective owners.

SESSION 11

Drawings by Query

Objective

By the end of this session, you will be able to:

- Specify the "where" filter to create drawing by query for hanger supports
- Edit the Coordinate System property of a drawing to create location plans

Overview

A general arrangement drawing allows you to control the look and feel of each drawing. For instance, you can specify the number of views in a sheet, as well as other properties of the views. Composed drawings are used to create general arrangement drawings. Composed drawings require you to place volumes or snapshot views for each portion of the model, and then associate views to volumes to finalize the drawings.

Smart 3D also allows you to create orthographic drawings using a filter-based query. This can be useful when many objects in the model, such as hangers or equipment, need to be documented with the same view layout, properties, and style. With drawings by query, there is no need to place volumes in the model. Volumes are generated based on the object that is the subject of the drawing, as well as navigation rules, which further control the size of the volume and the contents of the view.

In this session, we cover the procedure for how to create a drawing by query. We will also edit properties at a folder level and see that it propagates down to each child drawing.


Create Drawings by Query

NOTE This task is typically performed by your administrator.


- 1. Switch to the **Drawing Console** window.
- Right-click the Drawings Creation Filters\11 folder in the Drawing Console, and select New.

The Add Component dialog box displays.

 Select Drawings by Query Manager on the General tab of the Add Component dialog box.




4. Click **OK** on the **Add Component** dialog box to place a new component called **Drawings By Query Manager** under the **11** folder.



- 5. Right-click **Drawings By Query Manager** in the **Drawing Console**, and select **Rename**.
- 6. Type **Hanger Support Drawings**.
- 7. Right-click **Hanger Support Drawings** in the **Drawing Console**, and select **Setup**.





8. Select More from the Filter list on the Setup dialog box.


The **Select Filter** dialog box displays.

- Expand the 11 folder under the Drawings Creation Filters node on the Select Filter dialog box
- 10. Select the U01 Drawing filter.
- 11. Click **OK** on the **Select Filter** dialog box.


The software populates the **Filter** field on the **Setup** dialog box.

12. Select More from the Package list on the Setup dialog box.





- 13. Select HngSup3View Style2 on the Select Package dialog box.
- 14. Click **OK** on the **Select Package** dialog box.



The software returns control to the **Setup** dialog box.


- 15. Click **OK** on the **Setup** dialog box to save and exit the setup of the DBQM component.
- 16. Right-click **Hanger Support Drawings** on the **Drawing Console**,and select **Run Query**.

The software constructs the hierarchy underneath the DBQM component.

The hierarchy is constructed from the filter value on the DBQM setup, in this case the **U01** unit system, down to each hanger assembly.

17. Right-click **Hanger Support Drawings** on the **Drawing Console**, and select **Create Drawing(s)**.

The software creates a drawing for each hanger assembly under the **U01** unit system.



18. Expand **Hanger Support Drawings** and each node underneath until the drawing displays.


19. Right-click the drawing on the **Drawing Console**, and select **Update Now**.

The software generates the drawing.

20. After the update completes, right-click the drawing on the **Drawing Console** window, and select **Edit.**

The SmartSketch Drawing Editor window displays.


- 21. Maximize the drawing window in **SmartSketch Drawing Editor**.
- 22. Click Fit 🔯.



The drawing contents should look similar to the picture below:

23. Click Zoom Area 🔯.

24. Drag a rectangle around the top left quadrant of the drawing to get a closer look at the contents.



The grid bubbles are empty. This is because the distances are measured from the Global origin. In the next section of this lab, you will measure the hanger key point relative to the closest grid intersection of the U01 CS coordinate system.


25. Click **File > Exit** to exit **SmartSketch Drawing Editor**. You do not need to save the drawing because you did not change it.

Modify Coordinate System for Labels

- 1. Switch to the **Drawing Console** window.
- 2. Right-click the **Hangers Support Drawings** component in the **Drawing Console**, and select **Properties**.

The **Properties** dialog box displays.

- 3. Click the Style tab on the Properties dialog box.
- 4. Select U01 CS from the Coordinate System list.



- 5. Click **OK** on the **Properties** dialog box.
- 6. Right-click the drawing in the **Drawing Console**, and select **Update Now**.
- 7. The property change updates.
- 8. Right-click the drawing In the **Drawing Console**, and select **Update Now**.


The software generates the drawing.

9. After the update completes, right-click the drawing in the **Drawing Console** window, and select **Edit**.

The SmartSketch Drawing Editor window displays.

- 10. Maximize the drawing window in SmartSketch Drawing Editor.
- 11. Click Fit 🛂.

- 12. Click **Zoom Area**
- 13. Drag a rectangle around the top left quadrant of the drawing to get a closer look at the contents.



The grid bubbles are populated, indicating the nearest grid intersection to the assembly.

14. Click **File > Exit** to exit **SmartSketch Drawing Editor**. You do not need to save the drawing because you did not change it.