

SmartPlant 3D Piping Reference Data

Student Workbook

Process, Power & Marine









Copyright

Copyright © 2006 Intergraph Corporation. All Rights Reserved.

Including software, file formats, and audiovisual displays; may be used pursuant to applicable software license agreement; contains confidential and proprietary information of Intergraph and/or third parties which is protected by copyright law, trade secret law, and international treaty, and may not be provided or otherwise made available without proper authorization.

Restricted Rights Legend

Use, duplication, or disclosure by the Government is subject to restrictions as set forth in subparagraph (c) of the *Contractor Rights in Technical Data* clause at DFARS 252.227-7013, subparagraph (b) of the *Rights in Computer Software or Computer Software Documentation* clause at DFARS 252.227-7014, subparagraphs (b)(1) and (2) of the *License* clause at DFARS 252.227-7015, or subparagraphs (c) (1) and (2) of *Commercial Computer Software---Restricted Rights* at 48 CFR 52.227-19, as applicable.

Unpublished---rights reserved under the copyright laws of the United States.

Intergraph Corporation Huntsville, Alabama 35894-0001

Warranties and Liabilities

All warranties given by Intergraph Corporation about equipment or software are set forth in your purchase contract, and nothing stated in, or implied by, this document or its contents shall be considered or deemed a modification or amendment of such warranties. Intergraph believes the information in this publication is accurate as of its publication date.

The information and the software discussed in this document are subject to change without notice and are subject to applicable technical product descriptions. Intergraph Corporation is not responsible for any error that may appear in this document.

The software discussed in this document is furnished under a license and may be used or copied only in accordance with the terms of this license.

No responsibility is assumed by Intergraph for the use or reliability of software on equipment that is not supplied by Intergraph or its affiliated companies. THE USER OF THE SOFTWARE IS EXPECTED TO MAKE THE FINAL EVALUATION AS TO THE USEFULNESS OF THE SOFTWARE IN HIS OWN ENVIRONMENT.

Trademarks

Intergraph, the Intergraph logo, SmartSketch, FrameWorks, SmartPlant, INtools, MARIAN, and PDS are registered trademarks of Intergraph Corporation. Microsoft and Windows are registered trademarks of Microsoft Corporation. MicroStation is a registered trademark of Bentley Systems, Inc. ISOGEN is a registered trademark of Alias Limited. Other brands and product names are trademarks of their respective owners.

Table of Contents

Preface	4
Lab 1: Piping Material Class	5
Lab 2: Piping Specification Validation	12
Lab 3: Piping Commodity Part Data	17
Lab 4: Branch Insertion Rule	19
Lab 5: Bolted Components and Valve Operators	24
Lab 6: Connection Components	32
Lab7: PipeTakedown Parts Rule	34
Lab 8: Permissible Taps Rule	36
Lab 9: Model/Catalog Synchronization	38
Lab 10: Reportable Piping Commodity	40
Lab 11: Substitution Cap Screw Commodity Code	45
Lab 12: Custom Engineered/Stock Instruments	51
Lab 13: Instrument "On the Fly"	55
Lab 14: Piping Commodity Procurement Data	57
Lab 15: Create/Modify Spec in Catalog Task (Optional)	60

Preface

This document is designed as an aid for students attending the SmartPlant 3D Reference Data class presented by Intergraph Corporation, and it's a supplement to the standard product documentation.

Objective

This document is designed to provide comprehensive information of what is in SmartPlant 3D Reference Data version 6.1

Course description

Upon completing this course, you will be able to:

• Provide an overview of the SmartPlant 3D reference data. It describes general information about the catalog schema, terms, and the delivered piping reference data.

Course Reference Material

- SmartPlant 3D Reference Data Guide
- SmartPlant 3D Symbols Reference Data Guide
- Piping Reference Data Guide

Questions or suggestions relating to this document should be directed to:

SmartPlant 3D Training Services

Lab 1: Piping Material Class

Objective

After completing this lab, you will be able to:

• Create a new Piping Material Class

Note: This lab is intended as a basic introduction to spec creation. As such it is limited to straight pipe and few fittings (Example: 90 and 45 degree elbows, tees, etc). It is not intended as an example of a functional design spec.

Creating the Piping Specification CC150-1 Bulkload Worksheet

- Open the Ten_Specs_SpecificationData.xls file located in <SP3DInstalled_Location>\ CatalogData\BulkLoad\DataFiles
- 2. Select the following worksheets while holding down the control key:
 - a. PipingMaterialsClassData
 - b. PipingCommodityFilter
 - c. BendAngles
 - d. PipeNominalDiameters
 - e. WeldClearanceRule
 - f. StandardNotesData
- 3. Save the worksheets to a new Excel Workbook named "CC150-1.xls" in your own working directory.

Editing Piping Material Class Data

- 1. Open the PipingMaterialsClassData worksheet in the CC150-1.xls workbook.
- 2. Add the following data in the columns noted for the new piping specification.
 - a. SpecName: CC150-1
 - b. MaterialsOfConstructionClass: 31 (Reference AllCodeLists.xls, MaterialsOfConstructionClass)

c. MaterialsDescription: CL150, Carbon Steel, RFFE, .75" - 24" BE

d. FluidService: Process

e. DesignStandard : 40 (Reference AllCodeLists.xls, DesignStandard - ANSI-B31.3)

f. AutomatedFlangeSelectionOption: 10 (Reference AllCodeLists.xls - Enable)

g. PipingSpecStatus: 5 (Reference AllCodelists.xls, PipingSpecStatus- Draft)

h. Comments: Training Specs

i. RevisionNumber: A

j. PipingNote1: 203

3. Save the workbook.

Editing Piping Diameter Data

1. Open the NominalDiameter worksheet.

2. Add records for the new specification as shown below:

Head Start	SpecName	Npd	NpdUnitType
	CC150.1	0.75	in.
a	CC150-1	0.75 1	in
a			in
a		1.5	in
а		2	in
а		4	in
а		6	in
а		8	in
а		10	in
а		12	in
а		14	in
а		16	in
а		18	in
а		20	in
а		24	in
End			

3. Save the worksheet

Editing Bend Angle Data

- 1. Open the Bend Angle worksheet.
- 2. Add records for preferred bend angles for the new specification as shown below:

Head	SpecName	Npd	MpdUnitType	BendAngle
Start				
a	CC150-1	0.75	in	90deg
a	00100-1	1	in	90dea
a		1.5	in	90deg
a		2	in	90deg
a		4	in	90deg
a		6	in	90deg
а		8	in	90deg
а		10	in	90deg
а		12	in	90deg
а		14	in	90deg
а		16	in	90deg
а		18	in	90deg
а		20	in	90deg
а		24	in	90deg
а		0.75	in	45deg
а		1	in	45deg
а		1.5	in	45deg
а		2	in	45deg
а		4	in	45deg
а		6	in	45deg
а		8	in	45deg
а		10	in	45deg
а		12	in	45deg
а		14	in	45deg
а		16	in	45deg
а		18	in	45deg
а		20	in	45deg
a		24	in	45deg
End				

3. Save the worksheet.

Editing WeldClearanceRule Data

- 1. Open the WeldClearanceRule worksheet.
- 2. Add records for the new specification as shown below:

Head	SpecName	NominalPipingDiameterFrom	NominalPipingDiameterTo	NominalPipingDiameterUnits	WeldClass	WeldClearanceRadiusIncrease	WeldClearanceLength
Start							
a	CC150-1	0.75	6	in	5	6in	18in
		_			_		
а		8	12	in	5	8in	24in
a a		14	24	in	5	8in 16in	30in
a a		14 0.75	24 6	in in	5 10	8in 16in 6in	30in 18in
a a a		14 0.75 8	24 6 12	in in in	5 10 10	8in 16in 6in 8in	30in 18in 24in
a a a		14 0.75 8 14	24 6 12 24	in in in	5 10 10 10	8in 16in 6in 8in 16in	30in 18in 24in 30in
a a a a		14 0.75 8 14 0.75	24 6 12 24 6	in in in in	5 10 10 10 15	8in 16in 6in 8in 16in 6in	30in 18in 24in 30in 18in
a a a		14 0.75 8 14 0.75 8	24 6 12 24 6 12	in in in in in	5 10 10 10 15 15	8in 16in 6in 8in 16in 6in	30in 18in 24in 30in 18in 24in
a a a a		14 0.75 8 14 0.75 8 14	24 6 12 24 6 12 24	in in in in in in in	5 10 10 10 15 15	8in 16in 6in 8in 16in 6in 8in	30in 18in 24in 30in 18in 24in 30in
a a a a a		14 0.75 8 14 0.75 8 14 0.75	24 6 12 24 6 12 24 6	in in in in in in in in	5 10 10 10 15 15 15	8in 16in 6in 8in 16in 6in 8in 16in	30in 18in 24in 30in 18in 24in 30in 18in
a a a a a a		14 0.75 8 14 0.75 8 14 0.75	24 6 12 24 6 12 24 6 12	in in in in in in in	5 10 10 10 15 15 15 20 20	8in 16in 8in 16in 6in 8in 16in 8in	30in 18in 24in 30in 18in 24in 30in 18in 24in
a a a a a a a		14 0.75 8 14 0.75 8 14 0.75	24 6 12 24 6 12 24 6	in in in in in in in in	5 10 10 10 15 15 15	8in 16in 6in 8in 16in 6in 8in 16in	30in 18in 24in 30in 18in 24in 30in 18in

3. Save the worksheet.

Creating Piping Material Class Records

- 1. Open the PipingCommodityFilter worksheet.
- 2. Add records for pipes, bends, size changes and tee as shown below:


Item	Size	Schd	Commodity Code	Description
Pipe	0.75" – 1.5"	S-XS	PAAZZBPZZABAABSAAZZUS	Pipe, plain ends, ASTM-A106-B, [401]
Pipe	2"-24"	S-STD	PAAZZBOZZABAABOAAZZUS	Pipe, [401], BE, ASTM-A53-B Type S
PipeBend (default)	0.75"- 1.5"	S-XS	PAAZZBPZZABAABSAAZZUS	Pipe, plain ends, ASTM-A106-B, [401] Bend Radius 3 D
45 Deg Elbow (Default)	2"-24"	S-STD	MBXZZBOZZAAEADCZZUS	45 deg LR elbow, [403], BE, ASTM-A234-WPB, ANSI-B16.9
45 Deg Trimmable Elbow (Default)	2"-24"	S-STD	MBXZZBOZZAAEADCZZUS	45 deg LR elbow, [403], BE, ASTM-A234-WPB, ANSI-B16.9
90 Deg Elbow (Default)	2"-24"	S-STD	MCMZZBOZZAAEADCZZUS	90 deg LR elbow, [403], BE, ASTM-A234-WPB, ANSI-B16.9
90 Deg Trimmable Elbow (Default)	2"-24"	S-STD	MCMZZBOZZAAEADCZZUS	90 deg LR elbow, [403], BE, ASTM-A234-WPB, ANSI-B16.9
Concentric Size Change	4"-24"	S-STD	MBCZZBOZZAAEADCZZUS	Concentric reducer, [414], BE, ASTM-A234-WPB, ANSI-B16.9
Eccentric Size Change	4"-24"	S-STD	MBJZZBOZZAAEADCZZUS	Eccentric reducer, [414], BE, ASTM-A234-WPB, ANSI-B16.9
Tee	2"-24"	S-STD	Tee01	Tee, [403], BE, ASTM-A234-WPB, ANSI-B16.9

Head	SpecName	ShortCode	OptionCode	FirstSizeFrom	FirstSizeTo	FirstSizeUnits	SecondSizeFrom	SecondSizeTo	SecondSizeUnits	MultisizeOption	Comments	SelectionBasis	MaximumTemperature	MinimumTemperature	EngineeringTag		CommodityCode	FabricationCategoryOverride	SupplyResponsibilityOverride	FirstSizeSchedule	SecondSizeSchedule	ReportableCommodityCode	QuantityOfReportableParts	AssociatedCommodityCode	BendRadiusMultiplier
Start	CC150-1	Dining	1	0.75	1.5	in						1				PAAZZBPZZABAABSAAZZUS				S-XS		-			
a	50 150-1	Piping	- 1	0.75								1			-	PAAZZBOZZABAABOAAZZUS				S-STD		+	-		
a		<45 Degree Direction Change	1									35				PAAZZBPZZABAABSAAZZUS				S-XS			-		3
a		45 Degree Direction Change	1									35				PAAZZBPZZABAABSAAZZUS				S-XS		+	-		3
a		45-90 Degree Direction Chang										35				PAAZZBPZZABAABSAAZZUS				S-XS					3
a		90 Degree Direction Change		0.75								35				PAAZZBPZZABAABSAAZZUS				S-XS					3
a		<45 Degree Direction Change	1	_								70				MBXZZBOZZAAEADCZZUS				MATCH	MATCH				Ť
a		45 Degree Direction Change	1									65				MBXZZBOZZAAEADCZZUS				MATCH	MATCH				$\overline{}$
a		45-90 Degree Direction Chang		_								70				MCMZZBOZZAAEADCZZUS				MATCH	MATCH		_		$\overline{}$
a		90 Degree Direction Change	1	_								65				MCMZZBOZZAAEADCZZUS				MATCH	MATCH		_		
а		Concentric Size Change	1	4	4	in	2	2	in			1				MBCZZBOZZAAEADCZZUS				MATCH	MATCH				\Box
а		Concentric Size Change	- 1	6	6	in	4	4	in			1				MBCZZBOZZAAEADCZZUS				MATCH	MATCH				\Box
a		Concentric Size Change	1	8	8	in	4	6	in			1				MBCZZBOZZAAEADCZZUS				MATCH	MATCH				
a		Concentric Size Change	1	10	10	in	4	8	in			1				MBCZZBOZZAAEADCZZUS				MATCH	MATCH				
a		Concentric Size Change	- 1	12	12	in	6	10	in			1				MBCZZBOZZAAEADCZZUS				MATCH	MATCH				
a		Concentric Size Change	- 1	14	14	in	6	12	in			1				MBCZZBOZZAAEADCZZUS				MATCH	MATCH				
a		Concentric Size Change	- 1	16	16	in	8	14	in			1				MBCZZBOZZAAEADCZZUS				MATCH	MATCH				
a		Concentric Size Change	- 1	18	18	in	10	16	in			1				MBCZZBOZZAAEADCZZUS				MATCH	MATCH				
a		Concentric Size Change	- 1	20	20	in	12	18	in			1				MBCZZBOZZAAEADCZZUS				MATCH	MATCH				
a		Concentric Size Change	- 1	24	24	in	16	20	in			1				MBCZZBOZZAAEADCZZUS				MATCH	MATCH				
a		Eccentric Size Change	- 1	4	4	in	2	2	in			1				MBJZZBOZZAAEADCZZUS				MATCH	MATCH				
a		Eccentric Size Change	- 1	6	6	in	4	4	in			1				MBJZZBOZZAAEADCZZUS				MATCH	MATCH				
a		Eccentric Size Change	- 1	8	8	in	4	6	in			1				MBJZZBOZZAAEADCZZUS				MATCH	MATCH				
a		Eccentric Size Change	- 1	10	10	in	4	8	in			1				MBJZZBOZZAAEADCZZUS				MATCH	MATCH				
a		Eccentric Size Change	- 1	12	12	in	6	10	in			1				MBJZZBOZZAAEADCZZUS				MATCH	MATCH				
а		Eccentric Size Change	1	14	14	in	6	12	in			1				MBJZZBOZZAAEADCZZUS				MATCH	MATCH				
а		Eccentric Size Change	- 1	16	16	in	8	14	in			- 1				MBJZZBOZZAAEADCZZUS				MATCH	MATCH				
a		Eccentric Size Change	- 1	18	18	in	10	16	in			1				MBJZZBOZZAAEADCZZUS				MATCH	MATCH				
a		Eccentric Size Change	1	20	20	in	12	18	in			- 1				MBJZZBOZZAAEADCZZUS				MATCH	MATCH				
а		Eccentric Size Change	1	24	24		16	20	in			1				MBJZZBOZZAAEADCZZUS				MATCH	MATCH				
а		Tee	1	2	24	in						1				Tee01				MATCH	MATCH				

- 3. Save the worksheet.
- 4. Select Start => Programs => Intergraph SmartPlant3D => Database Tools => Bulkload Reference Data.
- 5. The Bulkload Utility form will appear.
- 6. Select the "Add" option under "Excel Files" and select CC150-1.xls
- 7. Load the records into the database using the "Add/Modify/Delete" mode.
- 8. Select an existing piping catalog. Find your catalog server name and database/schema names from the pull down menus. Obtain these names from the instructor.

Note: If the file is loaded into a new catalog, then additional data files will be required and the spec will be unusable until the required files are loaded into the database – this lab assumes that a functional catalog with existing specs and rules exists.

- 9. Enter a Log file name in your working directory.
- 10. Point the Symbol path to the symbols share for this class.



11. Review the log file once the Bulkload process is complete.

Lab 2: Piping Specification Validation


Objective

After completing this lab, you will be able to:

- Run the Verify Consistency between Piping Specification and Catalog tool
- Review and check for missing data in your piping specification

Database Verification/Consistency Checks

- 1. Open a session or create a new workspace and enter the Catalog task.
- 2. Select Tools -> Verify Consistency
- 3. The system displays the Verify Consistency between Piping Specification and Catalog form.
- 4. Select the "Piping materials classes" check box.
- 5. Select spec CC150-1 in the "Available piping material classes" picklist and select the "Add" option to move the spec into the Selected piping material classes" side of the form.
- 6. Enable the Verify symbol placement option. Define an output location for the logfile. (Note: the filename is automatically generated by the system).



- 7. Accept the form for processing by selecting the "OK" button.
- 8. You can rename the generated report ((Reportoutput.xls) filename to CC150report.xls
- 9. Review the system generated spreadsheet once processing is complete. Go to the index sheet and select the following links:
 - Rules data undefined
 - Piping commodity undefined in piping commodity material control data
 - Piping commodity undefined in piping commodity part data
 - Summary of catalog parts

Go to Rules data undefined report. Review the missing specification rules.




	: A le	Joil of the fules for	which data is underlined
Description Of The Error	Piping Materials Class	Revision Number	Rule Name
Rule data is missing	CC150-1	A	Field Fit Length rule
Rule data is missing	CC150-1	Α	Corrosion Allowance rule
Rule data is missing	CC150-1	Α	Service Limits rule
Rule data is missing	CC150-1	Α	Branch Intersection rule
Rule data is missing	CC150-1	Α	Permissible Taps rule
Rule data is missing	CC150-1	A	Minimum Pipe Length rule
Rule data is missing	CC150-1	A	Minimum Pipe Length rule for purchase length
WARNING : Optional rule data			
is missing	CC150-1	A	Default Change-of-Direction rule
WARNING : Optional rule data			
is missing	CC150-1	A	Joint Quality Factor rule
WARNING : Optional rule data			
is missing	CC150-1	A	Thickness Data rule
WARNING : Optional rule data			
is missing	CC150-1	A	Pipe Bending Elongation rule
WARNING : Optional rule data			
is missing	CC150-1	Α	Size Reduction rule
WARNING : Optional rule data			
is missing	CC150-1	Α	Inside Surface Treatment rule
WARNING : Optional rule data			
is missing	CC150-1	Α	Field Lining Thickness rule
WARNING : Optional rule data			
is missing	CC150-1	Α	Flared Pipe rule
WARNING : Optional rule data			
is missing	CC150-1	Α	Port Alignment rule
WARNING : Optional rule data			
is missing	CC150-1	Α	Weld Gap rule
WARNING : Optional rule data			
is missing	CC150-1	Α	Jacket Closure rule
WARNING : Optional rule data			
is missing	CC150-1	A	Swaged Jacket Pipe rule


Go to Piping commodity undefined in piping commodity material control data report. Note that tee commodity code is missing from the Piping Commodity Material Control Data sheet. This problem will be corrected in later labs.

	! Piping c	40 20 20	SmartPla			control data		
Description Of The Error	Piping Materials Class	Revision Number	Contractor Commodity Code	Primary Npd	Primary Npd Units	Secondary Npd	Secondary Npd Units	Multi-size Option
Piping commodity undefined in piping commodity material control data	CC150-1	A	Tee01	0		0		


Go to Piping commodity undefined in piping commodity part data report. Note that parts are missing from the part catalog. This problem will be corrected in later labs.



Go to Summary catalog parts report. This report displays a summary of the catalog parts required by your piping spec CC150-1




- 10. Go back to the Catalog Task and select Tools -> Run Reports
- 11. Select Catalog Reports Tab
- 12. Expand the report hierarchy and select Diagnostic folder.
- 13. Select Diagnostic Piping Commodity Specifications report



14. Select Run button and key in the spec name CC150-1

15. Hit Finish button to generate the report.



Modeling Verification

- 1. Enter the Systems and Specifications task.
- 2. Add the newly added spec to the plant hierarchy at any level you desire.
- 3. Enter the piping task.
- 4. Verify placement of spec components.

Note: Use the insert component command to **place the Tee** component on a straight pipe. System displays an error message. Note the error message indicating that the material control data of the component is not defined in the catalog.



5. Exit the model.

Lab 3: Piping Commodity Part Data

Objective

After completing this lab, you will be able to:

• Define piping components associated with a particular piping material class.

Reminder: The Piping Commodity Filter rule is intended to provide the data that is required to select unique piping commodity codes from the part catalog.

Editing Piping Commodity (Part) Data

1. Open the Ten_Specs_CatalogData.xls file located in <SP3DInstalled_Location>\
CatalogData\BulkLoad\DataFiles and save the following worksheets to a new workbook:

CustomInterfaces

GUIs


Tee

- 2. Open the Tee worksheet.
- 3. Add records for the new commodity code Tee01 as shown below:



- 4. Save the workbook as **Company_Catalog.xls**.
- 5. Open CC150-1.xls.
- 6. Open the Ten_Specs_SpecificationData.xls file located in <SP3DInstalled_Location>\ CatalogData\BulkLoad\DataFiles
- 7. Open the PipingCommodityMatlControlData worksheet
- 8. Save the sheet into the CC150-1.xls

9. Add the record for the new commodity code Tee01 as shown below:



- 10. Load the Company_Catalog.xls into the Catalog using the Add/Modify and Delete Mode.
- 11. Review the log file once the Bulkload process is complete.
- 12. Load the CC150-1.xls into the Catalog using the Add/Modify and Delete Mode.
- 13. Review the log file once the Bulkload process is complete.
- 14. Run the Verify Consistency between Piping Specification and Catalog command again.
- 15. Review the output report. Note that there is no entries in the *Piping commodity undefined in piping commodity material control data* and in the *Piping commodity undefined in piping commodity part data* reports.
- 16. Go to the Piping Task and place the Tee using the Insert component command.

Lab 4: Branch Insertion Rule

Objective

- After completing this lab, you will be able to create the branch insertion rule for the specified spec.
- 1. Open the Ten_Specs_SpecificationData.xls file located in <SP3DInstalled_Location>\ CatalogData\BulkLoad\DataFiles
- 2. Select PipeBranch worksheet. Move and copy this sheet into the CC150-1.xls in your working directory.
- 3. Add records to create the branch insertion rule for spec CC150-1 as shown below:

H	ea	de	-r

В	
r	
a	
n	
c	
c h	
	ĺ

	0.75	1	1.5	2	4	6	8	10	12	14	16	18	20	24
0.75	RW	RW	RW	S	S	S	S	S	S	S	S	S	S	S
1		RW	RW	S	S	S	S	S	S	S	S	S	S	S
1.5			RW	S	S	S	S	S	S	S	S	S	S	S
2				T	W	W	W	W	W	W	W	W	W	W
4					T	W	W	W	W	W	W	W	W	W
6						T	W	W	W	W	W	W	W	W
8							T	W	W	W	W	W	W	W
10								T	W	W	W	W	W	W
12									T	W	W	W	W	W
14										T	W	W	W	W
16											T	W	W	W
18												T	W	W
20													T	W
24														T

Head	SpecName	HeaderSize	BranchSize	AngleLow	AngleHigh	HdrSizeNPDUnitType	BrSizeNPDUnitType	ShortCode	SecondaryShortCode	
Start						-				
-	CC150-1	0.75		89.5deg	90.5deg	in	in	Reinforcing Weld	-	
	CC150-1	- 1		89.5deg	90.5deg	in	in	Reinforcing Weld		
	CC150-1	1		89.5deg	90.5deg	in	in	Reinforcing Weld		
-	CC150-1	1,5		89.5deg	90.5deg	in	in	Reinforcing Weld		
-	CC150-1	1.5		89.5deg	90.5deg	in	in	Reinforcing Weld	-	
	CC150-1	1.5		89.5deg	90.5deg	in	in	Reinforcing Weld	-	
-	CC150-1	2		89.5deg	90.5deg	in	in	Sockolet	-	
	CC150-1	4		89.5deg	90.5deg	in	in	Sockolet		
	CC150-1	6		89.5deg	90.5deg	in	in	Sockolet	-	
-	CC150-1	8		89.5deg	90.5deg	in	in	Sockolet		
-	CC150-1	10		89.5deg	90.5deg	in	in	Sockolet		
	CC150-1	12		89.5deg	90.5deg	in	in	Sockolet		
	CC150-1	14	25.77	89.5deg	90.5deg	in	in	Sockolet		
	CC150-1	16	75.5	89.5deg	90.5deg	in	in	Sockolet		
-	CC150-1	18		89.5deg	90.5deg	in	in	Sockolet		
	CC150-1	20		89.5deg	90.5deg	in	in	Sockolet		
	CC150-1	24		89.5deg	90.5deg	in	in	Sockolet	-	
-	CC150-1	2		89.5deg	90.5deg	in	in	Tee	-	
	CC150-1	4		89.5deg	90.5deg	in	in	Tee		
	CC150-1	6		89.5deg	90.5deg	in	in	Tee	-	
	CC150-1	8		89.5deg	90.5deg	in	in	Tee		
	CC150-1	10		89.5deg	90.5deg	in	in	Tee		
	CC150-1	12		89,5deg	90,5deg	in	in	Tee		
	CC150-1	14		89.5deg	90.5deg	in	in	Tee		
	CC150-1	16		89.5deg	90.5deg	in	in	Tee	-	
	CC150-1	18 20		89.5deg	90.5deg	in	in	Tee		
	CC150-1 CC150-1			89.5deg	90.5deg	in	in	Tee	-	
	CC150-1	24		89.5deg	90.5deg	in	in in	Tee		
	2000			89.5deg 89.5deg	90.5deg	in	10000	Weldolet	-	
	CC150-1	6 8			90.5deg	in	in	Weldolet		
	CC150-1 CC150-1	10		89.5deg 89.5deg	90.5deg 90.5deg	in	in in	Weldolet Weldolet	-	
	CC150-1	12		89.5deg	90.5deg	in	in	Weldolet	-	
	CC150-1	14		89.5deg	90.5deg	in	in	Weldolet		
	CC150-1	16		89.5deg	90.5deg	in	in	Weldolet	-	
-	CC150-1	18		89.5deg	90.5deg	in	in	Weldolet		
	CC150-1	20		89.5deg	90.5deg	in	in	Weldolet		
	CC150-1	24		89.5deg	90.5deg	in	in	Weldolet		

- 4. Run the Verify Consistency between Piping Specification and Catalog command.
- 5. Review the output report. Go to Branch fitting undefined in piping commodity filter report.

Note that all the branch fitting specified by the branch table is determined to be undefined in the piping commodity filter. Let add the missing components in the piping commodity filter.

	S	narti	Plant [®]				
! Branch fitting specified by				efined in the piping co	mmodity filter		
Description Of The Error	Piping Materials Class	Revision Number	Short Code	HeaderSize	Header Size NPD Unit Type	BranchSize	Branch Size
Branch fitting in pipebranch undefined in piping commodity filter	CC150-1	8-	Reinforcing Weld	0.75	in	0.75	in
Branch fitting in pipebranch undefined in piping	10000000000000000000000000000000000000			10000		1000000	
commodity filter Branch fitting in pipebranch undefined in piping	CC150-1		Reinforcing Weld	1	in	0.75	in
commodity filter Branch fitting in pipebranch undefined in piping	CC150-1		Reinforcing Weld	1	in	1	in
commodity filter	CC150-1		Reinforcing Weld	1.5	in	0.75	in
Branch fitting in pipebranch undefined in piping commodity filter	CC150-1		Reinforcing Weld	1.5	in	1	in
Branch fitting in pipebranch undefined in piping							
commodity filter Branch fitting in pipebranch undefined in piping	CC150-1		Reinforcing Weld	1.5	in	1.5	in
commodity filter	CC150-1		Sockolet	2	in	1.5	in
Branch fitting in pipebranch undefined in piping commodity filter	CC150-1		Sockolet	4	in	1.5	in
Branch fitting in pipebranch undefined in piping							
commodity filter Branch fitting in pipebranch undefined in piping	CC150-1		Weldolet	4	in	2	in
commodity filter	CC150-1		Sockolet	6	in	1.5	in
Branch fitting in pipebranch undefined in piping commodity filter	CC150-1		Weldolet	6	in	4	in
Branch fitting in pipebranch undefined in piping							Jan 2
commodity filter Branch fitting in pipebranch undefined in piping	CC150-1		Sockolet	8	in	1.5	in
commodity filter	CC150-1		Weldolet	8	in	6	in
Branch fitting in pipebranch undefined in piping commodity filter	CC150-1		Sockolet	10	in	1.5	in
Branch fitting in pipebranch undefined in piping	- SERVE 15		0.000000000		1901	1000	100
commodity filter Branch fitting in pipebranch undefined in piping	CC150-1		Weldolet	10	in	8	in
commodity filter	CC150-1		Sockolet	12	in	1.5	in
Branch fitting in pipebranch undefined in piping commodity filter	CC150-1		Weldolet	12	in	10	in
Branch fitting in pipebranch undefined in piping	CC130-1		yveidolet	12	(III)	10	111
commodity filter	CC150-1		Sockolet	14	in	1.5	in
Branch fitting in pipebranch undefined in piping commodity filter	CC150-1		Weldolet	14	in	12	in
Branch fitting in pipebranch undefined in piping	**************************************		Lower		J _e		Į.
commodity filter Branch fitting in pipebranch undefined in piping	CC150-1		Sockolet	16	in	1.5	in
commodity filter	CC150-1		Weldolet	16	in	14	in
Branch fitting in pipebranch undefined in piping commodity filter	CC150-1		Sockolet	18	in	1.5	in
Branch fitting in pipebranch undefined in piping	55000 5		533333170	100	1967	10000	
commodity filter Branch fitting in pipebranch undefined in piping	CC150-1		Weldolet	18	in	16	in
commodity filter	CC150-1		Sockolet	20	in	1.5	in
Branch fitting in pipebranch undefined in piping commodity filter	CC150-1		Weldolet	20	in	18	in
Branch fitting in pipebranch undefined in piping	Andrew Co.		A SECURITION OF THE SECURITION	1 2 2 2		1990	
commodity filter Branch fitting in pipebranch undefined in piping	CC150-1		Sockolet	24	in	1.5	in
commodity filter	CC150-1		Weldolet	24	in	20	in

- $6. \ \ Go\ to\ the\ Piping Commodity Filter\ work sheet.$
- 7. Add the record for the new commodities as shown below:

Item	Size	Commodity Code	Description
Sockolet	0.75" – 1.5"	MELAWDFZZAEYABQZZUM	Sockolet, SWE, 3000#, ASTM-A105
Weldolet	2"-20"	MEKZZBOZZAEYABQZZUM	Weldolet, [412], BE, CS, ASTM-A105 MSS SP-97
Reinforcing Weld	0.75"-1.5"		Reinforcing Weld CS, ASTM A53-B

ShortCode	OptionCode	FirstSizeFrom	FirstSizeTo	FirstSizeUnits	SecondSizeFrom	SecondSizeTo	SecondSizeUnits	MultisizeOption	Comments	SelectionBasis	JacketedPipingBasis	MaximumTemperature	MinimumTemperature	EngineeringTag	CommodityCode	FabricationCategoryOverride	SupplyResponsibilityOverride	FirstSizeSchedule	SecondSizeSchedule
Reinforcing Weld	1	1	15	in	0.75	0.75	in			25									
Reinforcing Weld	1	1.5		in	1	_	in			25									
Reinforcing Weld	1	0.75		in	<u> </u>		-			25									
Sockolet		2	24		0.75	1.5	-								MELAWDFZZAEYABQZZUM				

- 8. Save the CC150-1.xls
- 9. Load the information into the Catalog using the Add/Modify and Delete Mode.
- 10. Review the log file once the Bulkload process is complete.
- 11. Run the Verify Consistency between Piping Specification and Catalog command.
- 12. Review the output report. Go to the index sheet and select the following links:
 - Branch fitting undefined in piping commodity filter

Note that there is no entries in the *Branch fitting undefined in piping commodity filter* report.

- Piping commodity undefined in piping commodity material control data
- Piping commodity undefined in piping commodity part data

Note that there is no entries in both reports.

- Plain pipe end generic data undefined

Note that there are missing plain piping generic data for the sockolet component. The system is checking the generic data in all size combinations for a part (example: sockolet) that is referenced by the piping specification and not limiting the check to the sizes that are applicable to the component.

		martF								
Description of the error	Piping Materials Class	THE RESERVE OF THE PARTY OF THE	***	Industry Commodity Code	Short Material Description	Nominal Piping Diameter	Nominal Diameter Units	Schedule (Thickness)	End Standard	essure Ratin
Plain pipe end generic data undefined	CC150-1	A	MELAWDFZZAEYABQZZUM	MELAWDFZZAEYABQZZUI	N	2	în	Undefined	Default	1
Plain pipe end generic data undefined	CC150-1	A	MELAWDFZZAEYABQZZUM	MELAWDFZZAEYABQZZUI	V.	4	în	Undefined	Default	1
Plain pipe end generic data undefined	CC150-1	A	MELAWDFZZAEYABQZZUM	MELAWDFZZAEYABQZZUI	N	6	in	Undefined	Default	1
Plain pipe end generic data undefined	CC150-1	A	MELAWDFZZAEYABQZZUM	MELAWDFZZAEYABQZZUI	VI.	8	in	Undefined	Default	1
Plain pipe end generic data undefined	CC150-1	A	MELAWDFZZAEYABQZZUM	MELAWDFZZAEYABQZZUI	VI.	10	in	Undefined	Default	1
Plain pipe end generic data undefined	CC150-1	A	MELAWDFZZAEYABQZZUM	MELAWDFZZAEYABQZZUI	N	12	in	Undefined	Default	1
Plain pipe end generic data undefined	CC150-1	A	MELAWDFZZAEYABQZZUM	MELAWDFZZAEYABQZZUI	M	14	in	Undefined	Default	1
Plain pipe end generic data undefined	CC150-1	A	MELAWDFZZAEYABQZZUM	MELAWDFZZAEYABQZZUI	V	16	in	Undefined	Default	1
Plain pipe end generic data undefined	CC150-1	A	MELAWDFZZAEYABQZZUM	MELAWDFZZAEYABQZZUI	N	18	în	Undefined	Default	1
Plain pipe end generic data undefined	CC150-1	A	MELAWDFZZAEYABQZZUM	MELAWDFZZAEYABQZZUI	VI.	20	in	Undefined	Default	1
Digin nine and generic data undefined	CC150.1	Δ	MELAWDEZZAEVAROZZUM	MELAWDEZZAEVABOZZUI	A	24	in	Undofined	Dofault	1

13. Go to the Piping Task and test the branch insertion rule using Route Pipe command to route a 4" header line and a 2" branch line.

Lab 5: Bolted Components and Valve Operators

Objective


- After completing this lab, you will be able to add, delete or modify existing piping specifications.
- Use the automated flange selection logic to distinguish between flanges to be inserted on plain piping versus fitting-to-fitting situations.

Add records for flanges and valves in spec CC150-1 as shown below:

Item	Size	Commodity Code	Description
Flange at Fitting	2" -24"	FWN001	Flange, CL150, RFFE/BE, ASTM-A105, ANSI-B16.5, WN, [409]bore to match
Flange	2"-24"	FSO001	Flange CL150, RFFE,ASTM-A105, ANSI-B16.5, SO
Gate Valve	2"-12"	GAT001	Gate valve, CL300, RFFE, BB, OS&Y, ASTM-A216-WCB, trim 8, Crane 33

Adding Flanges

- 1. Open the Company_Catalog.xls
- 2. Open the WeldNeckFlange worksheet and edit as follows:



- 3. Make a copy of the WeldNeckFlange worksheet and rename it as SlipOnFlange.
- 4. Edit the SlipOnFlange sheet as follows:

Definition	PartClassType	SymbolDefinition	UserClassName	OccClassName	Symbolicon	OA:InsulationThickness
a	PipeComponentClass		Slip on Flange	Slip on Flange	Symbollcons\SP3DSliponFlange.gif	

Head	IndustryCommodityCode	FirstSizeSchedule	SecondSizeSchedule	CommodityType	GeometryType	GraphicalRepresentationOrNot	SymbolDefinition	MaterialGrade	LiningMaterial	PipingPointBasis[1]	ld[1]	PressureRating[1]	EndPreparation[1]	EndStandard[1]	ScheduleThickness[1]	FlowDirection[1]	PipingPointBasis[2]	ld[2]	PressureRating[2]	EndPreparation[2]	EndStandard[2]	ScheduleThickness[2]	FlowDirection[2]	PipingNote1	Npd[1]	NpdUnitType[1]	Npd[2] NpdUnitType[2]	FacetoFace	
Start																													
a	FSO001			FSO	15		SP3DSlipOnFlange.CSlipOnFlange	150	1	15		150	21	5		3	15			591	5		3		2		2 in	1in	
a								-	-	-														-	4		4 in	1.31in	
a								-	-	-	-													-	6		6 in	1.56in	
a								-	-	-	-													-	8		8 in	1.75in	
a						_		-	-	-	-													-	10		10 in	1.94in	
a						-		-		-	-												-	-	12		12 in	2.19in	
a					-	-		-	-	-	-												-	-	14		14 in	2.25in	
a																									16	ID	16 in	2.5in	
								-	_																				
a																									18	in	18 in	2.69in	
a a a																										in in			

- 5. Save the workbook.
- 6. Open the CC150-1.xls spreadsheet.
- 7. Open the PipingCommodityMatlControlData worksheet and add the following record:
 - The ContractorCommodityCode is FWN001.
 - The ShortMaterialDescription is Flange WN CL150 RFFE CS A105, ASME B16.5.
 - The ContractorCommodityCode is FSO001.
 - The ShortMaterialDescription is Flange CL150, RFFE, ASTM-A105, ANSI-B16.5, SO.

Note: Add the appropriate values in the Geometric Industry Standard, Fabrication Type, Supply Responsibility, Reporting Type, Gasket Requirement, Bolting Requirement, and Welding Requirement columns. (Hint: Check the AllCodeLists.xls spreadsheet for similar codelist items.)

	ContractorCommodityCode	'rom	٥	Units	SecondSizeFrom	SizeTo	SecondSizeUnits	MultisizeOption	IndustryCommodityCode	ClientCommodityCode	CIMISCommodityCode	ShortMaterialDescription	edShortMaterialDesc	LongMaterialDescription	GeometricIndustryStandard		Manufacturer	FabricationType	SupplyResponsibility	ReportingType	у	GasketRequirements	BoltingRequirements	WeldingRequirement
Head	Contracto	FirstSizeFrom	FirstSizeTo	FirstSizeUnits	Seconds	SecondSizeTo	Second	Multisiz	Industr	Cliento	CIMISC	ShortW	Localiz	LongN	Geome	Vendor	Manufa	Fabrica	Supply	Reporti	Quantity	Gasket	Bolting	Weldin
Head Start		FirstSizeF	FirstSize	FirstSize	Seconds	Second	Second	Multisiz	Industr	ClientC	CIMISC	ShortM	Locali	Long	Geome	Vendo	Manufa	Fabrica	Supply	Reporti	Quantit	Gasket	Bolting	Weldin
		FirstSizeF			Seconds	Second	Second	Multisiz	Industr	ClientC	CIMISC	Tee, [403], BE, ASTM-A234-WPB, ANSI-B16.9	Locali	Long	Geome	Vendo	Manufa	Labric ₂	Alddns 2		Quantit	Casket	Bolting 35	Weldin
		2			Seconds	Second	Second	Multisiz	Industr	ClientC	CIMISC				39		Manufa				Quantit			
Start	Tee01	2			Seconds	Second	Second	Multisiz	Industr	ClientC	CIMISC	Tee, [403], BE, ASTM-A234-VVPB, ANSI-B16.9	3.5, W		39		Manuf	15	2	5	Quantit	20	35	5

- 8. Save the workbook.
- 9. Load the information into the Catalog using the Add/Modify and Delete Mode.
- 10. Review the log file once the Bulkload process is complete.
- 11. Run the Verify Consistency between Piping Specification and Catalog command.
- 12. Review the output report. Go to the index sheet and select the following links:
 - Piping commodity undefined in piping commodity material control data
 - Piping commodity undefined in piping commodity part data
 - Summary of existing symbols
 - Summary of catalog parts

Adding Gate Valves


- 1. Open the Company_Catalog.xls workbook again.
- 2. Open the Gate Valve worksheet and edit as follows:

		Head Start a a a a a a Ence	GATO	Industry Commodity Code	FirstSizeSchedule	SecondSizeSchedule	GAT		Geometry Type		Sate∀a	lve.CG	SymbolDefinition	Symbolicon	Material Grade	LiningMaterial	BendRadius RendRadius Multinlier	MirrorBehaviorOption	PartDataBasis	ValveManufacturer	ValveModelNumber	ValveTrim	FlangeFaceSurfaceFinish	SurfacePreparation	ManufacturingMethod	MiscRequisitionClassification
PipingPointBasis[1]	14[1]	PressureRating[1]	EndPreparation[1]	EndStandard[1]		ScheduleThickness[1]	FlowDirection[1]	PipingPointBasis[2]	Id[2]	PressureRating[2]	EndPreparation[2]	EndStandard[2]	ScheduleThickness[2]	FlowDirection[2]	PipingNote1		+4±1000000000000000000000000000000000000		Npd[1]	NpdUnitType[1]		Npd[2]	NpdUnitType[2]		000000	racetorace
15		150	21	5			3	15		150	21	5		3		461	bm		2	in		2	in	7in		
										-						_	Olbm	-		in			in	9in		_
										-						_	olbm	\perp	6				in	10.		_
										-							Olbm	_	8				in	11.		_
										-						_	5lbm	\perp		in			in	13i		_
																650	Olbm		12	in		12	in	14i	n	

- 3. Save the workbook.
- 4. Open the CC150-1.xls workbook.
- 5. Open the PipingCommodityMatlControlData worksheet
 - The ContractorCommodityCode is GAT001.
 - The ShortMaterialDescription is Gate valve, CL150, RFFE, BB, OS&Y, ASTM-A216-WCB, trim 8, Crane 47
- 6. Note: Add the appropriate values in the Geometric Industry Standard, Fabrication Type, Supply Responsibility, Reporting Type, Gasket Requirement, Bolting Requirement, and

Welding Requirement columns of the part. (Hint: Check the AllCodeLists.xls spreadsheet for similar codelist items.)


7. Add the valve operator data for the Gate Valve.



8. Save the workbook.

Creating Piping Material Class Records.

- 1. Go to the PipingCommodityFilter worksheet.
- 2. Add records for the flanges and gate valve.



- 3. Save the file and exit.
- 4. Load the modified workbooks into the database using the Bulkload Utility.
- 5. Review the log file once the Bulkload process is complete. Run the Verify Consistency between Piping Specification and Catalog command.

- 6. Review the output report. Go to the index sheet and select the following links:
 - Piping commodity undefined in piping commodity material control data
 - Piping commodity undefined in piping commodity part data
 - Summary of existing symbols
 - Summary of catalog parts
 - Valve operator undefined in valve operator part data

! Valve			martPlan	
Description Of The Error	Piping Materials Class	Revision Number	Valve Operator Number	Contractor Commodity Code
Valve operator undefined in valve operator part data	CC150-1	A	GAT001-BLT-150-3	GAT001

Note: the system reports that the valve operator is not defined in the part catalog.

- Valve operator undefined in piping commodity material control data

! Valve op	erator is determined to		martPlant	
Description Of The Error	Piping Materials Class	Revision Number	Valve Operator Number	Contractor Commodity Code
Valve operator undefined in valve operator material control data	CC150-1	2	GAT001-BLT-150-3	GAT001

Note: the system reports that valve operator is not defined in the valve operator material control data

- PMCSymbolPlacement.xls

		Sm	artPlant									
Description Of The Error	Piping Materials Class	Revision Number	Industry Commodity Code	Short Code	Primary Size	Primary Size Units	Secondary Size	Secondary Size	Multi-size option	First Size Schedule	Second Size Schedule	Option Code
Placement of Symbol Failed. Please refer the log file	CC150-1	А	GAT001	Gate Valve	2	in						
Placement of Symbol Failed. Please refer the log file C:\Train\SymbolPlacementError Log.log	CC150-1	A	GAT001	Gate Valve	4	in						
Placement of Symbol Failed. Please refer the log file C:\Train\SymbolPlacementError Log.log		A	GAT001	Gate Valve	6	in						
Placement of Symbol Failed. Please refer the log file C:\Train\SymbolPlacementError Log.log		A	GAT001	Gate Valve		in						
Placement of Symbol Failed. Please refer the log file C:\Train\SymbolPlacementError Log.log		A	GAT001	Gate Valve	10							
Placement of Symbol Failed. Please refer the log file C:\Train\SymbolPlacementError Log.log	CC150-1	A	GAT001	Gate Valve	12	in						

Note: The system reports that the system fails to construct the gate valve GAT001 symbol for all sizes.

Adding valve operator data

- 7. Open the Company_Catalog.xls workbook again
- 8. Open the Operator3 worksheet
- 9. Add the valve operator data GAT001-BLT-150-3 as shown below:

Definition	PartClassType	SymbolDefinition	<u>Symbolicon</u>									
CommodityPart	ValveOperatorClass		Symbollcons\SP3DOP3.gif									
Head	ValveOperatorNumber	ValveSize	ValveSizeUnits	SymbolDefinition	MirrorBehaviorOption	ValveOperatorIsRotatable	DryWeight	DryCogX	DryCogY	DryCogZ	OperatorHeight	OperatorDiameter
Start												
a	GAT001-BLT-150-3	2	in	SP3DOP3.COP3		5					17.813in	10in
a		4	in								28.188in	13.75in
a		6	in								35.375in	15.5in
а											450	
-		8	in								45in	19.5in
a		10								_	45in 52.5in	19.5in 19.5in

- 10. Save the workbook.
- 11. Open CC150-1.xls.
- 12. Open the Ten_Specs_SpecificationData.xls file located in <SP3DInstalled_Location>\ CatalogData\BulkLoad\DataFiles
- 13. Open the ValveOperatorMatlControlData worksheet
- 14. Add the valve operator data GAT001-BLT-150-3 as shown below:

Head	OperatorPartNumber	ShortMatIDescription	LocalizedShortMaterialDescription	LongMaterialDescription	Vendor	Manufacturer	ValveOperatorType	ReportableCommodityCode	Quantity Of Reportable Parts	AltReportableCommodityCode	Quantity Of Alt Reportable Parts	HyperlinkToElectronicVendor	HyperlinkToElectronicManuals
Start GAT	001-BLT-150-3	Handwheel											

- 15. Save the sheet into the CC150-1.xls
- 16. Save the file and exit.
- 17. Load the modified workbooks into the database using the Bulkload Utility.
- 18. Review the log file once the Bulkload process is complete. Run the Verify Consistency between Piping Specification and Catalog command.

Review the output report. Go to the index sheet and select the following links:

- Piping commodity undefined in piping commodity material control data
- Piping commodity undefined in piping commodity part data
- Summary of existing symbols
- Summary of catalog parts
- Valve operator undefined in valve operator part data
- Valve operator undefined in piping commodity material control data
- PMCSymbolPlacement.xls


Lab 6: Connection Components

Objective

 After completing this lab, you will be able to define bolt and gasket data to an existing piping specification.

Creating Gasket Records.

- 1. Open the Ten_Specs_SpecificationData.xls file located in <SP3DInstalled_Location>\ CatalogData\BulkLoad\DataFiles
- 2. Select GasketSelection Filter and BoltSelectionFilter sheets. Move and copy these sheets into the CC150-1.xls
- 3. Go to the GasketSelectionFilter worksheet and add the following records:



Creating Bolt Records.

1. Go to the BoltSelectionFilter worksheet and add the following records:

l lead	SpecName	NominalDiameterFrom	NominalDiameterTo	NpdUnitType	BoltOption	MaximumTemperature	EndPreparation	PressureRating	EndStandard	AlternateEndPreparation	AlternatePressureRating	AlternateEndStandard	ContractorCommodityCode	Priority	BoltExtensionOption	FabricationCategoryOverride	SupplyResponsibilityOverride	Comments	PipingNote1
Head	3	۷	IZ.	Z_	Ш	N	3	п	3	ď	Í	1	כ	F	3	F	3)	_
Start		Z	Z	Z	<u> </u>	2	Ш	<u>п</u>	Ш	ď	-4	*	0	ш	ш		0)		
		2	24	in	1	2	ш 21	150	ш 5	4	~		BAZZZZZAAYBETZZUS	<u> </u>	1	7	10		
Start			24	in	1 1	2				121	150		_		1				

- 2. Save the file and load the CC150-1.xls using the Bulkload Utility. Review the log file.
- 3. Run the Verify Consistency between Piping Specification and Catalog command.
- 4. Review the output report. Go to the index sheet and select the following links:
 - Bolt for bolted joint undefined in bolt selection filter data
 - Bolts undefined in piping commodity material control data
 - Bolts undefined in bolt part data
 - Summary of bolt parts
 - Gasket for bolted joint undefined in gasket selection filter data
 - Gaskets undefined in piping commodity material control data
 - Gaskets undefined in gasket part data
 - Summary of gasket parts
- 5. Enter SmartPlant 3D and attempt to place a flange or flanged valve on the existing lines from the prior lab.

Lab7: PipeTakedown Parts Rule

Objective

- After completing this lab, you will be able to create the pipe takedown parts rule for the specified spec.
- 1. Open the Ten_Specs_SpecificationData.xls file located in <SP3DInstalled_Location>\ CatalogData\BulkLoad\DataFiles
- 2. Select PipeTakedownParts worksheet. Move and copy this sheet into the CC150-1.xls
- 3. Add records to create the pipe takedown parts rule for spec CC150-1 as shown below:
 - Place a Union when NPD is 0.75"
 - Place a Coupling when NPD is between 1" 1.75"
 - Place default flanges when NPD is between 2" 24"

Head	SpecName	TakeDownShortCode	WeldShortCode	IsPairRequired	Npd	NpdUnitType	IsWeld
Start							
а	CC150-1	Union	Butt Weld	0	0.75	in	1
а		Coupling	Butt Weld	0	1	in	1
а		Coupling	Butt Weld	0	1.5	in	1
a		Flange		1	2	in	1
а		Flange		1	4	in	1
а		Flange		1	6	in	1
а		Flange		1	8	in	1
а		Flange		1	10	in	1
а		Flange		1	12	in	1
а		Flange		1	14	in	1
а		Flange		1	16	in	1
а		Flange		1	18	in	1
а		Flange	Butt Weld	1	20	in	1
а		Flange	Butt Weld	1	24	in	1
End							

- 4. Go to the PipingCommodityFilter worksheet.
- 5. Add the record for the new commodities as shown below:

Item	Size	Commodity Code	Description
Union	0.75" – 0.75"	MAXAWBVZZADRABQZZUS	Union, CL3000, SWE, ASTM-A105, MSS-SP-83
Coupling	1" – 1.5"	MAKAWBVZZAAGABQZZUS	Coupling, CL3000, SWE, ASTM-A105, ANSI-B16.11



- 6. Save the sheet into the CC150-1.xls
- 7. Load the information into the Catalog using the Add/Modify and Delete Mode.
- 8. Review the log file once the Bulkload process is complete.
- 9. Run the Verify Consistency between Piping Specification and Catalog command.
- 10. Review the output report. Go to the index sheet and select the following links:
 - Piping commodity undefined in piping commodity material control data
 - Piping commodity undefined in piping commodity part data
 - Summary of existing symbols
 - Summary of catalog parts
- 11. Go to the Piping Task and test the pipe takedown parts rule.

Lab 8: Permissible Taps Rule

Objective

- After completing this lab, you will be able to create the permissible taps rule for the specified spec.
- 1. Open the Ten_Specs_SpecificationData.xls file located in <SP3DInstalled_Location>\ CatalogData\BulkLoad\DataFiles
- 2. Select PermissibleTaps worksheet. Move and copy this sheet into the CC150-1.xls
- 3. Add records to create the permissible taps rule for spec CC150-1 as shown below:
 - Set the default tap for a 1" NPD
 - Place a 3000# socket weld tap when NPD is between 0.75" 4"
 - Place a hole circular end tap when NPD is between 4" 24"

Head	SpecName	PermissibleTapNumber	IsPreferredTap
Start	004504	T 004	E 41 0E
<u> </u>	CC150-1	Tap-004	FALSE
A		Tap-006	TRUE
A		Tap-010	FALSE
A		Tap-012	FALSE
<u>A</u>		Tap-018	FALSE
A		Tap-021	FALSE
A		Tap-022	FALSE
А		Tap-023	FALSE
A		Tap-024	FALSE
A A A A A A A A A A A A A A A A A A A		Tap-025	
Α		Тар-026	FALSE
Α		Tap-027	FALSE
Α		Тар-028	FALSE
		Tap-029	FALSE
End			

Note: The Permissible TapNumbers are defined in TapProperties rule.

- 4. Save the sheet into the CC150-1.xls
- 5. Load the information into the Catalog using the Add/Modify and Delete Mode.
- 6. Review the log file once the Bulkload process is complete.

- 7. Run the Verify Consistency between Piping Specification and Catalog command.
- 8. Review the output report. Go to the index sheet and select the following link:
 - Rules data undefined
 - Tap undefined in tap properties data
- 9. Go to the Piping Task and test the permissible taps rule.

Lab 9: Model/Catalog Synchronization

Objective


• After completing this lab, you will be able to modify the piping specification/catalog and synchronize the catalog with the model data.

Component Modeling

- 1. Route items in the model that include the following items:
- 2. Large bore pipe and fittings (NPD = 4")
- 3. Small Bore pipe and fittings (NPD = 2")
- 4. At least one flanged component
- 5. At least three standard tees on the 2" pipeline: at the end of a pipe, somewhere along the pipe and between two fittings.

Modification of Specification Fabrication Category Data

- 1. Exit SP3D and open the CC150-1.xls workbook.
- 2. Open the PipingCommodityMatlControlData worksheet
- 3. Make the 2" Tee field fabricated for this spec as follows:



Note: Delete the existing Tee01 row first because the sizes are attributes that make the row unique.

4. Save the spreadsheet.

- 5. Open the Company_Catalog.xls
- 6. Open the Tee worksheet and edit the FacetoCenter dimension for the 2" Tee as follows:

FacetoCenter = 6in

Head Start		FirstSizeSchedule	SecondSizeSchedule	CommodityType	GeometryType	GraphicalRepresentationOrNot	SymbolDefinition	MaterialGrade	LiningMaterial	PipingPointBasis[1]	ld[1]	PressureRating[1]	EndPreparation[1]	EndStandard[1]	ScheduleThickness[1]	FlowDirection[1]	PipingPointBasis[2]	ld[2]	PressureRating[2]	EndPreparation[2]	EndStandard[2]	ScheduleThickness[2]	FlowDirection[2]	PipingPointBasis[3]	ld[3]	PressureRating[3]	EndPreparation[3]	EndStandard[3]	ScheduleThickness[3]	FlowDirection[3]	PipingNote1	DryWeight	Npd[1]:Primary	NpdUnitType[1]	Npd[z]:Primary NpdUnitType[z]	Npd[3]:Secondary	NpdUnit1ype[3]	FacetoCenter
m	Tee01	S-STD	S-STD	т	75		SP3DTee.CEqualTee	264		15			301	5	S-STD	3	15			301	5	S-STD	3	15		-	301	5	S-STD	3		3lbm	2 i	n	2 in	2 in		iin
m	10001	0.010	0.010	Ť	,,,		or objectorquaries	204					501		0.010		10			501		0 010							0.010			13lbm	4 i		4 in	4 in		.125in
m																																29lbm	6 i		6 in	6 in		.625in
m																																54lbm	8 i	n	8 in	8 in	1 7	in
m																																88lbm	10 i	n	10 in	10 in	1 8	.5in
m																																128lbm	12 i	n	12 in	12 in	1 1	0in
m																																176lbm	14 i	n	14 in	14 in		1in
m																																200lbm	16 i		16 in	16 in		2in
m				-																												318lbm	18 i		18 in	18 in		3.5in
m				-					-								-		-											-		369lbm	20 i		20 in	20 in		5in
m End																																560lbm	24 i	n	24 in	24 in	1	7in

7. Load the changes into the database using the Bulkload Utility. Review the log file.

Note: Make sure to mark modified all rows in the spreadsheet with an "M", and use the "Add, Modify, or Delete" Bulkload option.

- 8. Open Project Management Tool
- 9. Select the Model and go to Tool -> Synchronize Model with Catalog command. <u>Do not need to re-generate the views</u> in the model.
- 10. Select OK to start the process.
- 11. Enter SmartPlant 3D and go to Piping task. Use F5 to update graphics if using a session file to enter the model.
- 12. Review the TO DO LIST dialog box.
- 13. Hit the Update button in the TO DO LIST to update any out of date entries in the list.

Lab 10: Reportable Piping Commodity

Objective


- After completing this lab, you will be able to add a lap joint flange represents the primary piping commodity, and the stub end represents the reportable piping commodity for reporting purposes. It is not necessary that the stub end be modeled.
- 1. Add records for lap joint flange in spec CC150-1 as shown below:

Item	Option	Size	Commodity Code	Description
Flange	189	4" -8"	FLSL-01	Flange, CL150, RFFE/BE, ASTM-A105, ANSI-B16.5, FLSL
		4"-8"	StubEnd-01	Stub End, ANSI-B16.9, bevel end, Schedule bore to match

- 2. Open the Company_Catalog.xls
- 3. Edit the LapJointFlange sheet as follows:


Head		FirstSizeSchedule	SecondSizeSchedule	CommodityType	GeometryType	GraphicalRepresentatio	SymbolDefinition	MaterialGrade	LiningMaterial	PipingPointBasis[1]	ld[1]	PressureRating[1]	EndPreparation[1]	EndStandard[1]	ScheduleThickness[1]	FlowDirection[1]	PipingPointBasis[2]	[d[2]	PressureRating[2]	EndPreparation[2]	EndStandard[2]	ScheduleThickness[2]	FlowDirection[2]	PipingNote1	Npd[1]	NpdUnitType[1]	Npd[2]	NpdUnitType[2]	StubLength	LapThickness
Start	ti																													
o.u.																										2 1				
	FLSL-01		S-STD	FSSE	15			150		15		150	71	5		3	15			301	5	S-STD	3		4	in	4	in	6in	0.169in
			S-STD	FSSE	15			150		15		150	71	5		3	15			301	5	S-STD	3			in in	4 6		6in 8in	0.169in 0.194in

- 4. Go to StubEnd sheet.
- 5. Edit the StubEnd sheet as follows:



- 6. Save the file and exit.
- 7. Open the CC150-1.xls spreadsheet.
- 8. Open the PipingCommodityMatlControlData worksheet
 - The ContractorCommodityCode is FLSL-01.
 - The ShortMaterialDescription is Flange, CL150, RFFE/BE, ASTM-A105, ANSI-B16.5, FLSL
 - The ContractorCommodityCode is StubEnd-01.
 - The ShortMaterialDescription is Stub End, ANSI-B16.9, bevel end, Schedule bore to match

Note: Add the appropriate values in the Geometric Industry Standard, Fabrication Type, Supply Responsibility, Reporting Type, Gasket Requirement, Bolting Requirement, and Welding Requirement columns of the part. (Hint: Check the AllCodeLists.xls spreadsheet for similar codelist items.)



Creating Piping Material Class Record

- 9. Open the PipingCommodityFilter worksheet.
- 10. Add records for the lap joint flange and the Stub End.

Head	SpecName	ShortCode	OptionCode	FirstSizeFrom	FirstSizeTo	FirstSizeUnits	SecondSizeFrom	SecondSizeTo	SecondSizeUnits	MultisizeOption	Comments	SelectionBasis	CommodityCode	FabricationCategoryOverride	SupplyResponsibilityOverride	FirstSizeSchedule	SecondSizeSchedule	ReportableCommodityCode	QuantityOfReportableParts
Start																			
a		Flange	189	4	8	in						5	FLSL-01				MATCH	StubEnd-01	1

- 11. Save the file and load both workbooks using the Bulkload Utility.
- 12. Review the log file once the Bulkload process is complete.
- 13. Run the Verify Consistency between Piping Specification and Catalog command again.
- 14. Review the output report. Go to the index sheet and select the following links:
 - Piping commodity undefined in piping commodity material control data
 - Piping commodity undefined in piping commodity part data
 - Summary of existing symbols
 - Summary of catalog parts
 - Bolt for bolted joint undefined in bolt selection filter data
 - Bolts undefined in piping commodity material control data
 - Bolts undefined in bolt part data
 - Summary of bolt parts
 - Gasket for bolted joint undefined in gasket selection filter data
 - Gaskets undefined in piping commodity material control data
 - Gaskets undefined in gasket part data
 - Summary of gasket parts

Note: the report shows missing bolts and gaskets.

Creating Gasket Records.

15. Open the GasketSelectionFilter worksheet and add the following records:

Head	SpecName	NominalDiameterFrom	NominalDiameterTo	NpdUnitType	GasketOption	MaximumTemperature	EndPreparation	PressureRating	EndStandard	AlternateEndPreparation	AlternatePressureRating	AlternateEndStandard	FluidCode	ScheduleThickness	ContractorCommodityCode	Priority	RingNumber	FabricationCategoryOverride	SupplyResponsibility0verride
Start a	CC150-1	4		in	1		71	150	5						GMAHACABXBEPUS			7	10


Creating Bolt Records.

16. Open the BoltSelectionFilter worksheet and add the following records:

Head	SpecName	NominalDiameterFrom	NominalDiameterTo	NpdUnitType	BoltOption	MaximumTemperature	EndPreparation	PressureRating	EndStandard	AlternateEndPreparation	AlternatePressureRating	AlternateEndStandard	ContractorCommodityCode	Priority	BoltExtensionOption	FabricationCategoryOverride	SupplyResponsibilityOverride	Comments	PipingNote1
Start																			
a	CC150-1	4	8	in	1		71	150	5				BAZZZZZZAAYBETZZUS		1	7	10		
a	CC150-1	4	8	in	1		21	150	5	71	150	5	BAZZZZZZAAYBETZZUS		1	7	10		

- 17. Save the file and load both workbooks using the Bulkload Utility.
- 18. Review the log file once the Bulkload process is complete.
- 19. Run the Verify Consistency between Piping Specification and Catalog command again.

- 20. Review the output report.
- 21. Go to the Piping Task and place the lap joint flange.
- 22. Review the properties page.



Lab 11: Substitution Cap Screw Commodity Code

Objective

- After completing this lab, you will be able to add a lug-type wafer butterfly valve, where the valve body has threaded holes that are drilled to a manufacturer-specific depth for cap screws.
- 1. Add records for lug-type wafer butterfly valve in spec CC150-1 as shown below:

Item	Size	Commodity Code	Cap Screws	Description
Butterfly Valve	4" –8"	BFYHP-01	4 Partial cap screw substitution for threaded	Butterfly valve, CL150, RFTBE, Standard Lugged Pattern, ASTM-A216-WCB
			holes	

- 2. Open the Company_Catalog.xls
- 3. Go to ButterflyValve sheet.
- 4. Edit the ButterflyValve sheet as follows:

Head	IndustryCommodityCode	FirstSizeSchedule	SecondSizeSchedule	CommodityType	GeometryType	GraphicalRepresentationOrNot	SymbolDefinition	MaterialGrade	LiningMaterial	
Start										
a	BFYHP-01			BFYHP	15		SP3DButterflyValveSym.CButterflyValveS			

	sMultiplier	iorOption	acturer	Number		FlangeFaceSurfaceFinish	aration	ingMethod	itionClassification	:Basis[1]		ting[1]	tion[1]	d[1]	ickness[1]	n[1]	Basis[2]		ing[2]	tion[2]	d[2]	ickness[2]	on[2]				e[1]		·e[2]	
BendRadius	BendRadiusMultiplier	MirrorBehaviorOption	ValveManufacturer	ValveModelNumber	ValveTrim	FlangeFace	SurfacePreparation	ManufacturingMethod	MiscRequisitionCla	PipingPointBasis[1]	ld[1]	PressureRating[1]	EndPreparation[1]	EndStandard[1]	ScheduleThickness[1]	FlowDirection[1]	PipingPointBasis[2]	ld[2]	PressureRating[2]	EndPreparation[2]	EndStandard[2]	ScheduleThickness[2]	FlowDirection[2]	PipingNote1	DryWeight	Npd[1]	NpdUnitTyp	Npd[2]	NpdUnitType[2]	FacetoFace
BendRadius	BendRadius	MirrorBehav	ValveManuf	ValveModel 620	© ValveTrim	FlangeFace	SurfacePrep	Manufacturi	MiscRequis	PipingPoint	ld[1]			_⊆ EndStandar		FlowDirection		ld[2]		EndPrepara	_⊆ EndStandar		FlowDirection	PipingNote1	31llom Dry Weight		∋ NpdUnitTyp		NpdUnitTyp	EacetoFace
BendRadius	BendRadius	MirrorBehav	ValveManuf			FlangeFace	SurfacePrep	Manufacturi			ld[1]							[d[2]						PipingNote1		4		4		

- 5. Save the file and exit.
- 6. Open the CC150-1.xls spreadsheet.
- 7. Open the PipingCommodityMatlControlData worksheet
 - The Contractor Commodity Code is BFYHP-01.
 - The ShortMaterialDescription is Butterfly valve, CL150, RFTBE, Standard Lugged Pattern, ASTM-A216-WCB

Note: Add the appropriate values in the Geometric Industry Standard, Fabrication Type, Supply Responsibility, Reporting Type, Gasket Requirement, Bolting Requirement, and Welding Requirement columns of the part. (Hint: Check the AllCodeLists.xls spreadsheet for similar codelist items.)

Head	ContractorCommodityCode	FirstSizeFrom	FirstSizeTo	FirstSizeUnits	SecondSizeFrom	SecondSizeTo	SecondSizeUnits	MultisizeOption	Industry Commodity Code	ClientCommodityCode	CIMISCommodityCode	ShortMaterialDescription	LocalizedShortMaterialDesc	GeometricIndustryStandard	Vendor	Manufacturer	FabricationType	SupplyResponsibility	ReportingType	QuantityOfReportableParts	GasketRequirements	BoltingRequirements	WeldingRequirement
Start																							
a	BFYHP-01	4	8	in								Butterfly valve, CL150, RFTBE, Standard Lugged Pattern, ASTM-A216-WCB		4200			7	10	5		5	20	50


8. Add the valve operator data and the cap screws for the butterfly valve.

SubstCapScrewsQuantity	SubstCapScrewCntrCommodityCode	SubstCapScrewDiameter	TappedHoleDepth	MultiportYalveOpReq	ValveOperatorType	ValveOperatorGeoIndStd	ValveOperatorCatalogPartNumber
4	BCZZZZZZAAYBETZZUS				17	2035	BFYHP-Bolted-150-17

9. Save the spreadsheet.

Creating Piping Material Class Records.

- 10. Open the PipingCommodityFilter worksheet.
- 11. Add records for the butterfly valve.



Creating Gasket Records.

12. Open the GasketSelectionFilter worksheet and add the following records:

SpecName	NominalDiameterFrom	NominalDiameterTo	NpdUnitType	GasketOption	MaximumTemperature	EndPreparation	PressureRating	EndStandard	AlternateEndPreparation	AlternatePressureRating	AlternateEndStandard	FluidCode	ScheduleThickness	ContractorCommodityCode	Priority	RingNumber	FabricationCategoryOverride	SupplyResponsibilityOverride
CC150-1	4	8	in	1		21	150	5	211	150	5			GMAHACABXBEPUS			7	10


Creating Bolt Records.

13. Open the BoltSelectionFilter worksheet and add the following records:

SpecName	NominalDiameterFrom	NominalDiameterTo	NpdUnitType	BoltOption	MaximumTemperature	EndPreparation	PressureRating	EndStandard	AlternateEndPreparation	AlternatePressureRating	AlternateEndStandard	ContractorCommodityCode	Priority	BoltExtensionOption	FabricationCategoryOverride	SupplyResponsibilityOverride
CC150-1	4	8	in	1		21	150	5	211	150	5	BAZZZZZAAYBETZZUS	S	1	7	10

- 14. Save the file and load both workbooks using the Bulkload Utility.
- 15. Review the log file once the Bulkload process is complete.
- 16. Run the Verify Consistency between Piping Specification and Catalog command.
- 17. Review the output report. Go to the index sheet and select the following links:
 - Piping commodity undefined in piping commodity material control data
 - Piping commodity undefined in piping commodity part data

- Summary of existing symbols
- Summary of catalog parts
- Bolt for bolted joint undefined in bolt selection filter data
- Bolts undefined in piping commodity material control data
- Bolts undefined in bolt part data
- Summary of bolt parts
- Gasket for bolted joint undefined in gasket selection filter data
- Gaskets undefined in piping commodity material control data
- Gaskets undefined in gasket part data
- Summary of gasket parts
- 18. Go to the Piping Task and place the butterfly valve.
- 19. Review the properties page. "Go To" the bolts properties and verify cap screws.



Lab 11: Substitution Cap Screw Commodity C	Code

Lab 12: Custom Engineered/Stock Instruments

Objective:

After completing this lab, you will be able to:

• Add/Modify Custom Engineered/Stock Instrument.

Create a stock flowmeter (part number: Flow-001) with a tag number F-001. Stock items represent those piping items that are purchased from a manufacturer's catalog, where no real engineering is required other than selecting the correct size, material, etc.

Create a custom-engineered item Flow Meter called F-002. Both flowmeters will use the symbol called SP3DCoriolisFlowMeterTy1.CCFMeterTy1. The symbol can be found in [Install Product]\Programming\ExampleCode\Symbols\Piping

- 1. Open the Instrument Data.xls Excel Workbook.
- 2. Copy the worksheet ANG as FlowMeter1

∑FlowMeter1 GUIDs /

- 3. Locate printable document <u>SmartPlant 3D Symbols Reference Data Guide</u> (or open the symbol program) and find out the inputs required to construct the symbol SP3DCoriolisFlowMeterTy1.
- 4. Define all inputs that create the body of the instrument as **occurrence attributes** (oa). The part definition for this instrument will look as follows:

Definition	PartClassType	SymbolDefinition	UserClassName	Occ ClassName	Symbolicon	OA:FacetoFace	OA:FlowDiameter	OA:InstrumentHeight	OA:InstrumentDiameter	OA:InstrumentWidth	A:InstrumentWid	OA:InsulationThickness
a	InstrumentsClass	SP3DCoriolisFlowMeterTy1.CCFMeterTy1	Flowmeter 1 lab	Flowmeter 1 lab	Symbolicons\FlowMeter.gif							

5. Add the two instruments with the following data:

Make sure the Geometry Type is 15 (Linear, full size)

and Commodity Type is 5413 (Flow Controller).

Material Grade: 150

Make sure to delete any attributes used by the Control Gate Valve

Flowmeter 1:

Industry Commodity Code: Flow-001

Port data:

NPD: 4 in

Rating: 150 EndPrep: 21 End Standard: 5 Flow Direction: 3

FacetoFace: 12 in FlowDiameter: 5 in InstrumentHeight: 18 in InstrumentDiameter: 4 in InstrumentWidth: 6 in InstrumentWidth1: 8 in

Flowmeter 2:

Industry Commodity Code: F-002

Port data:

NPD: 4 in

Rating: 150 EndPrep: 21 End Standard: 5

FacetoFace: 12 in FlowDiameter: 5 in InstrumentHeight: 24 in InstrumentDiameter: 4 in InstrumentWidth: 6 in InstrumentWidth1: 8 in

Make sure you add the Requisition Type attribute.

_Head	IndustryCommodityCode	FirstSizeSchedule	SecondSizeSchedule	CommodityType	GeometryType	GraphicalRepresentationOrNot	SymbolDefinition	MaterialGrade	LiningMaterial	RequisitionType	BendAngle	BendRadius	BendRadiusMultiplier	PipingPointBasis[1]	14[1]	PressureRating[1]	EndPreparation[1]	EndStandard[1]	ScheduleThickness[1]	FlowDirection[1]	PipingPointBasis[2]	ld[2]	PressureRating[2]	EndPreparation[2]	EndStandard[2]	ScheduleThickness[2]	FlowDirection[2]	DryWeight	Npd[1]	NpdUnitType[1]	Npd[2]	NpdUnitType[2]	FacetoFace	FlowDiameter	InstrumentHeight	InstrumentDiameter	InstrumentWidth	InstrumentWidth1
Start																																						
a	Flow-001			5413	15			150		5	i					150	21	5		3			150	21	5		3		4	in	4	in	12in	5in	18in	4in	6in	8in
a	F-002			5413	15			150		10	1					150	21	5		3			150	21	5		3		4	in	4	in	12in	5in	24in	4in	6in	8in

6. Go to the InstrumentClassData sheet and add the following data:

Head	TagNumber	GenericTagNumber	SpecName	FirstSizeFrom	FirstSizeTo	FirstSizeUnits	SecondSizeFrom	SecondSizeTo	SecondSizeUnits	MultiSizeOption	RequisitionType	ContractorCommodityCode	InstrumentType	GeometryType	FirstSizeSchedule	SecondSizeSchedule	IsGraphicalRepresentation	MaximumTemperature	MaterialGrade	LiningMaterial	CorrosionAllowance	ShortMaterialDescription	LocalizedShortMaterialDesc	LongMaterialDescription	GeometricIndustry Standard	Vendor	Manufacturer	FabricationType	SupplyResponsibility	ReportingType		BoltingRequirements	WeldingRequirement
Start																																	
a	F-001			4	4	in					- 5	Flow-001	5413	15																			
a		F-002									10		5413	15								Custom Instr						7	2	- 5	- 5	5	50
End																																	

7. Go to the Piping Commodity Material Control Data sheet and add the following data for the stock instrument.

Head	ContractorCommodityCode	FirstSizeFrom	FirstSizeTo	FirstSizeUnits	ShortMaterialDescription	LocalizedShortMaterialDesc	GeometricIndustryStandard	Vendor	Manufacturer	FabricationType	SupplyResponsibility	ReportingType	Quantity	GasketRequirements	BoltingRequirements	WeldingRequirement
Start																
	Flow-001				Stock instr					7				5	5	50
End																

- 8. Create the FlowMeter.gif file and place it under \\<MachineName>\Symbols\SymbolIcons. (Remember this file may need to be copied to all workstations back at the office). You can use the picture for SP3DCoriolisFlowMeterTy1 in the SmartPlant 3D Symbols Reference
 Data Guide printable guide for illustration details.
- 9. Save the changes to Instrument Data.xls and use the Bulkload Utility to load the new class. Remember to add the letter A to all new rows in all sheets modified.

For faster processing, copy the worksheets that were modified above to a separate workbook: Instrument.xls. The system will require at least the following worksheets for this and next lab:

- a. FlowMeter1
- b. PipingCommodityMaterialControlData
- c. InstrumentClassData
- d. CustomInterfaces
- e. R-ClassNodeDescribes
- f. GUIDs
- 10. Once the bulkload process is complete, review the log file. If no errors, run the View Generator utility on the model to re-create the views in the model database ([Install Product]\Core\Tools\Administrator\Bin\ViewGenerator.exe).
- 11. Re-generate the report databases.
- 12. Run the Verify Consistency between Piping Specification and Catalog command.
- 13. Review the output report.
- 14. Go to the Piping Task and place both instruments.

Lab 13: Instrument "On the Fly"

Objective

After completing this lab, you will be able to:

• Add an Instrument "On the fly"

Create a Custom-engineered flow controller called F-101.

This flow controller will use the symbol called SP3DCICoriolisFlowMeterTy1.CCICFMetTy1.

The symbol can be found in [Install Product]\Programming\ExampleCode\Symbols\Piping

- 1. Open the Instrument Data.xls Excel Workbook.
- 2. Select IA1 sheet, copy it as FlowController into the Instrument.xls workbook from the previous lab.
- 3. Open the <u>SmartPlant 3D Symbols Reference Data Guide</u> printable guide and find out the inputs required to construct the symbol SP3DCICoriolisFlowMeterTy1.
- 4. Define all inputs that create the body of the instrument as occurrence attributes.
- 5. The Part definition for this instrument will look as follows:

Definition	PartClassType	SymbolDefinition	Symbolicon
a	instrumentsClass	SP3DClCoriolisFlowMeterTy1.CClCFMetTy1	Symbolicons\FlowController.gif

The occurrence attributes are:

oa:FacetoFace
oa:FlowDiameter
oa:InstrumentHeight
oa:InstrumentDiameter
oa:InstrumentWidth
oa:InstrumentWidth1
oa:InsulationThickness
OA:Npd
OA:NpdUnitType
OA:EndPreparation
OA:ScheduleThickness
OA:EndStandard
OA: PressureRating
OA:FlowDirection
OA:Id1
OA:PortIndex1
OA:Npd1
OA:NpdUnitType1
OA:EndPreparation1
OA:ScheduleThickness1
OA:EndStandard1
OA:PressureRating1
OA:FlowDirection1
OA:Id2
OA:Portindex1
OA:Npd2
OA:NpdUnitType2
OA:EndPreparation2
OA:ScheduleThickness2
OA:EndStandard2
OA:PressureRating2
OA:FlowDirection2

7. Add the part with the following data:

CommodityPart	ode	edule	chedule	уре	90	GraphicalRepresentationOrNot	ition	o o	al			Multiplier									apacity	lasis[1]		reRating[1]	on[1]	ard[1]	ckness[1]	n[1]			ype[1]
Head	IndustryCommodityC	FirstSizeSchedule	SecondSizeS	CommodityTyp	GeometryType	GraphicalF	SymbolDefinition	MaterialGrade	LiningMaterial	BendAngle	BendRadius	BendRadiusMultiplier	DryCogX	DryCogY	DryCogZ	WaterWeight	WaterCogX	WaterCogY	WaterCogZ	SurfaceAre	VolumetricC	PipingPointB	ld[1]	PressureR	EndPreparati	EndStand2	ScheduleThickn	FlowDirecti	DryWeight	Npd[1]	NpdUnitTy
Start																															
	F-101				15																									4	in
End																															

- 8. Open the Instrument Data.xls Excel Workbook.
- 9. Select R-ClassNodeDescribes sheet and save it to the Instrument.xls (if not already done in Lab 12).
- 10. Go to the R-ClassNodeDescribes sheet in Instrument.xls and add the following data:

RelationSource	RelationDestination
Custominstruments	FlowController


- 11. Create the FlowController.gif file and place it under \\<MachineName>\Symbols\SymbolIcons. A figure to go by of the symbol SP3DCICoriolisFlowMeterTy1 can be found in the Symbols Reference Data Guide printable guide.
- 12. Load the information into the Catalog using the Append Mode.
- 13. Run the View Generator utility on the model to re-create the views in the model database.
- 14. Re-generate the report databases.
- 15. Run the Verify Consistency between Piping Specification and Catalog command.
- 16. Review the output report.
- 17. Go to the Piping Task and place the F-101 instrument "on the fly".

Lab 14: Piping Commodity Procurement Data

Objective

After completing this lab, you will be able to:


- Use the Piping Commodity Procurement Data to determine the Size-Dependent Client Commodity Code on the basis of the Contractor Commodity Code from the piping commodity filter
- 1. Open the Ten_Specs_SpecificationData.xls workbook located in <SP3DInstalled_Location>\ CatalogData\BulkLoad\DataFiles.
- 2. Go to the DefaultProjectOptions sheet.
- 3. Save the sheet into the CC150-1.xls
- 4. Change the PipingCmdtyProcurementDataOpt option to 10.
- 5. Save the workbook.



- 7. Go to the PipingCommodityProcurementData sheet and add the following records:

Head	CommodityCode	FirstSize	FirstSizeUnits	SecondSize	SecondSizeUnits	MultisizeOption	FirstSizeSchedule	SecondSizeSchedule	ClientCommodityCode	CIMISCommodityCode	VendorPartNumber	ManufacturerPartNumber	UnitCost	RequisitionNumber	InstallationManHours	MaintenanceManHours
Start		-	-	0,	0,	_		0,		_	_	_	_	ш.	_	
	FS0001	2	in	2	in				FSACC2							
	FS0001	4	in	4	in				FSACC4							
a	FS0001	6	in	6	in				FSACC6							
a	FS0001	8	in	8	in				FSACC8							
a	FS0001	10	in	10	in				FSACC10							
a	FS0001	12	in	12	in				FSACC12							
а	FS0001	14	in	14	in				FSACC14							
a	FS0001	16	in	16	in				FSACC16							
a	FS0001	18	in	18	in				FSACC18							
a	FS0001	20	in	20	in				FSACC20							
a	FS0001	24	in	24	in				FSACC24							
a	FWN001	2	in	2	in			S-STD	FWSACC2							
a	FWN001	4	in	4	in			S-STD	FWSACC4							
a	FWN001	6	in	6	in			S-STD	FWSACC6							
a	FWN001	8	in	8	in			S-STD	FWSACC8							
a	FWN001	10	in	10	in			S-STD	FWSACC10							
a	FWN001	12	in	12	in			S-STD	FWSACC12							
a	FWN001	14	in	14	in			S-STD	FWSACC14							
a	FWN001	16	in	16	in			S-STD	FWSACC16							
a	FWN001	18	in	18	in			S-STD	FWSACC18							
a	FWN001	20	in	20	in			S-STD	FWSACC20							
a	FWN001	24	in	24	in			S-STD	FWSACC24							
a	GAT001	2	in	2	in				GTSACC2							
a	GAT001	4	in	4	in				GTSACC4							
a	GAT001	6	in	6	in				GTSACC6							
a	GAT001	8	in	8	in				GTSACC8							
a	GAT001	10	in	10	in				GTSACC10							
a	GAT001	12	in	12	in				GTSACC12							
End																

- 8. Save the sheet into the CC150-1.xls
- 9. Load the information into the Catalog using the Add/Modify/Delete Mode.
- 10. Open your session and go to the Piping Task.
- 11. Select the weld neck flange and open the properties page. Verify the client commodity code is displayed in the properties page.



Lab 15: Create/Modify Spec in Catalog Task (Optional)

Objective

After completing this lab, you will be able to:

- "Copy and Paste" a piping spec in the Catalog Task to create a brand new specification
- Modify piping spec data directly in the catalog database through the interface
- Edit/Create spec's Rules
- Edit/Create Branch Table in paper spec format
- Create and modify code list values through the Catalog Task


Using the Catalog Task only, start creation of a new piping spec "CC150-1C": 150#, RF, Carbon Steel, design std ANSI-B31.3, service: Utilities; Corrosion Allowance of 0.063, -20 to 800 degF, cement lined.

Use the following temperature-pressure chart:


TEMP F	100	200	300	400	500	600	700	800
Psig	285	260	230	200	170	140	110	80

Using the Catalog Task verify that cement lining is an available option and add Kynar lining as an additional lining option to the select list.


Use the following branch table for the new spec:




- 1. Open the Catalog Task to ... Piping Specification>Piping Materials Classes
- 2. Select a spec in the catalog tree view, e.g. CC150-1 or 1C0031.
- 3. Use Edit>Copy or the Copy ribbon bar button
- 4. Use Edit>Paste or the Paste ribbon bar button. When prompted, enter the new spec name: "CC150-1C"




- 5. Open the Catalog Task to Select Lists>Lining Material
- 6. Verify that "Cement Lined" is available in the short description column
- 7. Modify the Select List to include "Kynar" as an option in the short description column




- 8. Return to ...Piping Specification>Piping Materials Classes and edit the pasted spec name and spec properties in the grid view to match spec requirements
- 9. Select Tools>Options and set <u>all</u> "Units" tabs to display pressure ("force per area") to Psi



10. Navigate to Piping>Piping Specification>Piping Materials Classes> CC150-1C>Piping Materials Class Rules>Service Limits Rule and set the temperature and pressure limits rule to their proper values for this spec as provided above.



- 11. Open the Piping Commodity Filter node for the new piping specification, review the component data copied from the original spec.
- 12. If needed, define the branch components in the Piping Commodity Filter required by the branch table provided.
- 13. To enter the branch table preferred branching items, open the node at Piping>Piping Specification>Piping Materials Classes> CC150-1C>Piping Materials Class Rules>Branch
- 14. To generate a simplified paper-spec style view of the branch table do as follows:
 - a. With the Branch Table node selected, use Actions>Add Range
 - b. Enter the range values for existing data: From 89.5 To 90.5
 - c. Provide a name for the range of values, e.g. "90 Degrees"
 - d. Select the branch priority level: "Primary" and OK the form
 - e. Fill the branch table per the table in the instructions above



15. Once all desired fittings and components are defined, run Tools>Verify Consistency to check for errors.

In practice, make sure that a good backup of the Catalog is made after a new spec is defined. For the moment, there is no means of exporting the new specs created in the Catalog Task out to Excel.