





RP2040 pinout diagram & pin explanations & descriptions on page 12 of <https://pip-assets.raspberrypi.com/categories/814-rp2040/documents/RP-008371-DS-1-rp2040-datasheet.pdf>



It's standard to have 27 ohm resistors going into the MCU to prevent distortion of signals at high speeds (they're called termination resistors)

CLK are inputs from the slave (the flash memory), which means they're also outputs from the MCU

all the input/outputs are bidirectional

XIN is an output from the MCU (so it's an output from the MCU) that helps the crystal oscillate properly

XOUT is the output from the crystal (so it's an input to the MCU)

