

Approval Report for Boiler B-4

The inspection report indicates that Boiler B-4 is in satisfactory condition. No corrective actions are required.

Key Findings: 1. No visible leakage or abnormal vibration was observed. 2. Temperature and pressure readings were within normal limits. 3. Safety indicators and emergency shutdown controls were operational.

Recommendation: Equipment may continue normal operation.

Approval Status: Approved