

Approval Report

Based on the inspection report, the following actions have been taken:

1. The inspection was conducted during normal operation. 2. No visible leakage or abnormal vibration was observed. 3. Temperature and pressure readings were within normal operating limits. 4. Safety indicators and emergency shutdown controls were found operational.

The inspection status is SATISFACTORY, and the equipment may continue normal operation without immediate corrective action.

Approval is given for the continued operation of Boiler B-4.