

Near Sai Vitthal Colony District Amravati 444607



Collateral ID:



123AMI607-068543

Asset Valuation

INDIVIDUAL TECHNICAL REPORT				
Request ID:	HRQ-23-103769	Application No:	77936203997	
Customer Name:	Pawan Prabhakar Akolkar		(10004) AMRAVATI	
Product Name:	HI - RhI - Home Purchase - Re Finance	BSM/RM Name:	Pratik Bhojane	
Loan Property Type:		Visited User Type:	Technical Agency	
Contact Name:	Pawan Prabhakar Akolkar	Mobile :	8788366015	8087677978

PROPERTY ADDRESS					
Property Address:	Plot No 28 East Part S.No 30-3 And 30-4 Mouje Saturna	Location: Navathe			
	Pragne Badnera Anuradha Nagar Mahabank Nagar 444607Near Sai Vitthal Colony District-Amravati	City:	Amravati	Pin Code 444607	
	,	State:	Maharashtra	Country India	
	Plot No 28 East Part S.No 30-3 And 30-4 Mouje Saturna Pragne Badnera Anuradha Nagar Mahabank Nagar,	Nearby Landmark:	Near Sai Temple		
		Callatoral ID:	122 4 1 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2		

Type Of Property:	Bunglow	Plot Demarcated At Site:	YES
Approved Land Use:	Residential	Infrastructure Of The Surrounding Area:	YES
No of Floors:	0	Class Of Locality:	Middle Class Area
Carpet Area Measured:	No	Property Location:	Municipal Corporation
Material at site:	Na	Distance Travelled From Operating Office:	12
Natute of Location:	Urban	Distance from City Center Km:	15
Green Housing:	No	Report Condition:	Property Visited Report

PROPERTY DETAILS

UNIT DETAILS				
Detail	No. of Rooms	No. of Kitchens	No of Bathrooms	Usages & Remark
Ground Floor	0	0	0	0
First Floor	0	0	0	0
Second Floor	0	0	0	0
Other1	0	0	0	0
Other2	0	0	0	0

Structure	Occupancy Status Occupied	Occupied By Mr.Rajkumar	Apprx. Property Age (For Home Improvement/ Home
Maintenance Level	Occupied Since	Relationship of Occupant	Residual Age Of Property
0	YEAR 2022	Tenant Occupied	24

BOUNDARIES ON SITE				
	East	West	North	South
As per Sale Deed	Plot No.29	Remaing Part Of Same Of Plot	Service Lane	30 Feet Wide Road
Actual on Site	Plot No.29	Remaing Part Of Same Of Plot	Service Lane	30 Feet Wide Road
Boundary	Yes			

VALUATION AS PER GOVT. APPROVED RATES Land/Build up/Saleable Area Land/Build up/Saleable Rate 1 1 Constructed Area: Constructed Rate: 1 1 Realizable ₹ 2 **VALUATION DETAILS** Description Area in Sq. Ft Rate per Sq.Ft Amount(R) (A) 5952000 Land 1860 3200 0 0 Construction 0 (B) **EXTRA COST FOR INTERNAL AMENITIES/ HOME IMPROVEMENT DESCRIPTION RATE QUANTITY AMOUNT** Desc 1 0 0 0 Desc 3 0 0 0 Desc 4 0 0 0 Desc 6 0 0 0 Desc 7 0 0 0 Desc 8 0 0 0 Desc 9 0 0 0 Desc 10 0 0 0 Desc 11 0 0 0 Desc 2 0 0 0 Desc 12 0 0 0 Desc 5 0 0 0 Value As On Date: 5952000 Value of extra Amenities 0 0 % Completion Religzable value: 5952000 % Recommended 0 Realizable value Round Off: 5952000 Fifty-Nine Lakh Fifty-Two Thousand Realizable Value In Words: Visited By: Merit Construction Associates_Hfc Visited on: 17-Jul-2023 Violations observed Presently Property Havning Comman Enterance And Property Is Not Seprately Demarcated. (if any): Remarks: 1. Property Identifed By Property Documents, Local Inqury And Buyer Of The Property. 2. Presently Property Seprately Not Divided 3. Plot No.28 Admeasuing 3300 Sqft In Which Applicant Purchasing North South Divide East Part 1860 Sqft Plot Area. 4. As Per Buyer Openion He Will Demolish House So Only Land Area Considered For Valution 4. This Is HI RhI Home Purchase Re Finance Case, Report Release On The Basis Of Sale Deed Sr No.1293 Date 04/04/1997, Ats- Dated 22/06/2023, Layout Map-Dated-06/03/2019, Na Order- Dated-30/04/1976 5. As Per Ndma Norms Said Property Is Not In Crz And Not In Flood Prone Zone, The Height Of Building Above Ground Floor Level Is Less Than 15 M. Sesmic Zone Is 3. 6. Geo-Cordinates Of Property Is 20.895528, 77.741472 Entered By: Entered On: Merit Construction Associ 18-Jul-2023 **Completion Status:** Recommended by: Prasad Hire Not Applicable-Land Loan Recommender's Recommended For Approval Comment: Approver Name: Approver ID: Prasad Hire HE005084 18-Jul-2023 App Designation: Approved On: Area Technical Manager Okbefore Cheque Handover, The Construction On The Site Will Have To Be Demolished And Demarcation Of The Plot On The Approver's Eastern Side Should Be Done And The Technical Team Should Inspect Them. Credit Team Please Mark This Sanction Comment: Condition







Longitude: NULL
Latitude: NULL
Image Taken NULL

Latitude: NULL
Image Taken NULL

OMNI DOCS FILES

File Name Latitude Longitude Go To Map

DECLARATION

//We herby declare that: 1. The property was inspected by me/us. 2. I/We have no direct or indirect Interest in the property valued 3. The information furnished above is true and correct to my/our knowledge.

DISCAIMER: ICICI Group is merely acting in the capacity of a valuer and does not undertake any responsibility for aspects other than valuation of property as mentioned in the report. All assistance is provided on a best effort basis only.

The valuation report ("Report") is based on the location of the property, infrastructure available, overall development of the vicinity and prevailing market rates for similar properties and on the facts and confirmation provided by the client ("Client") or his professional advisor or any other party on behalf of the Client as on date of assessment, which the Client represents to be complete and accurate in all respects. Report contains no representations or warranties of any kind. The Client should exercise appropriate due diligence with respect to the property, including approval status, legal and tax diligence, prior to taking of any decision. Compliance with statutory requirements applicable for construction is the responsibility of person undertaking the construction activity. ICICI Group does not have any role in construction and pricing of the project / Property. ICICI Group has not undertaken any investigation into the title of the property and the valuation is made on the presumption that the property possesses a good and marketable title and is free from encumbrances.

The contents of this Report are strictly confidential and are intended for the exclusive use of the Client. This document may not be altered in any way, transmitted, copied or distributed, in part or in whole, to any other person or to the media or reproduced in any form, without prior written consent of ICICI Group. ICICI Group accepts no responsibility or liability to any third party for whole or any part of the Report.

ICICI Group specifically excludes any liability with respect to any losses incurred by the Client due to any act or omission of the developer or any other third party and any consequences thereof. ICICI Group's total aggregate liability to the Client for any reason, whatsoever, shall be limited to an aggregate sum not exceeding the total fees received