Generated 2026-03-12 21:07:52

Dell Inc. XPS 8960 | Intel(R) Core(TM) i9-14900K | 29.7 GB RAM

---

50
POOR

## Overall System Health

Based on analysis of event logs, drivers, hardware status, BSOD history, and Intel CPU microcode.

2 Critical | 2 Warnings | 1 Info

## Key Findings

### Critical Issues

- ⚠ 20 unexpected shutdowns (Kernel-Power 41) detected. Combined with BSODs, this points to a hardware or power delivery issue.
- ⚠ 6 WHEA (hardware error) events found. This strongly indicates a hardware problem – likely CPU, RAM, or motherboard. With an i9-14900K, this is a hallmark of the Intel voltage degradation issue.

### Warnings

- ⚠ 5 BSOD minidump(s) found in the last 30 days.
- ⚠ 20 third-party drivers are over 2 years old. Outdated drivers can cause BSODs.

### Informational

- ℹ INTEL CPU: BIOS date (2026-01-05) is recent and likely includes the Intel microcode fix. However, if the CPU was already degraded before the fix, damage may be irreversible.

# Intel CPU Stability Analysis

## Intel 13th/14th Gen Instability Check

| CPU Family | Microcode |
|---|---|
| Intel 14th Gen Core i9 (Raptor Lake Refresh) | `0x33010000` |

| BIOS Date |
|---|
| 2026-01-05 |

**Background:** Intel acknowledged that 13th/14th Gen desktop processors (i5/i7/i9) had an elevated operating voltage issue causing instability and permanent degradation. Root causes: eTVB (Enhanced Thermal Velocity Boost) and SVID (Serial VID) algorithms requesting excessive voltage. Intel released microcode 0x129 in August 2024 to mitigate this. CPUs already damaged may need replacement under Intel extended warranty.

**Recommendation:** BIOS appears up to date. If BSODs persist, the CPU may have already sustained degradation. Intel extended their warranty by 2 years for affected 13th/14th Gen CPUs. Visit warranty.intel.com to check status and submit a replacement claim.

### How to Check Intel Warranty

1. Go to **warranty.intel.com** and sign in or create an account
2. Click **Check Warranty Status** -- enter CPU ATPO/batch number
3. No batch number? Download Intel **Processor Diagnostic Tool**
4. Click **Submit a Warranty Request**
5. Select issue type: **System instability / BSOD**
6. Mention WHEA errors, bug check codes, and daily BSOD frequency
7. Intel typically cross-ships replacement CPUs
8. **Alternative:** Contact Dell Support -- they may handle it under Dell warranty

## BSOD / Crash Analysis

| | |
|---|---|
| Minidump Files | 5 |
| Crashes - 30 days | 5 |
| Unexpected Shutdowns | 20 |
| Bug Check Codes | 0 unique |

### Recent BSOD Events

| DATE | BUG CHECK | DETAILS |
|---|---|---|
| 2026-03-12 06:21:20 | | The computer has rebooted from a bugcheck. The bugcheck was: 0x0000003b (0x00000000c0000005, 0xfffff80520e9642a, 0xffff8086cc2d61a0, 0x0000000000000000). A dump was saved in: C:\WINDOWS\Minidump\031226-19312-01.dmp. Report Id: 24a0e51d-9e89-4e11-a408-44c5ec188008. |
| 2026-03-04 06:11:39 | | The computer has rebooted from a bugcheck. The bugcheck was: 0x00020001 (0x0000000000000001, 0x00007d56bdd5c385, 0x00007d56bdd5c3d5, 0xffff82a9422a3c2a). A dump was saved in: C:\WINDOWS\Minidump\030426-17312-01.dmp. Report Id: 0a310b64-da07-4145-b893-33bae64a3465. |
| 2026-02-25 20:07:21 | | The computer has rebooted from a bugcheck. The bugcheck was: 0x00000050 (0xfffff80388e57e4d, 0x0000000000000010, 0xfffff80388e57e4d, 0x0000000000000002). A dump was saved in: C:\WINDOWS\Minidump\022526-18109-01.dmp. Report Id: 82830b2f-15f0-479d-b9e5-8bc10ddbbd0b. |
| 2026-02-23 03:40:52 | | The computer has rebooted from a bugcheck. The bugcheck was: 0x00020001 (0x0000000000000001, 0x0000cc2bea444d28, 0x0000cc2bea444d78, 0xffff33d415bbb287). A dump was saved in: C:\WINDOWS\Minidump\022326-17875-01.dmp. Report Id: 90cbd9e7-a35e-4a3b-bd93-46ae37dbcc9d. |
| 2026-02-12 03:40:18 | | The computer has rebooted from a bugcheck. The bugcheck was: 0x0000003b (0x00000000c0000005, 0xfffff801c5233a2f, 0xfffff605ada4cab0, 0x0000000000000000). A dump was saved in: |

| DATE | BUG CHECK | DETAILS |
|---|---|---|
| | | C:\WINDOWS\Minidump\021226-18250-01.dmp. Report Id: 2bc00859-2cd0-4080-9a01-2ad3ba877c21. |
| 2026-02-11 03:10:32 | | The computer has rebooted from a bugcheck. The bugcheck was: 0x00020001 (0x0000000000000001, 0x0000444023bc4aff, 0x0000444023bc4aaf, 0xffffbbbfdc43b550). A dump was saved in: C:\WINDOWS\Minidump\021126-16937-01.dmp. Report Id: 2588c95e-59af-480b-9b96-07781b0e5968. |
| 2026-02-11 03:09:13 | | The computer has rebooted from a bugcheck. The bugcheck was: 0x00020001 (0x0000000000000011, 0x00000000002c32ce, 0x0000000000001005, 0xffffe70001205c70). A dump was saved in: C:\WINDOWS\Minidump\021126-17218-01.dmp. Report Id: ef0c9e11-16fc-484d-91a1-2889df8ae453. |
| 2026-02-10 18:46:20 | | The computer has rebooted from a bugcheck. The bugcheck was: 0x0000003b (0x00000000c0000005, 0xfffff8017592641e, 0xffffaa8fa8dddfb0, 0x0000000000000000). A dump was saved in: C:\WINDOWS\Minidump\021026-15421-01.dmp. Report Id: db60b3d2-9ecd-41bc-b9eb-1ca66d7d59a7. |
| 2026-02-05 00:00:19 | | The computer has rebooted from a bugcheck. The bugcheck was: 0x00000050 (0xffffffffffffff89, 0x0000000000000002, 0xfffff8027995641e, 0x0000000000000002). A dump was saved in: C:\WINDOWS\Minidump\020526-19671-01.dmp. Report Id: 7c05076e-c1ad-4670-8c73-4912ee14b3d5. |
| 2026-02-04 02:07:12 | | The computer has rebooted from a bugcheck. The bugcheck was: 0x00020001 (0x0000000000000011, 0x00000000002c32ce, 0x0000000000001005, 0xffffe70001205c70). A dump was saved in: C:\WINDOWS\Minidump\020426-19500-01.dmp. Report Id: c2ecb56b-2837-4dad-a2a4-755d87dc3039. |
| 2026-02-03 01:14:27 | | The computer has rebooted from a bugcheck. The bugcheck was: 0x000000ef (0xffffc187ba351080, 0x0000000000000000, 0xffffc187a758b080, 0x0000000000000000). A dump was saved in: C:\WINDOWS\Minidump\020326-19953-01.dmp. Report Id: b2f5d89e-229e-4c9d-a561-e8bbb6397889. |
| 2026-02-03 01:11:36 | | The computer has rebooted from a bugcheck. The bugcheck was: 0x0000003b (0x00000000c0000005, 0xfffff80396f29713, 0xffffd60fa58a6ac0, |

| DATE | BUG CHECK | DETAILS |
|---|---|---|
| | | 0x0000000000000000). A dump was saved in: C:\WINDOWS\Minidump\020326-17437-01.dmp. Report Id: 91694982-ded2-4f37-b641-1e46302edab5. |
| 2026-01-30 01:48:16 | | The computer has rebooted from a bugcheck. The bugcheck was: 0x000000f7 (0x00005681218e7958, 0x00000393e109ea92, 0xfffffc6c1ef6156d, 0x0000000000000000). A dump was saved in: C:\WINDOWS\Minidump\013026-19562-01.dmp. Report Id: dcab2863-5061-4e20-b157-0e3efdf0b777. |
| 2026-01-27 02:25:40 | | The computer has rebooted from a bugcheck. The bugcheck was: 0x0000003b (0x00000000c0000005, 0xfffff80176b29713, 0xfffff2079a9ceac0, 0x0000000000000000). A dump was saved in: C:\WINDOWS\Minidump\012726-19765-01.dmp. Report Id: eaf3ac00-14b8-416f-9e85-172c434cc675. |
| 2026-01-26 18:27:49 | | The computer has rebooted from a bugcheck. The bugcheck was: 0x0000003b (0x00000000c0000005, 0xfffff806e4f29713, 0xffff8502a450eac0, 0x0000000000000000). A dump was saved in: C:\WINDOWS\Minidump\012626-18078-01.dmp. Report Id: b6ee3979-ddaa-4db0-a288-962c71374229. |

## Unexpected Shutdowns - Kernel-Power 41

20 events found — system lost power or crashed without clean shutdown.

| DATE | DETAILS |
|---|---|
| 2026-03-12 06:21:05 | The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly. |
| 2026-03-12 06:20:22 | The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly. |
| 2026-03-11 07:25:15 | The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly. |
| 2026-03-10 07:17:27 | The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly. |

| DATE | DETAILS |
|---|---|
| 2026-03-09 06:12:20 | The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly. |
| 2026-03-08 09:48:10 | The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly. |
| 2026-03-06 21:23:55 | The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly. |
| 2026-03-05 06:58:42 | The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly. |
| 2026-03-04 06:11:25 | The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly. |
| 2026-03-03 06:10:26 | The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly. |

## Minidump Files

Analyze with **WinDbg** (Microsoft Store): `.symfix; .reload; !analyze -v`

| FILE | DATE | SIZE |
|---|---|---|
| `031226-19312-01.dmp` | 2026-03-12 06:21:17 | 7072.7 KB |
| `030426-17312-01.dmp` | 2026-03-04 06:11:36 | 12322.6 KB |
| `022526-18109-01.dmp` | 2026-02-25 20:07:18 | 7086.1 KB |
| `022326-17875-01.dmp` | 2026-02-23 03:40:50 | 12585.7 KB |
| `021226-18250-01.dmp` | 2026-02-12 03:40:15 | 242.5 KB |

# Event Log Analysis

## WHEA Hardware Errors

**WHEA errors are strong indicators of hardware failure.** With an Intel 13th/14th Gen CPU, these often signal voltage-induced CPU degradation.

| DATE | SOURCE | ID | MESSAGE |
|---|---|---|---|
| 2026-03-04 06:11:40 | Microsoft-Windows-WHEA-Logger | 17 | A corrected hardware error has occurred. Component: PCI Express Root Port Error Source: Advanced Error Reporting (PCI Express) Primary Bus:Device:Function: 0x0:0x1C:0x0 Secondary Bus:Device:Function: 0x0:0x0:0x0 Primary Device Name:PCI\VEN_8086&DEV_7ABC&SUBSYS_0BC01028&REV_11 Secondary Device Name: |
| 2026-02-18 08:21:08 | Microsoft-Windows-WHEA-Logger | 17 | A corrected hardware error has occurred. Component: PCI Express Root Port Error Source: Advanced Error Reporting (PCI Express) Primary Bus:Device:Function: 0x0:0x1C:0x0 Secondary Bus:Device:Function: 0x0:0x0:0x0 Primary Device Name:PCI\VEN_8086&DEV_7ABC&SUBSYS_0BC01028&REV_11 Secondary Device Name: |
| 2026-02-01 07:55:11 | Microsoft-Windows-WHEA-Logger | 17 | A corrected hardware error has occurred. Component: PCI Express Root Port Error Source: Advanced Error Reporting (PCI Express) Primary Bus:Device:Function: 0x0:0x1C:0x0 Secondary Bus:Device:Function: 0x0:0x0:0x0 Primary Device Name:PCI\VEN_8086&DEV_7ABC&SUBSYS_0BC01028&REV_11 Secondary Device Name: |
| 2025-12-30 17:10:56 | Microsoft-Windows-WHEA-Logger | 17 | A corrected hardware error has occurred. Component: PCI Express Root Port Error Source: Advanced Error Reporting (PCI Express) Primary Bus:Device:Function: 0x0:0x1C:0x0 Secondary Bus:Device:Function: 0x0:0x0:0x0 Primary Device Name:PCI\VEN_8086&DEV_7ABC&SUBSYS_0BC01028&REV_11 Secondary Device Name: |

| DATE | SOURCE | ID | MESSAGE |
|---|---|---|---|
| 2025-12-08 17:46:19 | Microsoft-Windows-WHEA-Logger | 17 | A corrected hardware error has occurred. Component: PCI Express Root Port Error Source: Advanced Error Reporting (PCI Express) Primary Bus:Device:Function: 0x0:0x1C:0x0 Secondary Bus:Device:Function: 0x0:0x0:0x0 Primary Device Name:PCI\VEN_8086&DEV_7ABC&SUBSYS_0BC01028&REV_11 Secondary Device Name: |
| 2025-11-20 18:18:36 | Microsoft-Windows-WHEA-Logger | 17 | A corrected hardware error has occurred. Component: PCI Express Root Port Error Source: Advanced Error Reporting (PCI Express) Primary Bus:Device:Function: 0x0:0x1C:0x0 Secondary Bus:Device:Function: 0x0:0x0:0x0 Primary Device Name:PCI\VEN_8086&DEV_7ABC&SUBSYS_0BC01028&REV_11 Secondary Device Name: |

## System Critical Events

| DATE | SOURCE | ID | MESSAGE |
|---|---|---|---|
| 2026-03-12 06:21:05 | Microsoft-Windows-Kernel-Power | 41 | The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly. |
| 2026-03-12 06:20:22 | Microsoft-Windows-Kernel-Power | 41 | The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly. |
| 2026-03-11 07:25:15 | Microsoft-Windows-Kernel-Power | 41 | The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly. |
| 2026-03-10 07:17:27 | Microsoft-Windows-Kernel-Power | 41 | The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly. |

| DATE | SOURCE | ID | MESSAGE |
|---|---|---|---|
| 2026-03-09 06:12:20 | Microsoft-Windows-Kernel-Power | 41 | The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly. |
| 2026-03-08 09:48:10 | Microsoft-Windows-Kernel-Power | 41 | The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly. |
| 2026-03-06 21:23:55 | Microsoft-Windows-Kernel-Power | 41 | The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly. |
| 2026-03-05 06:58:42 | Microsoft-Windows-Kernel-Power | 41 | The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly. |
| 2026-03-04 06:11:25 | Microsoft-Windows-Kernel-Power | 41 | The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly. |
| 2026-03-03 06:10:26 | Microsoft-Windows-Kernel-Power | 41 | The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly. |
| 2026-03-01 10:55:31 | Microsoft-Windows-Kernel-Power | 41 | The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly. |
| 2026-02-25 20:07:07 | Microsoft-Windows-Kernel-Power | 41 | The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly. |
| 2026-02-25 20:06:22 | Microsoft-Windows-Kernel-Power | 41 | The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly. |
| 2026-02-23 08:04:50 | Microsoft-Windows-Kernel-Power | 41 | The system has rebooted without cleanly shutting down first. This error could be |

| DATE | SOURCE | ID | MESSAGE |
|---|---|---|---|
| | | | caused if the system stopped responding, crashed, or lost power unexpectedly. |
| 2026-02-23 03:40:39 | Microsoft-Windows-Kernel-Power | 41 | The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly. |

### System Errors - Last 50

▶ Click to expand - 50 events

## Driver Analysis

| | | | |
|---|---|---|---|
| Total Drivers | 316 | Third-Party | 58 |
| With Errors | 0 | Outdated - 2yr+ | 20 |

### Third-Party Drivers - 58

▶ Click to expand

## Disk Health

### Samsung SSD 970 EVO Plus 2TB

HEALTHY

| | | | |
|---|---|---|---|
| Type | SSD | Size | 1863 GB |
| Bus | NVMe | Wear | N/A |
| Temp | 37C | Power On | N/A hrs |
| Read Errors | N/A | Write Errors | N/A |

### Samsung SSD 970 EVO Plus 2TB

HEALTHY

| | | | |
|---|---|---|---|
| Type | SSD | Size | 1863 GB |
| Bus | NVMe | Wear | N/A |
| Temp | 38C | Power On | N/A hrs |
| Read Errors | N/A | Write Errors | N/A |

### NVMe Samsung SSD 990 PRO with Heatsink 1TB

HEALTHY

| | | | |
|---|---|---|---|
| Type | SSD | Size | 931.5 GB |
| Bus | NVMe | Wear | N/A |
| Temp | 60C | Power On | N/A hrs |
| Read Errors | N/A | Write Errors | N/A |

### Samsung SSD 990 PRO 2TB

HEALTHY

| | | | |
|---|---|---|---|
| Type | SSD | Size | 1863 GB |
| Bus | NVMe | Wear | N/A |

| | | | |
|---|---|---|---|
| Temp | 40C | Power On | N/A hrs |
| Read Errors | N/A | Write Errors | N/A |

### Samsung SSD 990 PRO 2TB

HEALTHY

| | | | |
|---|---|---|---|
| Type | SSD | Size | 1863 GB |
| Bus | NVMe | Wear | N/A |
| Temp | 40C | Power On | N/A hrs |
| Read Errors | N/A | Write Errors | N/A |

### NVMe PC811 SK hynix 1024GB

HEALTHY

| | | | |
|---|---|---|---|
| Type | SSD | Size | 953.9 GB |
| Bus | NVMe | Wear | N/A |
| Temp | 60C | Power On | N/A hrs |
| Read Errors | N/A | Write Errors | N/A |

## Volumes

| DRIVE | LABEL | FS | SIZE | FREE | % FREE | HEALTH |
|---|---|---|---|---|---|---|
| C: | OS | NTFS | 911.7 GB | 173.9 GB | 19.1% | Healthy |
| E: | Storage space | NTFS | 4935.9 GB | 323.4 GB | 6.6% | Healthy |
| D: | | NTFS | 931.5 GB | 892.7 GB | 95.8% | Healthy |

## Memory – RAM

| | |
|---|---|
| Total RAM | 29.7 GB |
| Sticks Installed | 2 |
| Speed Mismatch | No |
| XMP Concern | No |

### Installed Modules

| SLOT | SIZE | SPEED | MANUFACTURER | PART NUMBER |
|---|---|---|---|---|
| DIMM1 | 16 GB | 5600 MHz | 80AD000080AD | HMCG78AGBUA081N |
| DIMM2 | 16 GB | 5600 MHz | 80AD000080AD | HMCG78AGBUA081N |

## Thermal and Power

| Power Plan | CPU Performance | ACPI\ThermalZone\TZ00_0 |
|---|---|---|
| Balanced | 138.4% | 70.1C / 158.2F |

## System Information

| | | | |
|---|---|---|---|
| Computer | SHIGS78-PC24 | Model | Dell Inc. XPS 8960 |
| OS | Microsoft Windows 11 Pro | OS Build | 10.0.26200 / 26200 |
| CPU | Intel(R) Core(TM) i9-14900K | Cores / Threads | 24 / 32 |
| Max Clock | 3200 MHz | BIOS | 2.22.0 / 2026-01-05 |
| Baseboard | Dell Inc. 09M47G vA00 | RAM | 29.7 GB |
| Last Boot | 2026-03-12 06:21:01 | Uptime | 00.14:46:42 |

## Windows Updates and Integrity

### Recent Windows Updates

| DATE | RESULT | UPDATE |
|---|---|---|
| 2026-03-11 | Succeeded | 2026-03 Security Update (KB5079473) (26200.8037) |
| 2026-03-11 | Succeeded | 2026-03 .NET 9.0.14 Security Update for x64 Client (KB5081278) |
| 2026-03-11 | Succeeded | 2026-03 .NET 8.0.25 Security Update for x64 Client (KB5081277) |
| 2026-02-12 | Succeeded | Update for Windows Security platform - KB5007651 (Version 10.0.29510.1001) |
| 2026-02-11 | Succeeded | 2026-02 Security Update (KB5077181) (26200.7840) |
| 2026-02-11 | Succeeded | Windows Malicious Software Removal Tool x64 - v5.139 (KB890830) |
| 2026-02-11 | Succeeded | 2026-02 .NET 9.0.13 Security Update for x64 Client (KB5077864) |
| 2026-02-10 | Succeeded | 2026-02 .NET 8.0.24 Security Update for x64 Client (KB5077863) |
| 2026-02-04 | Succeeded | Intel Corporation Driver Update (32.0.101.7077) |
| 2026-01-21 | Succeeded | Intel Corporation Driver Update (32.0.101.7077) |
| 2026-01-13 | Succeeded | 2026-01 .NET 9.0.12 Update for x64 Client (KB5074753) |
| 2026-01-13 | Succeeded | 2026-01 Security Update (KB5074109) (26200.7623) |
| 2026-01-13 | Succeeded | 2026-01 .NET 8.0.23 Update for x64 Client (KB5074752) |
| 2026-01-08 | Succeeded | Update for Microsoft Defender Antivirus antimalware platform - KB4052623 (Version 4.18.25110.6) - Current Channel (Broad) |
| 2026-01-08 | Succeeded | Security Intelligence Update for Microsoft Defender Antivirus - KB2267602 (Version 1.443.563.0) - Current Channel (Broad) |

### Recommended Integrity Checks

Run these in an **Administrator PowerShell**:

```
sfc /scannow
DISM /Online /Cleanup-Image /RestoreHealth
```

```
chkdsk C: /f /r (requires reboot)
```

## Application Reliability

| App Crashes | 20 | App Hangs | 0 |
|---|---|---|---|

### Application Crashes - 20

▶ Click to expand

## Recommended Actions

Prioritized steps to resolve BSOD issues. **Red-highlighted steps are highest priority.**

1

### Update Dell BIOS

Visit **dell.com/support**, enter Service Tag, download and install the latest BIOS for XPS 8960.

2

### Check Intel Warranty

If BSODs persist, visit **warranty.intel.com** -- Intel extended warranty for affected 13th/14th Gen CPUs.

3

### Run Memory Diagnostics

Windows Memory Diagnostic or **MemTest86** (free) overnight.

4

### Disable XMP in BIOS

If RAM exceeds 5600 MHz, disable XMP/EXPO and test at JEDEC defaults.

5

### Run SFC and DISM

`sfc /scannow` then `DISM /Online /Cleanup-Image /RestoreHealth`

6

### Update All Drivers

Visit **dell.com/support** -- chipset, GPU, and network drivers.

7

### Analyze Minidumps

Install **WinDbg**, run `!analyze -v` on .dmp files.

8

### Monitor Temperatures

Install **HWiNFO64**. i9-14900K should stay below 95C.

System Health Diagnostic Tool (Python) | 2026-03-12 21:07:52 | SHIGS78-PC24