Generated 2026-03-16 12:46:22

Dell Inc. XPS 8960 | Intel(R) Core(TM) i9-14900K | 29.7 GB RAM

Overall System Health

Based on analysis of event logs, drivers, hardware status, BSOD history, and Intel CPU microcode.

2 Critical | 3 Warnings | 1 Info

Key Findings

Critical Issues

- ⚠ 20 unexpected shutdowns (Kernel-Power 41) detected. Combined with BSODs, this points to a hardware or power delivery issue.
- ⚠ 7 WHEA (hardware error) events found. This strongly indicates a hardware problem - likely CPU, RAM, or motherboard. With an i9-14900K, this is a hallmark of the Intel voltage degradation issue.

Warnings

- ⚠ 5 BSOD minidump(s) found in the last 30 days.
- ⚠ 20 third-party drivers are over 2 years old. Outdated drivers can cause BSODs.
- ⚠ CPU temperature at 81.1C - elevated. Monitor cooling performance.

Informational

- ℹ INTEL CPU: BIOS date (2026-01-05) is recent and likely includes the Intel microcode fix. However, if the CPU was already degraded before the fix, damage may be irreversible.

Intel CPU Stability Analysis

Intel 13th/14th Gen Instability Check

CPU Family	Microcode
Intel 14th Gen Core i9 (Raptor Lake Refresh)	`0x33010000`

BIOS Date
2026-01-05

Background: Intel acknowledged that 13th/14th Gen desktop processors (i5/i7/i9) had an elevated operating voltage issue causing instability and permanent degradation. Root causes: eTVB (Enhanced Thermal Velocity Boost) and SVID (Serial VID) algorithms requesting excessive voltage. Intel released microcode 0x129 in August 2024 to mitigate this. CPUs already damaged may need replacement under Intel extended warranty.

Recommendation: BIOS appears up to date. If BSODs persist, the CPU may have already sustained degradation. Intel extended their warranty by 2 years for affected 13th/14th Gen CPUs. Visit warranty.intel.com to check status and submit a replacement claim.

How to Check Intel Warranty

1. Go to **warranty.intel.com** and sign in or create an account
2. Click **Check Warranty Status** -- enter CPU ATPO/batch number
3. No batch number? Download Intel **Processor Diagnostic Tool**
4. Click **Submit a Warranty Request**
5. Select issue type: **System instability / BSOD**
6. Mention WHEA errors, bug check codes, and daily BSOD frequency
7. Intel typically cross-ships replacement CPUs
8. **Alternative:** Contact Dell Support -- they may handle it under Dell warranty

BSOD / Crash Analysis

Minidump Files	5
Crashes - 30 days	5
Unexpected Shutdowns	20
Bug Check Codes	0 unique

Recent BSOD Events

DATE	BUG CHECK	DETAILS
2026-03-16 07:34:45		The computer has rebooted from a bugcheck. The bugcheck was: 0x00020001 (0x0000000000000001, 0x0000a25dddcbce1b, 0x0000a25dddcbce4b, 0xffff5da2223431b4). A dump was saved in: C:\WINDOWS\Minidump\031626-18546-01.dmp. Report Id: 427996ab-b0cf-4ca3-bff3-de2f6ca01bc8.
2026-03-15 02:16:26		The computer has rebooted from a bugcheck. The bugcheck was: 0x0000003b (0x00000000c0000005, 0xfffff8056b7e642a, 0xffffbf08f091e1a0, 0x0000000000000000). A dump was saved in: C:\WINDOWS\Minidump\031526-17718-01.dmp. Report Id: 67207c32-30e1-442a-8f99-dbffbad73692.
2026-03-12 06:21:20		The computer has rebooted from a bugcheck. The bugcheck was: 0x0000003b (0x00000000c0000005, 0xfffff80520e9642a, 0xffff8086cc2d61a0, 0x0000000000000000). A dump was saved in: C:\WINDOWS\Minidump\031226-19312-01.dmp. Report Id: 24a0e51d-9e89-4e11-a408-44c5ec188008.
2026-03-04 06:11:39		The computer has rebooted from a bugcheck. The bugcheck was: 0x00020001 (0x0000000000000001, 0x00007d56bdd5c385, 0x00007d56bdd5c3d5, 0xffff82a9422a3c2a). A dump was saved in: C:\WINDOWS\Minidump\030426-17312-01.dmp. Report Id: 0a310b64-da07-4145-b893-33bae64a3465.
2026-02-25 20:07:21		The computer has rebooted from a bugcheck. The bugcheck was: 0x00000050 (0xfffff80388e57e4d, 0x0000000000000010, 0xfffff80388e57e4d, 0x0000000000000002). A dump was saved in:

DATE	BUG CHECK	DETAILS
		C:\WINDOWS\Minidump\022526-18109-01.dmp. Report Id: 82830b2f-15f0-479d-b9e5-8bc10ddbbd0b.
2026-02-23 03:40:52		The computer has rebooted from a bugcheck. The bugcheck was: 0x00020001 (0x0000000000000001, 0x0000cc2bea444d28, 0x0000cc2bea444d78, 0xffff33d415bbb287). A dump was saved in: C:\WINDOWS\Minidump\022326-17875-01.dmp. Report Id: 90cbd9e7-a35e-4a3b-bd93-46ae37dbcc9d.
2026-02-12 03:40:18		The computer has rebooted from a bugcheck. The bugcheck was: 0x0000003b (0x00000000c0000005, 0xfffff801c5233a2f, 0xfffff605ada4cab0, 0x0000000000000000). A dump was saved in: C:\WINDOWS\Minidump\021226-18250-01.dmp. Report Id: 2bc00859-2cd0-4080-9a01-2ad3ba877c21.
2026-02-11 03:10:32		The computer has rebooted from a bugcheck. The bugcheck was: 0x00020001 (0x0000000000000001, 0x0000444023bc4aff, 0x0000444023bc4aaf, 0xffffbbbfdc43b550). A dump was saved in: C:\WINDOWS\Minidump\021126-16937-01.dmp. Report Id: 2588c95e-59af-480b-9b96-07781b0e5968.
2026-02-11 03:09:13		The computer has rebooted from a bugcheck. The bugcheck was: 0x00020001 (0x0000000000000011, 0x00000000002c32ce, 0x0000000000001005, 0xffffe70001205c70). A dump was saved in: C:\WINDOWS\Minidump\021126-17218-01.dmp. Report Id: ef0c9e11-16fc-484d-91a1-2889df8ae453.
2026-02-10 18:46:20		The computer has rebooted from a bugcheck. The bugcheck was: 0x0000003b (0x00000000c0000005, 0xfffff8017592641e, 0xffffaa8fa8dddfb0, 0x0000000000000000). A dump was saved in: C:\WINDOWS\Minidump\021026-15421-01.dmp. Report Id: db60b3d2-9ecd-41bc-b9eb-1ca66d7d59a7.
2026-02-05 00:00:19		The computer has rebooted from a bugcheck. The bugcheck was: 0x00000050 (0xffffffffffffff89, 0x0000000000000002, 0xfffff8027995641e, 0x0000000000000002). A dump was saved in: C:\WINDOWS\Minidump\020526-19671-01.dmp. Report Id: 7c05076e-c1ad-4670-8c73-4912ee14b3d5.
2026-02-04 02:07:12		The computer has rebooted from a bugcheck. The bugcheck was: 0x00020001 (0x0000000000000011, 0x00000000002c32ce, 0x0000000000001005,

DATE	BUG CHECK	DETAILS
		0xffffe70001205c70). A dump was saved in: C:\WINDOWS\Minidump\020426-19500-01.dmp. Report Id: c2ecb56b-2837-4dad-a2a4-755d87dc3039.
2026-02-03 01:14:27		The computer has rebooted from a bugcheck. The bugcheck was: 0x000000ef (0xffffc187ba351080, 0x0000000000000000, 0xffffc187a758b080, 0x0000000000000000). A dump was saved in: C:\WINDOWS\Minidump\020326-19953-01.dmp. Report Id: b2f5d89e-229e-4c9d-a561-e8bbb6397889.
2026-02-03 01:11:36		The computer has rebooted from a bugcheck. The bugcheck was: 0x0000003b (0x00000000c0000005, 0xfffff80396f29713, 0xffffd60fa58a6ac0, 0x0000000000000000). A dump was saved in: C:\WINDOWS\Minidump\020326-17437-01.dmp. Report Id: 91694982-ded2-4f37-b641-1e46302edab5.
2026-01-30 01:48:16		The computer has rebooted from a bugcheck. The bugcheck was: 0x000000f7 (0x00005681218e7958, 0x00000393e109ea92, 0xfffffc6c1ef6156d, 0x0000000000000000). A dump was saved in: C:\WINDOWS\Minidump\013026-19562-01.dmp. Report Id: dcab2863-5061-4e20-b157-0e3efdf0b777.

Unexpected Shutdowns - Kernel-Power 41

20 events found — system lost power or crashed without clean shutdown.

DATE	DETAILS
2026-03-16 07:34:31	The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly.
2026-03-15 02:16:14	The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly.
2026-03-12 06:21:05	The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly.
2026-03-12 06:20:22	The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly.

DATE	DETAILS
2026-03-11 07:25:15	The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly.
2026-03-10 07:17:27	The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly.
2026-03-09 06:12:20	The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly.
2026-03-08 09:48:10	The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly.
2026-03-06 21:23:55	The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly.
2026-03-05 06:58:42	The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly.

Minidump Files

Analyze with **WinDbg** (Microsoft Store): `.symfix; .reload; !analyze -v`

FILE	DATE	SIZE
`031626-18546-01.dmp`	2026-03-16 07:34:42	11798.3 KB
`031526-17718-01.dmp`	2026-03-15 02:16:24	12966.1 KB
`031226-19312-01.dmp`	2026-03-12 06:21:17	7072.7 KB
`030426-17312-01.dmp`	2026-03-04 06:11:36	12322.6 KB
`022526-18109-01.dmp`	2026-02-25 20:07:18	7086.1 KB

Event Log Analysis

WHEA Hardware Errors

WHEA errors are strong indicators of hardware failure. With an Intel 13th/14th Gen CPU, these often signal voltage-induced CPU degradation.

DATE	SOURCE	ID	MESSAGE
2026-03-16 07:34:46	Microsoft-Windows-WHEA-Logger	17	A corrected hardware error has occurred. Component: PCI Express Root Port Error Source: Advanced Error Reporting (PCI Express) Primary Bus:Device:Function: 0x0:0x1C:0x0 Secondary Bus:Device:Function: 0x0:0x0:0x0 Primary Device Name:PCI\VEN_8086&DEV_7ABC&SUBSYS_0BC01028&REV_11 Secondary Device Name:
2026-03-04 06:11:40	Microsoft-Windows-WHEA-Logger	17	A corrected hardware error has occurred. Component: PCI Express Root Port Error Source: Advanced Error Reporting (PCI Express) Primary Bus:Device:Function: 0x0:0x1C:0x0 Secondary Bus:Device:Function: 0x0:0x0:0x0 Primary Device Name:PCI\VEN_8086&DEV_7ABC&SUBSYS_0BC01028&REV_11 Secondary Device Name:
2026-02-18 08:21:08	Microsoft-Windows-WHEA-Logger	17	A corrected hardware error has occurred. Component: PCI Express Root Port Error Source: Advanced Error Reporting (PCI Express) Primary Bus:Device:Function: 0x0:0x1C:0x0 Secondary Bus:Device:Function: 0x0:0x0:0x0 Primary Device Name:PCI\VEN_8086&DEV_7ABC&SUBSYS_0BC01028&REV_11 Secondary Device Name:
2026-02-01 07:55:11	Microsoft-Windows-WHEA-Logger	17	A corrected hardware error has occurred. Component: PCI Express Root Port Error Source: Advanced Error Reporting (PCI Express) Primary Bus:Device:Function: 0x0:0x1C:0x0 Secondary Bus:Device:Function: 0x0:0x0:0x0 Primary

DATE	SOURCE	ID	MESSAGE
			Device Name:PCI\VEN_8086&DEV_7ABC&SUBSYS_0BC01028&REV_11 Secondary Device Name:
2025-12-30 17:10:56	Microsoft-Windows-WHEA-Logger	17	A corrected hardware error has occurred. Component: PCI Express Root Port Error Source: Advanced Error Reporting (PCI Express) Primary Bus:Device:Function: 0x0:0x1C:0x0 Secondary Bus:Device:Function: 0x0:0x0:0x0 Primary Device Name:PCI\VEN_8086&DEV_7ABC&SUBSYS_0BC01028&REV_11 Secondary Device Name:
2025-12-08 17:46:19	Microsoft-Windows-WHEA-Logger	17	A corrected hardware error has occurred. Component: PCI Express Root Port Error Source: Advanced Error Reporting (PCI Express) Primary Bus:Device:Function: 0x0:0x1C:0x0 Secondary Bus:Device:Function: 0x0:0x0:0x0 Primary Device Name:PCI\VEN_8086&DEV_7ABC&SUBSYS_0BC01028&REV_11 Secondary Device Name:
2025-11-20 18:18:36	Microsoft-Windows-WHEA-Logger	17	A corrected hardware error has occurred. Component: PCI Express Root Port Error Source: Advanced Error Reporting (PCI Express) Primary Bus:Device:Function: 0x0:0x1C:0x0 Secondary Bus:Device:Function: 0x0:0x0:0x0 Primary Device Name:PCI\VEN_8086&DEV_7ABC&SUBSYS_0BC01028&REV_11 Secondary Device Name:

System Critical Events

DATE	SOURCE	ID	MESSAGE
2026-03-16 07:34:31	Microsoft-Windows-Kernel-Power	41	The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly.
2026-03-15 02:16:14	Microsoft-Windows-Kernel-Power	41	The system has rebooted without cleanly shutting down first. This error could be

DATE	SOURCE	ID	MESSAGE
			caused if the system stopped responding, crashed, or lost power unexpectedly.
2026-03-12 06:21:05	Microsoft-Windows-Kernel-Power	41	The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly.
2026-03-12 06:20:22	Microsoft-Windows-Kernel-Power	41	The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly.
2026-03-11 07:25:15	Microsoft-Windows-Kernel-Power	41	The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly.
2026-03-10 07:17:27	Microsoft-Windows-Kernel-Power	41	The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly.
2026-03-09 06:12:20	Microsoft-Windows-Kernel-Power	41	The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly.
2026-03-08 09:48:10	Microsoft-Windows-Kernel-Power	41	The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly.
2026-03-06 21:23:55	Microsoft-Windows-Kernel-Power	41	The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly.
2026-03-05 06:58:42	Microsoft-Windows-Kernel-Power	41	The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly.
2026-03-04 06:11:25	Microsoft-Windows-Kernel-Power	41	The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly.

DATE	SOURCE	ID	MESSAGE
2026-03-03 06:10:26	Microsoft-Windows-Kernel-Power	41	The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly.
2026-03-01 10:55:31	Microsoft-Windows-Kernel-Power	41	The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly.
2026-02-25 20:07:07	Microsoft-Windows-Kernel-Power	41	The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly.
2026-02-25 20:06:22	Microsoft-Windows-Kernel-Power	41	The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly.

System Errors - Last 50

▶ Click to expand - 50 events

Driver Analysis

Total Drivers	312	Third-Party	58
With Errors	0	Outdated - 2yr+	20

Third-Party Drivers - 58

▶ Click to expand

Disk Health

Samsung SSD 970 EVO Plus 2TB

HEALTHY

Type	SSD	Size	1863 GB
Bus	NVMe	Wear	N/A
Temp	36C	Power On	N/A hrs
Read Errors	N/A	Write Errors	N/A

Samsung SSD 970 EVO Plus 2TB

HEALTHY

Type	SSD	Size	1863 GB
Bus	NVMe	Wear	N/A
Temp	37C	Power On	N/A hrs
Read Errors	N/A	Write Errors	N/A

NVMe Samsung SSD 990 PRO with Heatsink 1TB

HEALTHY

Type	SSD	Size	931.5 GB
Bus	NVMe	Wear	N/A
Temp	60C	Power On	N/A hrs
Read Errors	N/A	Write Errors	N/A

Samsung SSD 990 PRO 2TB

HEALTHY

Type	SSD	Size	1863 GB
Bus	NVMe	Wear	N/A

Temp	40C	Power On	N/A hrs
Read Errors	N/A	Write Errors	N/A

Samsung SSD 990 PRO 2TB

HEALTHY

Type	SSD	Size	1863 GB
Bus	NVMe	Wear	N/A
Temp	40C	Power On	N/A hrs
Read Errors	N/A	Write Errors	N/A

NVMe PC811 SK hynix 1024GB

HEALTHY

Type	SSD	Size	953.9 GB
Bus	NVMe	Wear	N/A
Temp	60C	Power On	N/A hrs
Read Errors	N/A	Write Errors	N/A

Volumes

DRIVE	LABEL	FS	SIZE	FREE	% FREE	HEALTH
C:	OS	NTFS	911.7 GB	173.2 GB	19%	Healthy
E:	Storage space	NTFS	4935.9 GB	106.6 GB	2.2%	Healthy
D:		NTFS	931.5 GB	892.7 GB	95.8%	Healthy

Memory – RAM

Total RAM	29.7 GB
Sticks Installed	2
Speed Mismatch	No
XMP Concern	No

Installed Modules

SLOT	SIZE	SPEED	MANUFACTURER	PART NUMBER
DIMM1	16 GB	5600 MHz	80AD000080AD	HMCG78AGBUA081N
DIMM2	16 GB	5600 MHz	80AD000080AD	HMCG78AGBUA081N

Thermal and Power

Power Plan	CPU Performance	ACPI\ThermalZone\TZ00_0
Balanced	111.9%	81.1C / 178F

System Information

Computer	SHIGS78-PC24	Model	Dell Inc. XPS 8960
OS	Microsoft Windows 11 Pro	OS Build	10.0.26200 / 26200
CPU	Intel(R) Core(TM) i9-14900K	Cores / Threads	24 / 32
Max Clock	3200 MHz	BIOS	2.22.0 / 2026-01-05
Baseboard	Dell Inc. 09M47G vA00	RAM	29.7 GB
Last Boot	2026-03-16 07:34:27	Uptime	00.05:11:43

Windows Updates and Integrity

Recent Windows Updates

DATE	RESULT	UPDATE
2026-03-15	Succeeded	9PLJQ12FQ3CV-MicrosoftCorporationII.WinAppRuntime.Main.1.8
2026-03-11	Succeeded	2026-03 Security Update (KB5079473) (26200.8037)
2026-03-11	Succeeded	2026-03 .NET 9.0.14 Security Update for x64 Client (KB5081278)
2026-03-11	Succeeded	2026-03 .NET 8.0.25 Security Update for x64 Client (KB5081277)
2026-02-12	Succeeded	Update for Windows Security platform - KB5007651 (Version 10.0.29510.1001)
2026-02-11	Succeeded	2026-02 Security Update (KB5077181) (26200.7840)
2026-02-11	Succeeded	Windows Malicious Software Removal Tool x64 - v5.139 (KB890830)
2026-02-11	Succeeded	2026-02 .NET 9.0.13 Security Update for x64 Client (KB5077864)
2026-02-10	Succeeded	2026-02 .NET 8.0.24 Security Update for x64 Client (KB5077863)
2026-02-04	Succeeded	Intel Corporation Driver Update (32.0.101.7077)
2026-01-21	Succeeded	Intel Corporation Driver Update (32.0.101.7077)
2026-01-13	Succeeded	2026-01 .NET 9.0.12 Update for x64 Client (KB5074753)
2026-01-13	Succeeded	2026-01 Security Update (KB5074109) (26200.7623)
2026-01-13	Succeeded	2026-01 .NET 8.0.23 Update for x64 Client (KB5074752)
2026-01-08	Succeeded	Update for Microsoft Defender Antivirus antimalware platform - KB4052623 (Version 4.18.25110.6) - Current Channel (Broad)

Recommended Integrity Checks

Run these in an **Administrator PowerShell**:

```
sfc /scannow
DISM /Online /Cleanup-Image /RestoreHealth
```

```
chkdsk C: /f /r (requires reboot)
```

Application Reliability

App Crashes	20	App Hangs	0

Application Crashes - 20

▶ Click to expand

Recommended Actions

Prioritized steps to resolve BSOD issues. **Red-highlighted steps are highest priority.**

1

Update Dell BIOS

Visit **dell.com/support**, enter Service Tag, download and install the latest BIOS for XPS 8960.

2

Check Intel Warranty

If BSODs persist, visit **warranty.intel.com** -- Intel extended warranty for affected 13th/14th Gen CPUs.

3

Run Memory Diagnostics

Windows Memory Diagnostic or **MemTest86** (free) overnight.

4

Disable XMP in BIOS

If RAM exceeds 5600 MHz, disable XMP/EXPO and test at JEDEC defaults.

5

Run SFC and DISM

`sfc /scannow` then `DISM /Online /Cleanup-Image /RestoreHealth`

6

Update All Drivers

Visit **dell.com/support** -- chipset, GPU, and network drivers.

7

Analyze Minidumps

Install **WinDbg**, run `!analyze -v` on .dmp files.

8

Monitor Temperatures

Install **HWiNFO64**. i9-14900K should stay below 95C.

System Health Diagnostic Tool (Python) | 2026-03-16 12:46:22 | SHIGS78-PC24