	System	Brand	PLC Model	CPU Exact Model Number	Final Resolution Pénding work	Status	Closed date	Closed By	Remarks
1	Bypass stack (Diverter Damper)	Siemens	\$7-1500	1517H-3PN	1)Change Chinese Language Comments to English for software 2)Hardware is showing not equal		2027	20%	

	System	Brand	PLC Model	CPU Exact Model Number	Final Resolution Pending work	Status	Closed date	Closed By	Remarks
3	Ball cleaning system	Siemens	\$7-1200	1214C	Description Not clear & Wrong to be correctd Some descriptions are missing for example M78 tag in ball		1/2/2/2	Milosie	_
4	Self cleaning System	Siemens	57-1200	1214C	cleaning 3)Network Description to be added to show the function of the logic 4)Alarm Screen missing in the ball cleaning system 5) Memory Card for ball cleaning HMI not provided"		K.	#19	
	Debris Filter	Siemens	57-1200				3	A CONTRACTOR OF THE PROPERTY O	

51.3	No D	Document Ref.	System	Brand	PLC Model	CPU Exact Model Number	Final Resolution Pending work	Closed date Closed By	Signature	â
6		JAS101 - TK4004P- Amendment Agreement 04	Service Air compressor	Slemens	57-1500	1513R	1) Chineese Language for HMI & Software to be changed to english	2023 DUBION	200	<i>y</i>

System	Brand	PLC Model	CPU Exact Model Number	Final Resolution Pending work	Status	Closed date	Closed By	Remarks
8 Gas compressor	Siemens	\$7-410	сри	1)I/O and Logic description to be provided		15th May	20×3	

.0

SI.No	Document Ref.	System	Final Resolution Pending work	Closed date	Closed By Ro	emarks
9	JAS101 - TK4004P- Amendment Agreement 04	WTP	1)Symbols and commets to be provided and shall be unique for all timers and memory 2)Symobolic names descriptions to be provided for all DBS 3)DB Description should be unique currently many tags with same descriptions 4)SCADA Alarms in FC27 Should be Uniform and Shall not use PLC variable should use seperate variable 5)USED alarms in FC27 Should not be as spare. 6) Wincc component obekect manager missing 7)STL Logics to be change LAD/FBD or training to be provided 8)Symbols & Commands to be provided and shall be unique for all timmer and memory location 9) License for HMI Engineering 10)License for Logic software missing	16th June	Moeith Schil	

SI.No	Document Ref.	System	Brand	PLC Model	CPU Exact Model Number	Final Resolution Pending work	Closed date	Closed By	Signature
10	JAS101 - TK4004P- Amendment Agreement 04	ETP/OWS	Siemens	S7-1500		1)IO Tags description to be provided rather than "tgas-1" 2)License for HMI To be provided	John Ap.	D NB leg	* 20×

	System	Brand	PLC Model	CPU Exact Model Number	Final Resolution Pending work	Status	Closed date	Closed By	Remarks
12	W8H For RMS	slemens	\$7-200 SMART	ST30	1)Backup to be provided and verfied for logic 2)Backup to be provided and verfied for HMI 3) Licnesne to be provided for HMI		15th May	200	

Appendix 2: Negotiated Items

SI.NO	Document Ref.	Description	Final Resolution	Closed date	Closed By	Remarks
20	JAS101 - TK4004P- Amendment Agreement 04	Upgrade of Application Servers to latest Service Pack	Upgrade to Latest T3000. As recently informed upgrade can be done until the end of May 2023, exception for TDY upgrade, which will be done later, once software updgrade is available, and can be done online. EGA: Upgrade to latest version to be done at the time of implementation. Extension of outage may not be possible, which is under review. TDY system hardware and software to be upgared as confirmed by Siemens	5/5/2000	yok for	To loted of rentered of real case

S/N Observation description Date Closed Closed By		IC	C_App2a	
	S/N	Observation description	Date Closed	Closed By
IC App 23 40 PMS 2500 Signal verfication with Live / 1023	IC App 25 40	PMS 2500 Signal verfication with Live	1 5 2 223	11/1/20
IC_App2a 49 PMS 2500 Signal verfication with Live System still pending 6 – Jan – 2023	C_App2a 49	System still pending	6-Jun - 2023	Yah of out

Open ite m No.	LOP Status	Source ID	Punch items	Description of NOI	Category	Unit	ккѕ	Building	Classification-1	Originator From	Originator name)	Priority	Assigned Team	Action by	Date Raised	Date Closed	Closed By
1757	Active	FMS System	All FMS system Alarms are configured as Warning alarm(Yellow event) instead of TRIP (RED event). To be rectified.	N/A	C1	na	FMS System	N/A	СОМ-Е	EGA	Bala/LOGA	P3	E-COM	S3	2021/05/24	: CI	Bulings 17
1772	Active	50LAC11/21/31 FMS	The 50 >> protection wrongly configured as 51 . To Fixed.	N/A	C1	50	50LAC11/21/31 FMS	UBA02	СОМ-Е	EGA	Balamurali	P3	E-COM	S 3	2021/05/24	1	
1978	Active	24CEK10	Fault record fail alarm to be rectified.	N/A	C1	24	24CEK10	UBA02	COM-E	EGA	Balamurali	P3	E-COM	S3	2021/06/13	3	Crosed
2441	Active	FMS system	GSUT- relay B current not reading in FMS	N/A	C1	24	FMS system	N/A	E-COM	EGA	Balamurali	P3	E-COM	S3	2021/08/29	, 7	00/100/
2443	Active		24BBA10 Incomer A current , voltage not reading in FMS to be fixed.	N/A	C1	24	FMS system	N/A	E-COM	EGA	Balamurali	P3	E-COM	S3	2021/08/29	,) 1500 WW S/2
2444	Active	I FMS system I	24BBA20 201 was mentioned as BBA20201 to be corrected.	N/A	C1	24	FMS system	N/A	E-COM	EGA	Balamurali	P3	E-COM	S3	2021/08/29	,	10/1/2012
2445	Active		SFC, SEE MV relay name to be modified for clear identification.	N/A	C1	24	FMS system	N/A	E-COM	EGA	Balamurali	P3	E-COM	S3	2021/08/29)	

Open the	LOP Status	Source ID	Punch items	RKS	Supany	(Charatricutson-1	Originator From	Originatur nazyoj	Priority	Assigned Team	Action by	Date (Panied	trate Glosed	Closed By
44	Active	Inspection call No. 34 RevA	Not any Third Party Communication Redundancy checked due to not availibility of Third Party. To be checked on site	схх	UBA02	FAT	EGA	Yahia	P3	IC-COM	S3	2019/11/06	250	ghoto
						,	-					- f.:	4	

Open Ite m No.	LOP Status	Source ID	Punch items	Category	Unit	Building	Originator From	Originator name)	Assigned Team	Date Closed	Closed By
177	Dispute	24BBA	The DCS Command should reset incase the Breaker fail to close and does not depend on operator reset action	Dispute	24	UBA02	EGA	Yahia	IC-COM	4 May ron	j. hof

m No. LOP Status Source ID Punch items	Originator name)	Priority	Assigned Team	Action by	Raised	Date Closed	Closed By	\ \ \ \	
186 Active 24BBA Communication signal from DCS TO MV SWGR and HMI Screen is not demonstrated and not ready.	Yahia	P2	IC-COM	S3	7/12/2020	(109	ed lam	M.	

-	LOP Status	Seem 0	Psiruli mints		EVETER	Direct parties of NOV	Санциу	Appel	locs.	(SARAHI)	(Classification)).	Original Train	Chapmana name!	Process	Assessed Team	No.	(Care) Recent	Date:Climate	Chirel By
195	Dispute	24BDDT00	Tapchanger incomplete alarm shall be included in ASD	DCS		N/A	Dispute	24	BDT00	N/A	сом-Е	EGA	Balamurali	P3	E-COM	S3	2020/07/12	C	osey

2020/07/12 COSCY

Manchell Over Chreek Chreek By

2020/07/12 COSCY

Manchell Over Chreek Chreek By

2020/07/12 COSCY

Manchell Over Chreek By

Manchell Over C

S/BY PWR SUP TER REMICAB



Gene	ral Engir	neering Parameter	Dynamic Values/ Forcing	Hardware										
Para	meter Set 1	Parameter Set 2												
Туре	Name	Value>>	Visible Port	Visible Para	Archive >>	Alarm <<	Alarm Type	Prio rity	Active Alarm Text	Deactive Alarm Text	Acknowledge M.	Suppress	Signal >>	Descriptio
1	IN1		E3		. 13								E2	Binary Inpu
1	IN2													Binary Inpu
0	OUT		B		100	- 2	ALARM	0	TAP CH INCOMPL ALARM	TAP CH INCOMPL ALARM]	No Auto Ackno		2	Binary Out
0	OUTN						ALARM	0	PROTRLY TRIP		No Auto Ackno			Negated 0

SPPA-T3000

Alarm Sequence Report

Name:

Comment:

Created at:

2022/06/09 10:02:02.309

Time:

From

2021/06/09 09:01:27.325

To

2022/06/09 10:01:27.325

Tags:

24BDT00GH002||XJ37

PointGroups:

Alarm Types:

all entries

Priorities:

>= 0

Suppression:

Unsuppressed And Suppressed Alarms + Status Changes

Values:

all entries

Initial Values:

not included

Soe:

not included

Time	Туре	Prio	Name	Designation	Value	Note
2021/10/13 15:22:54.013	Α	0	24BDT00GH002 XJ37	S/BY PWR SUP TFR REM CAB	[TAP CH	+D-SUP
2021/10/13 15:23:06.035	Α	0	24BDT00GH002 XJ37	S/BY PWR SUP TFR REM CAB	[TAP CH	-D-SUP

Open Ite m No.	LOP Status	Source ID	Punch items	Originator From	Originator name)	Priority	Action by	Date Raised	Date Closed	Closed By
390	Closed for Siemens		Trip first-out, to be demonstrated	EGA	Yahia	P3	SIEMENS	6/8/2020	25-My. 7	or3.

Open Ite m No.	LOP Status	Source ID	Punch items	Description of NOI	Category	Unit	ккѕ	Building	Classification-1	Originator From.	Originator name)	Priority	Assigned Team	Action by	Date Raised	Date Closed	Closed By
631	To be agreed	24EKC_1GH001	RMS Water Bath heater exact function description to include all control and functions	N/A	To be agreer	24	EK	UEN	COM-I&C	EGA	Yahia	P3	IC-COM	S3	2020/12/10	28/8/622	15
684	Dispute	24EK_00GH001	Local/Remote Signal for all RMS PLC to be configured and shown in the DCS HMI , example Condnsate drain pumps	N/A	Dispute	24	EK	UEN	COM-I&C	EGA	Yahia	P3	IC-COM	S3	2020/12/17	2/8/2	111
1946	Active	3rd Party Communication	All 3rd Party communication with redundant links are still not yet established and demonstrated by EGA	N/A	В	па	3rd Party Communication	N/A	COM-I&C	EGA	Yahia	P2	IC-COM	S3	2021/06/13	28/1/12	yhy-
2413	Active	HRSG	IP Econimizer Flow meters A/B is found to go out of range and give to many alarms on 22-AUG-2021 11:14AM TO 11:40AM. S3 To revise the range of the transmiter to avoid that behaviour.	N/A	C1	24	HRSG	UHA	COM-I&C	EGA	Yahia Mostafa	P3	COM-I&C	\$3	2021/08/29	28/18/25	y diff

.60

1 gedes

Open Ite m No.	LOP Status	Source ID	Punch Items	Description of NOI	Category	Unit	ккѕ	Building	Classification-1	Originator From.	Originator name)	Priority	Assigned Team	Action by	Date Raised	Date Closed	Glosed By
781	Dispute	24EK_00GH001	Flow computer communication module MOXA single device used for both flow computers please use separate MOXA	N/A	Dispute	24	EK	UEN	COM-I&C	EGA	Yahia	P3	IC-COM	S3	2020/12/17	2750	They
1031	Dispute		Co2 Measurment to be added and to be transferred to DCS	N/A	Dispute	24	HNE	UHA	COM-I&C	EGA	Yahia	P2	IC-COM	\$3	2021/01/24	23.36	ghif
1129	Active	Fire alarm	Fuel Gas station sprinkle syste equipement tested however sprinkler system is not tested per procedure.	N/A	В	24	UEN	UEN	COM-I&C	EGA	Yahia	P2	IC-COM	\$3	2021/02/11	27.5%	get
1291	To be agreed		Air intake Microsoft windows is CE Version 6 which is found to be obsolete	N/A	Γο be agreeα	24	Air Intake Functional Test	MBL	COM-I&C	EGA	Yahia	P3	IC-COM	SIEMENS	2021/04/01	27-5-15	44

Open Ite m No.	LOP Status	Source ID	Punch items	Description of NOI	Unit	ккѕ	Buildin g	Classificat ion-1	Originator name)	Priority	Date Raised	Date Closed	Closed By	
869	Active	24HNE	CEMS NOX System calculation to be shown in the document	N/A	50	HNE	UHA	COM-I&C	Yahia	P3	1/7/2021	1-Nov-20	Jahref	

913 Active 24HNE DLC/SCADA time synchronization HNE Vahia D3 IC-COM S3 1/7/2021 c0/		LOP Status	Source ID	Punch items	ккѕ	Originator name)	Priority	Assigned Team	Action by	Date Raised	Date Closed
THE TAIL PECISOADA UNITE SYLICITION 2001	913	Active	24HNE	PLC/SCADA time synchronization	HNE	Yahia	P3	IC-COM	S3	1/7/2021	23/2/2

		Raised	1
RMS Flow Metering system SAT is not complete and not signed due to totilizer not communicating correctly SAT is not complete and not signed due to totilizer not N/A To be agree 24 RMS Flow Metering UEN COM-I&C EGA Yahia P2 IC-C	S3 :	2021/01/07 17 5	later first

Open his	LOP Status	Вомусе Ф	Pupil mm	KAS	hanne .	Summary 1	Organism From:	Colgorates: material	Province	Assigned Years	Action by	Osti (Grand	face Channel,	J. Garage	
995	Active	24MBX2X	There is no changeover option between compressor 1 and 2 Compressor 1 is running all the time Thit is totally not accepted Change over must be available from DCS	MBX2X	UMB	COM-I&C	EGA	Yahia	P3	IC-COM	SIEMENS	2021/01/14	Mod.	Yaharfa	W-

1002 Active 24EKC_1GH001 WBH Temperature control can not be demonstrated due to N/A C1 24 EKC_1GH001 UBA01 COM-I&C EGA Yahia P2 IC-COM S3 2021/01/14 1 1 1 1 1 1 1 1 1	Openide Us No	LOP Status	Source III	Puntifilans	Cleantiplian of NCC	Galegaey	Unit	HME	Building	Charicanin t	Originator From:	(Originator stamle)	Priority	Assigned Team	Action by	Date Raised	Date Closed By	
	1002	Active				C1			UBA01	COM-I&C	EGA	Yahia	P2	IC-COM	\$3	2021/01/14	17- IN Coper	7

Open ite m No.	DP Status	Source ID	Punch items	KKS	Originator name)	Priority	Assigned Team	Action by	Date Raised	Date Closed	Closed By
1008	Active	24MBR	Analogue values failure or bad qaulity must have have alarm and need to be sent to DCS	GT DCS SAT	Yahia	Р3	IC-COM	S3	17/01/2021	5Jan 20	1 holy

Open ne m No.	LOP Status	Source ID	Punch dirms	Discription of NO	Category	U)WI	:KKS	thanning	Characterities 1	Originator from:	Grégoriassi isames	Pilodity	Assegned Team	Authori By	Date Rained	Date Closed	Closed By
1009	Aclive	24MBR	Pump outlet pressure low alarm is not generated from PLC and need to be sent to DCS	N/A	C1	na	GT DCS SAT	UBA01	COM-I&C	EGA	Yahia	Р3	IC-COM	83	2021/01/17	5.00	John

m

Open to m No	LOP Status	Source (II)	Papen deros	Description of NO	Gategory	Man	KKS	Burning:	Classification (Originator From	Originator narmit	Priority	Assigned Team	/Action Py	Date Raised	Oate Goson	Glowed By
1024	To be agreed	24HNE	DCS To show in Designation description "CEMS" For all exchange signal	N/A	To be agree	50	HNE	UHA	COM-I&C	EGA	Yahia	P3	ІС-СОМ	83	2021/01/17	(m)	41
70			31												a	32	

Open the	LOP Status	Soutce ID	Punch dems	KKS	Building	Classification-1	Originator Front	Originator masse)	Promity	Assigned Team	Action by	Date Rawed	Date Closed	Closed By	1
1078	Dispute	24XJA01	Communication to FMS \DCS to demonstrated	XJA01	UBN	СОМ-Е	EGA	Balamurali	P3	E-COM	\$3	2021/01/28	Cla	sed	
N.E.												(9	Buler	Mc)/22

Open the	LOP Status	Soutce ID	Punch items	KKS	molding	Classification (Originator From	Grigorator same)	Plionty	Assigned Feam	Action uy	Date Rused	Date Glosed Greed By	
1758	Active	FMS System	Original Liscence to be provided to operator station.	FMS System	N/A	сом-е	EGA	Balamurali	P3	E-COM	\$3	2021/05/24	MANICOLO	of a
													7590	
													20 lamwa	A
												(Ja Jaman	

Open Ite m No	LOP Status	Source fit	Punch domé	RKS	Building	Olassification 1	Originator From	Originator pame)	Roonly	Assigned Team	Action by	Oute Raised	Date Closed	Classed By
2127	Active	FMS system	Network cables tag missing to be fixed with clear source and destination description.	FMS system	N/A	сом-е	EGA	Balamurali	P3	E-COM	\$3	2021/07/14		duplicate ex
													6	Balamidal

2446 Active FMS system SWRO feeders total signals not included in FMS to be FMS system N/A E-COM EGA Balamurali P3 E	E-COM S3 2	P3 E-COM S3	
			2021/08/29 Applicated
			21/7
			Rulamata

Open to n: No	LOF States	Source 60	Punch Issue	KKII	нани	Characteristics	Ottown	(Angeles and Angeles and Angel	Cracely	Assigned Team	Action	Robert	Sate Chinese	Chrone (le	
1189	Active	FMS/DCS	Current and Voltage signals ranges to be reconfirmed and configurated w.r.t FMS settings. During test, simulated values from FMS having discrepancies in DCS setting	(24CHA01GH001, 24CHA02GH001)	UBA02	COM-I&C	EGA	Loganathan	P2	ю-сом	S 3	2021/03/04	4/11/22	white	

n No.	LOP Status	Source ID	Punch Items	KKS	Building	Classification-1	Originator From	Originator name)	Priority	Assigned Team	Action	Date Raised	Date Closed
1191	Active	FMS/DCS	Some of the signals are not tested as per the signal list	(24CHA01GH001, 24CHA02GH001)	UBA02	COM-I&C	EGA	Loganathan	P2	IC-COM	S3	2021/3/4	11/11/2022 24

Open Ite m No.	LOP Status	Source ID	Punch items	KKS	Originator name)	Assigned Team	Action by	Date Raised	Date Closed	Closed By
1312	Dispute	Carbohydrazine Dosing Function test	Pump 3 during changeover not working and getting tripped during changeover.	Carbohydrazine Dosing Function test	Loganathan	E-COM	S 3	4/1/2021	222	yet.
1314	Active	Carbohydrazine Dosing Function test	Pump selection not changing when the selected running pump gets tripped but changeover is working.	Carbohydrazine Dosing Function test	Loganathan	IC-COM	S 3	4/1/2021	Dec-1	JH
1318	Dispute	Dosing Experientest	In Function group start, the Pump which gets tripped due to any fault is starting healthy pump but when the tripped pump get normalized, it is starting again and stopped the running healthy pump which is started due to the failed pump.	Carbohydrazine Dosing Function test	Loganathan	E-COM	S 3	4/1/2021	25	The

Open m N	ite o.	OP Status	Source ID	Punch items	ккѕ	Originator name)	Assigned Team	Action by	Date Raised	Date Closed	Closed By
171	8	Active	QCC -Dosing system	Door stopper damaged to be replaced.	QCC -Dosing system	Balamurali	E-COM	S 3	5/24/2021	close	
ž.								-	(7130	lamid

	LOP Status	Source ID	Punch items	KKS	Originator name)	Priority	Assigned Team	Action by	Date Raised	Date Closed	Closed By
1339	Active	Dosing	Electrical trip changeover happens but stroke control not started due to non-availability of auto control setpoint for stroke to be clarified.	Phosphate Dosing Function test	Loganathan	P3	ІС-СОМ	S 3	4/1/2021 /	13-12-7	Jeff
1346	Dispute	Phosphate Dosing Function test	In Function group start, the Pump which gets tripped due to any fault is starting healthy pump but when the tripped pump get normalized , it is starting again and stopped the running healthy pump which is started due to the failed pump.	Phosphate Dosing Function test	Loganathan	P2	IC-COM	\$3	4/1/2021	المحاسلا	yho

	LOP Status	Source ID	Punch items	KKS	Originator name)	Priority	Assigned Team	Action by	Date Raised	Date Closed	Closed By	1_
1402	Active		Panel name plate/ rating plate etc not provided to be provided.	50QCC Oxygen Scavenger system	Balamurali	P3	E-COM	S 3	4/1/2021	, 13W	umw 2	522 522
										al	sed-	

Open ite m No.	LOP Status	Source ID	Punch items	KKS	Originator name)	Priority	Assigned Team	Action by	Date Raised	Date Closed	Closed By
1532	Active	MV Feedwater Pump	All RACK in faceplate are shouwing trouble alarm and I&C Alarm , Signals commissioning to be checked and Witnessed with EGA	MV Feedwater Pump	Yahia	P2	IC-COM	S 3	08/04/2021	7-5m-2	yets /

Open ite	LOP Status	Source ID	Punch items	KKS	Originator name)	Poority	Assigned Team	Action by	Date Raised	Date Closed	Closed By	
1533	Active	MV CEP Pump	All RACK in faceplate are shouwing trouble alarm and I&C Alarm , Signals commissioning to be checked and Witnessed with EGA	MV CEP Pump	Yahia	P2	IC-COM	S 3	08/04/2021	6-Jun2	23 y Aux	

Open III m No	LOP Status	Source ID	Panich dono	KKS	Building	Classification-1	Originator F/om	Originalist name)	Property	Assigned Team	Action by	Cate Raised	Date Closed	Classed By	0
1702	Active	FMS/DCS	MV Swgr Protection Relay Comm Fail/ Watch dog signal to be Signaled to DCS	FMS/DCS	N/A	СОМ-Е	EGA	Balamurali	P3	E-COM	S 3	2021/05/24	C1	13 Mamul	al'

Ca0006312 3/11/20>2

Open Ite m No.	LOP Status	Source ID	Punch (tems	ккs	Originator name)	Priority	Assigned Team	Action by	Date Raised	Date Closed	Closed By
1947	Active	Time Sync For 3rd Party	All 3rd Party time synch Still not established or demonstrated by EGA	Time Sync For 3rd Party	Yahia	P2	ІС-СОМ	S 3	13/06/2021	6-19an-20	3 yakister

15	G mans	Nextiliam	Description of NO	Company	3	MASS	1	Chydraso.	and the second	Organis	Process	Accigned Team	N Age	Page 2	Dian Dicted	Closes By
	ЕТР	24 VDC Power failure alarm and DCS communication failure alarms. Panet alarms etc. are not logging in the alarm section of Local ETP Panel HM	NVA	5	24	ETP	UVB	COMHEC	EGA	Loganathan	2	Р3 ІС-СОМ	SS	2021/06/13	1250	y shulfor

Open Ite m No.	LOP Status	Source ID	Punch items	Category	Originator From	Originator name)	Assigned Team	Date Closed	Closed By	
2048	Closed for SIEMENS.	DCS SAT	H1 , CP443-5 EXT For profibus is showing all the time communication fault on the screens	Dispute	EGA	Yahia	IC-COM	3My 2.23	you for with de	- -912

Open ite	LOP Status	Source ID	Pumoti items	KKS	Building	Classification d	Originator From	Originals:	Promy	Assigned Team	Action by	Date Raised	Date Closed	Closed By	/
2096	Active	Air intake	During PLC Redundancy test it is found that there is no any alarm configured(CPU, Communication, Ballery) these must be configured and send to DCS as I&C alarm	Air Inlake Functional Tesl	N/A	COM-I&C	EGA	Yahia	Р3	IC-COM	SIEMENS	2021/07/05	1-34	Yatay	
													U.		

	LOP Status	Source ID	Punch items	KKS	Originator name)	Priority	Assigned Team	Action by	Date Raised	Date Closied	Closed By
2142	Active	50CJC12	Power supply Fault to be wired and test to be repeated	50CJC12	Yahia	P3	COM-I&C	S3	14/07/2021	6-5n-25	3 yhofa
2144	Active	50CJC12	All MCB fault to be wired	50CJC12	Yahia	РЗ	COM-I&C	S3	14/07/2021	-WATE 2	Cato And
2311	Active	50CJC12 Redundancy test	50CJC12.AA-A10 to be replaced, FO port is loose.	50CJC12 Redundancy test	Muas	P3	COM-I&C	\$3	17/08/2021	15m-223	Jak Jo LO For Pel M.

Ilo-0602 Iog-1034


Open Ite m No.	LOP Status	Source ID	Punch items	Category	Originator From	Originator name)	Assigned Team	Date Closed	Closed By
2146	Active	system Communication	It is noted with that with any cable removal alarm is appering however with normalization it is not reseting , example 24AQX10EV001 TRBL alarm	C1	EGA	Yahia	COM-I&C	3-May-2023	Fixe Lwil


Open Ite m No.	LOP Status	Source ID	Punch items	KKS	Originator name)	Assigned Team	Action by	Date Raised	Date Closed	Closed By
2213	Dispute		No alarms for breaker off neither on local HMI nor in DCS	Ball cleaning system	Muaz	COM-I&C	S3	7/14/2021	9/3/23	Songar Songar

2230	Active		PCV 24EKH61AA103 on gas compressor Continues hunting while in operation		N/A	C1	24	24EKH81AA10 3	UEN	сом-Е	EGA	Senthil kumar	Р3	E-COM	S3	2021/07/25		, P.
Specific in the	LOP Status	Same	Appetració	SYSTEM	Dywoglass of WO	Camping	uw	NHS	in the same of	(Similario)	Chapman .	Grummer	Himmy	Assembly Teach	Account by	Class Ranged	Date Christi	Chisvethi

¢=

Close 122





Open Ite m No.	LOP Status	Source ID	Punch items	Originator From	Originator name)	Priority	Action by	Date Raised	Date Closed	Closed By
2538	Closed for Siemens		All programming and configuration tools to be provided along with their respective Master Backup, Software, Licenses, and Manuals.	EGA	Muaz	P3	S3/SIEMENS	8/29/2021	Pars of	Mounth She

Open (te in No.	LOP Status	Source ID	Punch items	киз	Building	Glassifications)	Originator Prom	Originatos (sente)	Enomy	Assigned Team	Action by	Unie Barad	Data Closed	Clorent Hy	^	
2599	Aclive	GT/ST	GT- SFC/SEE, Spare compact CF card for both Chanels, leaded with all program to be provided.	GT/ST	N/A	сом	EGA	Rashed/Sashi/Hari /Khaled Abbas	P3	сом	SIEMENS	2021/08/29	86-10-2	2 de	hod.	Recirend
2601	Active		ST- SEE, Spare compact CF card for both Chanels, leaded with all program to be provided.	GT/ST	N/A	COM	EGA	Rashed/Sashi/Hari /Khaled Abbas	P3	сом	SIEMENS	2021/08/29	06-10-	2 J 205/	d	,

timbedocer (com) 13 alumors 6/10/2

Open Ite m No.	LOP Status	Source ID	Punch items	Description of NOI	Category	Unit	ккѕ	Assigned Team	Action by	Date Raised	Date Closed	Closed By
2749	Closed for Siemens	DCS SAT	DCS SAT Incomplete testing must be completed and Signoff of the all DCS Procedure must be completed	N/A	C1	24	DCS SAT	COM-I&C	SIEMENS	8/29/2021	2/4/2	they

Open the	LOP Status	Source ID	Punch deuts	KKS	Building	Classification-1	Originator From	Cirquisator rilania)	Pricetty	Assigned Team	Action by	Olde Plated	Date Closes	Closed By	1
2753	Active	DCS printer 2	It is found that the table is not well plugged and fixed with insulation tap	DCS printer 2	N/A	COM-I&C	EGA	Yahia Mostafa	P3	COM-I&C	S3	2021/08/29	5 oct	y dut	
													200 /		

ron f

8 8 80 V

Open ite m No.	LOP Status	Source ID	Punch items	Originator name)	Priority	Assigned Team	Action by	Date Raised	Date Closed	Closed By
2757	Active		SM133 IO module has a fault, but couldn't find the exact reason for the fault from logic.	Manoharan	Р3	сом	S 3	8/31/2021	2-7/429	The