


## Crystals Power Supply +5V PWR\_FLAG PWR\_FLAG +3.3V X2 does not need to be implemented X1 ECS-2520S PWR\_FLAG TC25L5I32K7680 D4 RSX101VAM Debugger motor\_driver.sch Reset R1 50k R1 does not need to be implemented SW1 o various.sch Sheet: / File: General\_purpose\_lancer\_board.sch Title: General—purpose Lancer board Size: A3 Date: 2019–12–14 KiCad E.D.A. kicad (5.0.0)





#### Cross switch





#### Potentio














### microSD





# Line Sensor



reRo		
Sheet: /various/ File: various.sch		
Title: General-purpose Lancer board		
Size: A3	Date:	Rev: 1.0
KiCad E.D.A. kicad (5.0.0)		ld: 3/3
	7	8