

GOVERNMENT OF INDIA • MINISTRY OF COAL

COAL INDIA LIMITED (CIL) • CENTRAL MINE GOVERNANCE SYSTEM

Official Statutory Inspection & Compliance Audit Report — Generated: 2026-09-28 14:04 UTC

|                    |                                         |                     |                                                   |
|--------------------|-----------------------------------------|---------------------|---------------------------------------------------|
| Report Ref No:     | REP-260928-C9970D                       | Inspection Date:    | 2026-09-28                                        |
| Mine Facility:     | Rajmahal Open Cast Project (ECL-OCF-01) | Subsidiary:         | Eastern Coalfields Limited                        |
| Contractor Agency: | Direct Operations                       | Inspecting Officer: | Amitabh Singh (Senior Overman / Safety Inspector) |
| Inspection Type:   | Safety                                  | Geo-Coordinates:    | 25.0489° N, 87.3821° E                            |
| Compliance Score:  | 80.0 / 100                              | Workflow Status:    | APPROVED                                          |

AI-ASSISTED RISK ASSESSMENT: 45.0/100 — [LOW]

Contributing Factors: Normal operation standards met.

Statutory Checklist Findings

| Item / Rule                                        | Category      | Result | Remarks                                                     |
|----------------------------------------------------|---------------|--------|-------------------------------------------------------------|
| Haul road berm height ≥ tyre height (DGMS Reg 115) | Safety        | FAIL   | Berm height only 1.1m against 2.2m dumper tyre requirement. |
| Reverse horn (AVRA) functional on all HEMM         | Safety        | PASS   | Tested functional.                                          |
| Dust suppression mist / bowser operational         | Environmental | PASS   | Misting bowser active.                                      |

Recorded Violations & Corrective Directives

| Violation Code    | Category | Severity | Statutory Reference & Details                                                                                                                               |
|-------------------|----------|----------|-------------------------------------------------------------------------------------------------------------------------------------------------------------|
| VIO-260928-BB438D | Safety   | MEDIUM   | Non-Compliance: Haul road berm height ≥ tyre height (DGMS Reg 115): Field observation recorded: Berm height only 1.1m against 2.2m dumper tyre requirement. |
| VIO-260928-CC7814 | Safety   | HIGH     | Critical Observation: Substandard Haul Road Berm: Berm height at Bench 3 is sub-regulation under DGMS Reg 115.                                              |

FIELD OFFICER VERIFICATION  
Digitally Signed & Submitted  
Date: 2026-09-28

MINE MANAGER VALIDATION  
Reviewed and Enforced  
Action Assigned

CORPORATE GOVERNANCE (CIL)  
Statutory Compliance Seal  
Status: APPROVED