

GOVERNMENT OF INDIA • MINISTRY OF COAL

COAL INDIA LIMITED (CIL) • CENTRAL MINE GOVERNANCE SYSTEM

Official Statutory Inspection & Compliance Audit Report — Generated: 2026-09-26 22:16 UTC

Report Ref No:	REP-2026-CIL-003	Inspection Date:	2026-09-20
Mine Facility:	Gevra Expansion OCP (SECL-GEV-02)	Subsidiary:	South Eastern Coalfields Limited
Contractor Agency:	Singrauli Extraction & Transport	Inspecting Officer:	Amitabh Singh (Senior Overman / Safety Inspector)
Inspection Type:	Labour Compliance	Geo-Coordinates:	22.3554° N, 82.5872° E
Compliance Score:	88.0 / 100	Workflow Status:	VIOLATIONS_FLAGGED

AI-ASSISTED RISK ASSESSMENT: 17.0/100 — [LOW]

Contributing Factors: Labour Compliance compliance posture evaluated against statutory norms.

Recorded Violations & Corrective Directives

Violation Code	Category	Severity	Statutory Reference & Details
VIO-SECL-26-005	Equipment & Safety	HIGH	Missing High-Voltage Ground Wire on Electric Shovel 4: Trailing cable grounding conductor open-circuited. Risk of catastrophic electrocution.

FIELD OFFICER VERIFICATION Digitally Signed & Submitted Date: 2026-09-20	MINE MANAGER VALIDATION Reviewed and Enforced Action Assigned	CORPORATE GOVERNANCE (CIL) Statutory Compliance Seal Status: APPROVED
---	--	--