

GOVERNMENT OF INDIA • MINISTRY OF COAL

COAL INDIA LIMITED (CIL) • CENTRAL MINE GOVERNANCE SYSTEM

Official Statutory Inspection & Compliance Audit Report — Generated: 2026-09-26 22:16 UTC

Report Ref No:	REP-2026-CIL-004	Inspection Date:	2026-09-18
Mine Facility:	Sodepur Underground Colliery (ECL-SOD-03)	Subsidiary:	Eastern Coalfields Limited
Contractor Agency:	Brahmaputra Mining Consortium	Inspecting Officer:	Amitabh Singh (Senior Overman / Safety Inspector)
Inspection Type:	Equipment	Geo-Coordinates:	23.6840° N, 86.8800° E
Compliance Score:	94.0 / 100	Workflow Status:	MM_VALIDATED

AI-ASSISTED RISK ASSESSMENT: 11.0/100 — [LOW]

Contributing Factors: Equipment compliance posture evaluated against statutory norms.

Recorded Violations & Corrective Directives

Violation Code	Category	Severity	Statutory Reference & Details
VIO-SECL-26-006	Safety	MEDIUM	Overspeeding Dumpers on Mine Arterial Haul Road: GPS telematics detected 3 dumpers traveling at 48 km/h in designated 25 km/h zone.

FIELD OFFICER VERIFICATION Digitally Signed & Submitted Date: 2026-09-18	MINE MANAGER VALIDATION Reviewed and Enforced Action Assigned	CORPORATE GOVERNANCE (CIL) Statutory Compliance Seal Status: APPROVED
---	--	--