

GOVERNMENT OF INDIA • MINISTRY OF COAL

COAL INDIA LIMITED (CIL) • CENTRAL MINE GOVERNANCE SYSTEM

Official Statutory Inspection & Compliance Audit Report — Generated: 2026-09-28 10:50 UTC

Report Ref No:	REP-260928-BDEC26	Inspection Date:	2026-09-28
Mine Facility:	Rajmahal Open Cast Project (ECL-OCF-01)	Subsidiary:	Eastern Coalfields Limited
Contractor Agency:	ABC Mining Services Pvt Ltd	Inspecting Officer:	Amitabh Singh (Senior Overman / Safety Inspector)
Inspection Type:	Safety	Geo-Coordinates:	25.0492° N, 87.3830° E
Compliance Score:	35.0 / 100	Workflow Status:	APPROVED

AI-ASSISTED RISK ASSESSMENT: 45.0/100 — [LOW]

Contributing Factors: Normal operation standards met.

Statutory Checklist Findings

Item / Rule	Category	Result	Remarks
Dust suppression spray active	Safety	FAIL	Sprinklers dry on upper bench
PPE compliant	Safety	PASS	All workers wearing helmets and high-vis

Recorded Violations & Corrective Directives

Violation Code	Category	Severity	Statutory Reference & Details
VIO-260928-0D1610	Safety	MEDIUM	Non-Compliance: Dust suppression spray active: Field observation recorded: Sprinklers dry on upper bench
VIO-260928-9D3EAD	Safety	HIGH	Critical Observation: Dry Haul Road & Dust Hazard: Excessive fugitive dust reducing haulage visibility under DGMS Reg 124
VIO-260928-B6A662	Labour & Health Compliance	HIGH	Active Workers with Expired Medical Fitness Certificates: Identified 3 active contractor workers on-site with expired Form O medical examinations.
VIO-260928-B893F7	Contractor Statutory Compliance	HIGH	Expired Mandatory Compliance Documentation: Contractor documentation is past statutory validity: Environmental Clearance.

FIELD OFFICER VERIFICATION

Digitally Signed & Submitted
Date: 2026-09-28

MINE MANAGER VALIDATION

Reviewed and Enforced
Action Assigned

CORPORATE GOVERNANCE (CIL)

Statutory Compliance Seal
Status: APPROVED