Title : Environment Monitoring using IOT

Document : Requirement Specifications

Functional Requirements

- Ambient temperature, relative humidity(RH), atmospheric pressure and altitude to be measured
- Parameter ranges required:

o Temperature: -40 to 85 deg C

o RH: 0% to 100%

o Atmospheric pressure: 300hPa to 1100 hPa

o Altitude in metres

Accuracies:

o Temperature : =/-0.5 deg C

o RH:1%

o Atmospheric pressure: +/- 1.0 hPa

- Minimum update rate of parameters: 2 seconds
- Power supply: 5V (USB powered)
- Display of parameter values on local display
- Update on cloud database should be accessible to user for debugging purposes
- Current values of parameters should be made available to user in a mobile at any place with Internet connectivity

Non-functional requirements

- Should have compact custom PCB
- Display and sensor modules to be connected using polarized cables
- Should have low power consumption. Should be capable of being USB powered for program upload and debugging from a laptop