Title: Ambient Parameter Monitoring using IOT

Document: Requirement Specifications

Functional Requirements

- Ambient temperature and relative humidity to be measured, temperature in Celsius scale and relative humidity as a percentage.
- Temperature range to be measured: 0-50 degrees C
- Relative Humidity range to be measured : 20-90 %
- Temperature accuracy: +/- 2 degrees
- RH accuracy +/-5%
- Minimum update rate of parameters: 2 seconds
- Power supply: 5V (USB powered)
- Display of parameter values on local display
- Update on cloud database should be accessible to user for debugging purposes.
- Current values of parameters should be made available to user in a mobile at any place with Internet connectivity.

Non-functional requirements

- Should have compact custom PCB
- Display and sensor modules to be connected using polarized cables.
- Should have low power consumption. Should be capable of being USB powered for program upload and debugging from a laptop.