Repair Invoice

Repair shop: QuickFix Auto Body
Invoice date: 2026-09-02
Customer: Alice Claimant
Vehicle: 2021 Toyota Camry, VIN 4T1B11HK5MU123456

Rear bumper cover (OEM) + paint	$ 1,850.00
Trunk lid replacement	$ 2,600.00
Left tail light assembly	$ 420.00
Front windshield replacement	$ 500.00
Labor 14h @ $70	$ 980.00
TOTAL	$ 6,350.00