

Tacoma Roofing Co.

4410 South Tacoma Way, Tacoma, WA 98409
(253) 555-0501 license TACOMRC901QR

Roof Inspection Report and Repair Estimate

Estimate number	TR-26-2098
Issue date	October 8, 2026
Valid through	November 7, 2026
Property	2847 N Junett St, Tacoma, WA 98407
Owner	Jennifer Long
Inspector	R. Delgado, senior estimator
Roof type	Architectural asphalt shingle, approx. 12 years old

Summary of findings

A full exterior inspection of the North End split-level was completed on the date above. The roof is in generally fair condition for its age. It is serviceable through the coming wet season with the minor repairs listed below. There are no active leaks and no evidence of interior water intrusion. Addressing the flashing and the two lifted shingles now will protect the deck before the winter rains arrive.

Condition by area

Area	Condition	Observation
South slope	Fair	Minor granule loss, wear consistent with age
North slope	Good	Even coverage, no lifting
Chimney flashing	Attention	Sealant cracked, two shingles lifted nearby
Ridge and hip	Good	Caps intact, nails seated
Gutters and downspouts	Good	Clear and draining, straps secure
Valleys	Good	No debris packing, metal sound
Attic ventilation	Adequate	Soffit and ridge vents open

Photo documentation of the chimney flashing and south slope is retained on file and available on request.

Recommended scope of work

The following work is recommended to restore the flashing seal and replace the two worn shingles. Line pricing includes labor, materials, cleanup, and haul away.

Line	Description	Amount
1	Full roof inspection (waived if repair is booked)	\$350.00
2	Reseal chimney flashing, replace cracked sealant bead	\$220.00
3	Replace two lifted shingles, south slope near chimney	\$140.00
	Estimate total if all work approved	\$710.00

Optional items considered but not required at this time

Item	Note	Indicative price
Gutter guard install	Reduces fall cleaning, not urgent	\$480.00
Full re-roof	Deferred, 2 to 4 seasons of life remain	\$14,500.00
Attic baffle add	Ventilation already adequate	\$260.00

Warranty

Flashing and shingle repairs carry a two year workmanship warranty. Manufacturer coverage on replacement shingles follows the original product terms. The workmanship warranty is transferable to a new owner within the coverage window at no charge.

Scheduling

Repair work is typically scheduled within seven to ten business days of approval, weather permitting. A crew of two completes this scope in a single visit of roughly three hours. No occupant relocation is required.

Terms and conditions

1. Estimate validity. This estimate is valid for thirty days from the issue date. Pricing after that window is subject to review for material cost changes.
2. Inspection credit. The \$350 inspection fee is credited in full toward any repair work booked from this visit and completed within the validity window.
3. Payment. A deposit is not required for repairs under \$1,000. The balance is due on completion by card or check. Estimates over \$5,000 follow a separate deposit schedule.
4. Access and safety. The owner agrees to provide clear access to the roof area and to keep vehicles and pets clear during the visit. Work pauses in unsafe weather.
5. Concealed conditions. If concealed damage to the deck or underlayment is found once shingles are lifted, work stops and the owner is notified with a revised estimate before proceeding.
6. Cleanup. All debris is removed and the ground is magnet swept for stray nails at the end of the visit.

Acceptance

To book this repair, sign below or call the office. The inspection fee credit applies once the repair is scheduled.

Owner signature	_____ Date _____
Estimator	R. Delgado Tacoma Roofing Co.
Booking contact	(253) 555-0501, office hours 8 to 5 weekdays

Thank you for considering Tacoma Roofing Co. We appreciate the opportunity to help you protect your home before winter.