

Annual Haul-out and Condition Survey

Vessel owner: John W. Singleton (Jack). This report documents the December haul-out, bottom service, and condition survey of the F/V Bay Runner, a 42 foot fiberglass deadrise workboat with twin Cummins QSB 6.7 diesels. The vessel was hauled, pressure washed, surveyed, and returned to the water ready for the off-season layup and spring commissioning.

1. Vessel Particulars

Vessel	F/V Bay Runner
Type	Fiberglass deadrise workboat
Length	42 feet
Power	Twin Cummins QSB 6.7 diesel
Engine hours	4,820 at haul
Home slip	Slip 47, Annapolis City Marina
Owner	John W. Singleton
Survey purpose	Annual condition and insurance

2. Hull and Running Gear

The hull was pressure washed and inspected above and below the waterline. Gelcoat is sound with normal wear at the rub rail and chine. No blistering of concern. Running gear, shafts, struts, and propellers were checked for play and alignment. Zincs were 60 percent consumed and replaced. Bottom paint was applied after fairing two minor areas near the keel.

Item	Finding	Action	Cost
Gelcoat	Sound, normal wear	None	n/a
Zinc anodes	60 pct consumed	Replaced full set	\$88.00
Bottom paint	Due	Two coats ablative	\$388.00
Shafts and struts	Within tolerance	None	n/a
Propellers	Light edge wear	Dressed	\$120.00

3. Propulsion and Systems

Both Cummins diesels were checked for leaks, belt condition, and coolant. Oil and filters were changed and the Racor fuel filters serviced. The hydraulic pot puller circuit was inspected and a weeping seal noted for off-season rebuild, tracked in maintenance log X09. Steering and throttle controls operate normally.

- Engines: oil and filters changed, no leaks, coolant topped.
- Fuel: Racor primary filters replaced, water separators clear.
- Hydraulics: puller seal weeping, scheduled for shed rebuild January 2026.
- Electrical: batteries load tested, charging system normal.
- Steering: no play, fluid level good.

4. Safety Equipment

Required safety gear was inventoried for the USCG commercial fishing vessel requirements. Flares within date, life ring present, PFDs serviceable. The EPIRB battery is due and was flagged for replacement before the spring season, ordered through West Marine and recorded in X09.

Equipment	Status	Next Due
Visual distress flares	In date	2027 season
PFDs, crew of four	Serviceable	Annual check
Life ring and throw line	Good	Annual check
EPIRB	Battery due	Before spring 2026
Fire extinguishers	Charged, tagged	Annual

5. Survey Summary and Valuation

The F/V Bay Runner is in good and seaworthy condition for its age and commercial service. With the bottom service, zinc replacement, and scheduled hydraulic rebuild, the vessel is fit for the 2026 commercial crab and summer charter seasons. The fair market value for insurance purposes is estimated below and supports the existing hull and liability coverage.

Estimated hull value	\$118,000
Replacement value	\$165,000
Condition rating	Good, in service
Recommended coverage	Agreed value hull and protection and indemnity
Survey valid through	2026-12-31

6. Yard Invoice Summary

Service	Amount
Haul, wash, block, relaunch	\$450.00
Bottom paint and fairing	\$388.00
Zincs and propeller dressing	\$208.00
Survey and report	\$275.00
Total	\$1,321.00

Payment terms net 15 days. Thank you for trusting Marshwood Partners with the Bay Runner. We will hold your spring relaunch slot in the yard schedule.

Surveyed and prepared by Marshwood Partners yard staff. This report is advisory and does not replace an independent insurance survey if required by the underwriter.

Appendix. Spring Commissioning Checklist

The following items must be completed before the April 1 commercial opening. Coordinate the hydraulic seal rebuild and EPIRB battery with the off-season maintenance log X09.

Task	Owner	Target	Status
Hydraulic puller seal rebuild	Self, shed	January 2026	Scheduled
EPIRB battery replacement	West Marine	Before April	Ordered
Sea trial after relaunch	Self and Tommy	March prep	Pending
Electronics power-on test	Self	Pre-season	Done
Bilge and pumps check	Self	Pre-season	Pending

Yard contact: Marshwood Partners, (410) 555-1340, yard@marshwoodpartners.com. Relaunch slot held in the spring schedule.