

Silver Spring Toyota

13731 Georgia Avenue, Silver Spring, MD 20906
Service Department: (301) 929-7500 | www.ssptoyota.com

Vehicle Service Record

Customer:

Tony Michael Nguyen Sr.

Address:

3114 Woodmoor Drive, Silver Spring, MD 20901

Phone:

(301) 555-0112

Vehicle:

2020 Toyota Camry SE

VIN:

4T1B11HKXLU487219

Mileage In:

28,411 miles

License Plate:

3ZKB847 (MD)

Service Date:

February 3, 2026

Service Advisor:

Marcus Webb

R.O. Number:

SS26-02-4817

Services Performed

Item	Description	Part Number	Labor	Parts	Total
1	Engine Oil and Filter Change Synthetic 5W-30, 5 quarts (Toyota Genuine Motor Oil)	04152-YZZA6	\$18.00	\$42.50	\$60.50
2	Tire Rotation Four tires rotated front-to-rear, torque to spec		\$20.00	\$0.00	\$20.00
3	27-Point Multi-Point Inspection Includes brake check, fluid levels, belt and hose visual, lights, wipers		\$9.45	\$0.00	\$9.45
				Subtotal	\$89.95
				Tax (6%)	\$5.40
				Total Due	\$95.35

Inspection Notes

System	Condition	Recommendation
Engine Oil	Replaced - Synthetic 5W-30	Next change at 33,411 miles or 6 months
Tires	All four: 6/32 tread depth, even wear	Rotate at next service
Brakes (front)	8mm pad thickness remaining	Good condition

Brakes (rear)	7mm pad thickness remaining	Good condition
Air Filter (engine)	Slightly dirty	Recommend replacement at next visit
Cabin Air Filter	Clean	No action required
Wiper Blades	Slight streaking on driver side	Replacement recommended
Battery	12.6V, CCA 98% of spec	Good condition
All Fluid Levels	Topped up as needed	No leaks observed
Exterior Lights	All functional	No action required

Payment Method: Visa ending 8841 Amount Paid: \$95.35

Thank you for choosing Silver Spring Toyota. Your next recommended service is an engine air filter replacement and wiper blade replacement, due at approximately 30,000 miles or August 2026.