Tools check-in/out Monitoring

Monitor tools check-in/out and generate periodic events.

Overview

Tools check in/out monitoring deals with monitoring the tools that employees use. It is important to ensure that all tools that employees use - go through a common checkout process. This is to ensure that the tools are not lost or stolen. Event is raised when employees don't check-out the tool and carry them out.

Vision Al-based monitoring

Vision Al-based model for monitoring is used to ensure that all tools that employees use - go through a common checkout process. Event is raised when employees don't check-out the tool and carry them out. Configuration is required to mark where the check-out counter is located.

Model

We would be releasing the model for monitoring equipment noise levels in Q2-2023.

Contact Us

- For technical issues, you can open a Github issue here.
- For business inquiries, you can contact us through our website.