cost =

2.4099

cost =

3.3113

cost =

2.3441

cost =

1.2599

cost =

0.9111

cost =

0.6938

cost =

0.5135

cost =

0.3801

cost =

0.2853

cost =

0.2178

cost =

0.1688

cost =

0.1324

cost =

0.1048

cost =

0.0836

cost =

0.0672

cost =

0.0542

cost =

0.0439

cost =

0.0357

cost =

0.0291

cost =

0.0237

cost =

0.0194

cost =

0.0159

cost =

0.0130

cost =

0.0107

cost =

0.0088

cost =

0.0072

cost =

0.0059

cost =

0.0049

cost =

0.0040

cost =

0.0033

cost =

0.0027

cost =

0.0022

cost =

0.0018

cost =

0.0015

cost =

0.0012

cost =

0.0010

cost =

8.4672e-04

cost =

6.9746e-04

cost =

5.7453e-04

cost =

4.7329e-04

cost =

3.8991e-04

cost =

3.2122e-04

cost =

2.6464e-04

cost =

2.1803e-04

cost =

1.7963e-04

cost =

1.4800e-04

cost =

1.2194e-04

cost =

1.0046e-04

cost =

8.2774e-05

Iteration number: 48

expPoint =

0.1000

1.5000

currPoint =

0.1000

1.4999

cost =

1.0146e-04

>>